

PORSCHE

Vehicle Identification

Delivered on

1-8-95

Date

Mileage

Workshop-no.									

Speedometer Change

Date

Mileage

1. Jct 600 LTD
2. NEWCASTLE
Stamp of
Official Porsche Centre

Stamp of
Official Porsche Centre

- 1.
- 2.
- 3.
- 4.
- 5.

WPOZZZ992SS315484
993 331
MB405-835 G5021- 10
L39U SA
C16 233 373 374 398
425 490 567 573 650

1. Vehicle ident. no. (V.I.N.)
2. Model no./Model descr.
3. Engine code
Transmission code

4. Paint code/
interior trim
5. Optional
equipment

Maintenance Record

Have your car serviced between 2 000 – 2 500 miles/3 000 – 4 000 km, thereafter every 12 000 miles/20 000 km or at least once a year.

*Please tick the appropriate box

<p><input type="checkbox"/> Vehicle maintenance 2 000 – 2 500 miles 3 000 – 4 000 km</p> <p>Date: <u>21 NOV 96</u></p> <p>Job no.: _____</p> <p>Mileage: <u>11 837</u></p> <p>Performed at customer's cost Centre's stamp</p> <p style="text-align: right;"><i>Oil & filter change</i></p>	<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>2-2-00</u></p> <p>Job no.: <u>56819</u></p> <p>Mileage: <u>31844</u></p> <p>Performed at customer's cost Centre's stamp</p> <p style="text-align: right;">AFN READING Official Porsche Centre Bath Road Calcot, Reading Berkshire RG31 7SG Tel: 0118-930 3911</p>
<p><input checked="" type="checkbox"/> Yearly maintenance PORSCHE <input checked="" type="checkbox"/> Vehicle maintenance * JCT600</p> <p>Date: <u>16-10-97</u></p> <p>Job no.: <u>09417</u> CUSTOMER TECHNICAL SERVICE CENTRE</p> <p>Mileage: <u>14805</u> NEVILLE ROAD, BRADFORD BD4 8QW TEL: (01274) 773800 (NEW TEL No.) FAX: (01274) 730019</p> <p>Performed at customer's cost Centre's stamp</p> <p style="text-align: right;"><i>DN</i></p>	<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>14/02/01</u></p> <p>Job no.: <u>137965</u></p> <p>Mileage: <u>44,970</u></p> <p>Performed at customer's cost Centre's stamp</p> <div style="border: 1px solid black; padding: 5px; width: fit-content; margin-left: auto;"> <p>DICK LOVETT LTD PORSCHE SERVICE TEL: 0117 900 3320</p> </div>
<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>27-1-99</u></p> <p>Job no.: <u>35487</u></p> <p>Mileage: <u>21,995.</u></p> <p>Performed at customer's cost Centre's stamp</p> <div style="border: 1px solid black; padding: 5px; width: fit-content; margin-left: auto;"> <p>DICK LOVETT LTD PORSCHE SERVICE TEL: 01793 615888</p> </div> <p style="text-align: right;"><i>[Signature]</i></p>	<p style="text-align: center;"><u>60,000</u></p> <p><input type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>26-7-01</u></p> <p>Job no.: <u>160662</u></p> <p>Mileage: <u>55 558</u></p> <p>Performed at customer's cost Centre's stamp</p> <div style="border: 1px solid black; padding: 5px; width: fit-content; margin-left: auto;"> <p>DICK LOVETT LTD PORSCHE SERVICE TEL: 0117 900 3320</p> </div> <p style="text-align: right;"><i>[Signature]</i></p>

Maintenance Record

Have your car serviced every 12 000 miles/20 000 km or at least once a year.

*Please tick the appropriate box

<input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance * Date: <u>3/3/02</u> Job no.: <u>INT</u> Mileage: <u>63750</u> Performed at customer's cost	 PORSCHE STRASSE Telephone: <u>01 13 2340911</u> Centre's stamp
--	--

<input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance * Date: <u>6th Jun 2005</u> Job no.: <u>1932</u> Mileage: <u>75107</u> Performed at customer's cost	<u>24,000 miles</u> RLR (NORTH EAST) LTD PORSCHE SPECIALIST MIDDLESBROUGH TEL: 01642 751911 Centre's stamp
---	---

<input type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance * Date: <u>27-06-03</u> Job no.: <u>266251</u> Mileage: <u>69,963</u> Performed at customer's cost	<u>72,000</u> DICK LOVETT LTD PORSCHE SERVICE TEL: 0117 900 3320 Centre's stamp
---	--

<input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance * Date: <u>22/8/06</u> Job no.: <u>10112</u> Mileage: <u>76423</u> Performed at customer's cost	Porsche Centre Newcastle Silverlink Park Wallsend Newcastle Upon Tyne NE28 9ND RF Centre's stamp
---	--

<input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance * Date: <u>5/9/03</u> Job no.: <u>INTERNAL</u> Mileage: <u>71454</u> Performed at customer's cost	 PORSCHE STRASSE Telephone: <u>01 13 2340911</u> Centre's stamp
---	--

<input checked="" type="checkbox"/> Yearly maintenance * <input type="checkbox"/> Vehicle maintenance * Date: <u>8 10 07</u> Job no.: <u>18443</u> Mileage: <u>77253</u> Performed at customer's cost	Porsche Centre Newcastle Silverlink Park Wallsend Newcastle Upon Tyne NE28 9ND Centre's stamp
--	--

Maintenance Record

Have your car serviced every 12 000 miles/20 000 km or at least once a year.

*Please tick the appropriate box

<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>18.8.2009</u></p> <p>Job no.: <u>98117</u></p> <p>Mileage: <u>20727</u></p> <p>Performed at customer's cost <i>[Signature]</i> Centre's stamp</p> <div data-bbox="653 316 1094 496" style="border: 1px solid blue; padding: 5px; text-align: center;"> <p>TOM FERGUSON PORSCHE SPECIALIST ENGINEERS TELEPHONE 0191 226 0855</p> </div>	<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>JULY 2013</u></p> <p>Job no.: <u>WR 143</u></p> <p>Mileage: <u>81,610</u></p> <p>Performed at customer's cost Centre's stamp</p> <p><i>* Gearbox oil change + fuel filter</i></p> <div data-bbox="1549 320 1871 485" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>PERFORMANCE PORSCHE <small>Independent Porsche Specialists</small> Call 0800 988 2133</p> </div>
<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>17.8.2010</u></p> <p>Job no.: <u>0945</u></p> <p>Mileage: <u>78582</u></p> <p>Performed at customer's cost <i>[Signature]</i> Centre's stamp</p> <div data-bbox="688 660 1136 836" style="border: 1px solid blue; padding: 5px; text-align: center;"> <p>TOM FERGUSON PORSCHE SPECIALIST ENGINEERS TELEPHONE 0191 4900 777</p> </div>	<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>18-7-2014</u></p> <p>Job no.: <u>9491</u></p> <p>Mileage: <u>83,762</u></p> <p>Performed at customer's cost</p> <div data-bbox="1549 635 2003 975" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>RPM PORSCHE SPECIALIST WWW.RPMTECHNIK.CO.UK</p> </div>
<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>29.2.2012</u></p> <p>Job no.: <u>3229</u></p> <p>Mileage: <u>79551</u></p> <p>Performed at customer's cost</p> <div data-bbox="569 1086 1094 1353" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>PORSCHTEK Specialist Porsche Centre Leeds 0113 2773220 www.porschtek.co.uk</p> </div>	<p><input checked="" type="checkbox"/> Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>21/07/15</u></p> <p>Job no.: <u>11767</u></p> <p>Mileage: <u>87,861</u></p> <p>Performed at customer's cost</p> <div data-bbox="1507 1011 1976 1369" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>RPM PORSCHE SPECIALIST WWW.RPMTECHNIK.CO.UK</p> </div>

Maintenance Record

Have your car serviced between 2 000 – 2 500 miles/3 000 – 4 000 km, thereafter every 12 000 miles/20 000 km or at least once a year.

*Please tick the appropriate box

<p><input type="checkbox"/> Vehicle maintenance 2 000 – 2 500 miles 3 000 – 4 000 km</p> <p>Date: _____</p> <p>Job no.: _____</p> <p>Mileage: _____</p> <p>Performed at customer's cost Centre's stamp</p>	<p><input checked="" type="checkbox"/> ^{6K} Yearly maintenance *</p> <p><input type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>17/07/2014</u></p> <p>Job no.: <u>3234</u></p> <p>Mileage: <u>83,762</u></p> <p>Performed at customer's cost Centre's stamp</p> 
<p><input checked="" type="checkbox"/> ^{12K} Yearly maintenance *</p> <p><input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>20/7/15</u></p> <p>Job no.: <u>4712</u></p> <p>Mileage: <u>87,861</u></p> <p>Performed at customer's cost Centre's stamp</p> 	<p><input checked="" type="checkbox"/> ^{6K} Yearly maintenance *</p> <p><input type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>21/07/16</u></p> <p>Job no.: <u>820</u></p> <p>Mileage: <u>92,85</u></p> <p>Performed at customer's cost Centre's stamp</p> 
<p><input checked="" type="checkbox"/> ^{48K} Yearly maintenance *</p> <p><input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>17/07/17</u></p> <p>Job no.: <u>2823</u></p> <p>Mileage: <u>96,579</u></p> <p>Performed at customer's cost Centre's stamp</p> 	<p><input type="checkbox"/> ^{6K} Yearly maintenance *</p> <p><input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>17/7/18</u></p> <p>Job no.: <u>7010</u></p> <p>Mileage: <u>100644</u></p> <p>Performed at customer's cost Centre's stamp</p>  <p>01923 269 788 www.jzmporsche.com</p>

Maintenance Record

Have your car serviced every 12 000 miles/20 000 km or at least once a year.

*Please tick the appropriate box

<p><input checked="" type="checkbox"/> ^{12K} Yearly maintenance * <input type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>23/8/2019</u> Job no.: <u>22155</u> Mileage: <u>10578</u> Performed at customer's cost</p> <p>RPM Technik PORSCHE SPECIALIST +44 (0)1296 663 824 WWW.RPMTECHNIK.CO.UK Centre's stamp</p>	<p><input checked="" type="checkbox"/> ^{12K} Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>24/08/2020</u> Job no.: <u>23961</u> Mileage: <u>109,246</u> Performed at customer's cost</p> <p>RPM Technik PORSCHE SPECIALIST +44 (0)1296 663 824 WWW.RPMTECHNIK.CO.UK Centre's stamp</p>
<p><input checked="" type="checkbox"/> ^{6K Service} Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>23/08/2021</u> Job no.: <u>25806</u> Mileage: <u>112,898 miles</u> Performed at customer's cost</p> <p>RPM Technik PORSCHE SPECIALIST +44 (0)1296 663 824 WWW.RPMTECHNIK.CO.UK Centre's stamp</p>	<p><input checked="" type="checkbox"/> Yearly maintenance * ^{24K} <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>15-8-2022</u> Job no.: <u>11951</u> Mileage: <u>115212</u> Performed at customer's cost</p> <p>RPM Technik PORSCHE SPECIALIST +44 (0)1296 663 824 WWW.RPMTECHNIK.CO.UK Centre's stamp</p>
<p><input checked="" type="checkbox"/> ^{6K service} Yearly maintenance * <input checked="" type="checkbox"/> Vehicle maintenance *</p> <p>Date: <u>09/08/23</u> Job no.: <u>29694</u> Mileage: <u>118329</u> Performed at customer's cost</p> <p>RPM Technik PORSCHE SPECIALIST +44 (0)1296 663 824 WWW.RPMTECHNIK.CO.UK Centre's stamp</p>	<p><input type="checkbox"/> Yearly maintenance * <input type="checkbox"/> Vehicle maintenance *</p> <p>Date: _____ Job no.: _____ Mileage: _____ Performed at customer's cost</p> <p>Centre's stamp</p>

Record of Brake Fluid Change

The brake fluid must be changed at least every 3 years. (Only use Original Porsche Brake Fluid.)





<p>Brake fluid change</p> <p>Date: <u>27-1-99</u></p> <p>Job no.: <u>35487</u></p> <p>Mileage: <u>21,995</u></p> <p>Performed at customer's cost</p> <div data-bbox="727 304 1137 568" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>DICK LOVETT LTD PORSCHE SERVICE TEL: 01793 615088</p> </div> <p style="text-align: right;">Centre's stamp <i>[Signature]</i></p>	<p>Brake fluid change</p> <p>Date: <u>02-02-00</u></p> <p>Job no.: <u>56819</u></p> <p>Mileage: <u>31844</u></p> <p>Performed at customer's cost</p> <div data-bbox="1734 347 2055 611" style="text-align: right;"> <p>AFN READING Official Porsche Centre Bath Road Calcot, Reading Berkshire RG31 7SG Tel: 0118-930 3911</p> </div> <p style="text-align: right;">Centre's stamp</p>
<p>Brake fluid change</p> <p>Date: <u>26-7-01</u></p> <p>Job no.: <u>160662</u></p> <p>Mileage: <u>55 558</u></p> <p>Performed at customer's cost</p> <div data-bbox="711 703 1109 951" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>DICK LOVETT LTD PORSCHE SERVICE TEL: 0117 900 3320</p> </div> <p style="text-align: right;">Centre's stamp <i>[Signature]</i></p>	<p>Brake fluid change</p> <p>Date: <u>27-06-03</u></p> <p>Job no.: <u>266251</u></p> <p>Mileage: <u>69,963</u></p> <p>Performed at customer's cost</p> <div data-bbox="1589 719 1967 967" style="border: 1px solid black; padding: 5px; text-align: center;"> <p>DICK LOVETT LTD PORSCHE SERVICE TEL: 0117 900 3320</p> </div> <p style="text-align: right;">Centre's stamp <i>[Signature]</i></p>
<p>Brake fluid change</p> <p>Date: <u>22/8/06</u></p> <p>Job no.: <u>10112</u></p> <p>Mileage: <u>76423</u></p> <p>Performed at customer's cost</p> <div data-bbox="701 1094 1094 1326" style="text-align: center;"> <p>Porsche Centre Newcastle Silverlink Park Wallsend Newcastle Upon Tyne NE28 9ND</p> </div> <p style="text-align: right;">Centre's stamp</p>	<p>Brake fluid change</p> <p>Date: <u>18.8.2009</u></p> <p>Job no.: <u>9877</u></p> <p>Mileage: <u>77727</u></p> <p>Performed at customer's cost</p> <div data-bbox="1600 1070 2070 1246" style="border: 1px solid blue; padding: 5px; text-align: center;"> <p>TOM FERGUSON PORSCHE SPECIALIST ENGINEERS TELEPHONE 0191 226 0855</p> </div> <p style="text-align: right;">Centre's stamp <i>[Signature]</i></p>

DATE 31/7/13
 JOB No w21437
 MILEAGE 81,610


PERFORMANCE
PORSCHE
Independent Porsche Specialists
Call 0800 988 2133

Record of Brake Fluid Change

The brake fluid must be changed at least every 3 years. (Only use Original Porsche Brake Fluid.)

<p>Brake fluid change</p> <p>Date: <u>18/7/17</u></p> <p>Job no.: <u>2823</u></p> <p>Mileage: <u>96,579</u></p> <p>Performed at customer's cost</p> <p>Centre's stamp</p> 	<p>Brake fluid change</p> <p>Date: <u>2/10/2019</u></p> <p>Job no.: <u>7236</u></p> <p>Mileage: <u>12704</u></p> <p>Performed at customer's cost</p> <p>Centre's stamp</p>  <p>PORSCHE SPECIALIST</p> <p>+44 (0)1296 663 824</p> <p>WWW.RPMTECHNIK.CO.UK</p>
<p>Brake fluid change</p> <p>Date: <u>24/08/2020</u></p> <p>Job no.: <u>23961</u></p> <p>Mileage: <u>109,246</u></p> <p>Performed at customer's cost</p> <p>Centre's stamp</p>  <p>PORSCHE SPECIALIST</p> <p>+44 (0)1296 663 824</p> <p>WWW.RPMTECHNIK.CO.UK</p>	<p>Brake fluid change</p> <p>Date: <u>15-8-2020</u></p> <p>Job no.: <u>11951</u></p> <p>Mileage: <u>115212</u></p> <p>Performed at customer's cost</p> <p>Centre's stamp</p>  <p>PORSCHE SPECIALIST</p> <p>+44 (0)1296 663 824</p> <p>WWW.RPMTECHNIK.CO.UK</p>
<p>Brake fluid change</p> <p>Date: _____</p> <p>Job no.: _____</p> <p>Mileage: _____</p> <p>Performed at customer's cost</p> <p>Centre's stamp</p>	<p>Brake fluid change</p> <p>Date: _____</p> <p>Job no.: _____</p> <p>Mileage: _____</p> <p>Performed at customer's cost</p> <p>Centre's stamp</p>

RPM TECHNIK
Unit 6 and 7
Old Airfield Industri
HP23 4QR

01296 663 824
info@rpmtechnik.co.uk
rpmtechnik.co.uk

RPM Technik
Units 6 & 7, Old Airfield Ind Est
Cheddington Lane, Long Marston
Hertfordshire. HP23 4QR



MERCHANT ID: *****2750
TERMINAL ID: *****9102
DATE: 09/08/2023 TIME: 16:58
BATCH: 000862-006 INVOICE: 003141
RPN: 180000457124 AUTH NO.: 871516
AMERICAN EXPRESS SALE
AID A000000025010801
*****1018 ICC
SALE AMOUNT £1201.98

MANTHEY



SERVICED VEHICLE

Make Porsche
Model 911 3.6 993 Carrera Coupe 2dr
Petrol Manual (272 bhp)
Registration N323NUA
Chassis No WP0ZZ99ZSS315484
Engine No 63S05499
Mileage 118329
Registered 01/08/1995

SERVICE INVOICE

Service No 13784
Invoice No 29694
Date 09/08/2023
Payment
Order No

Your Ref BARKERA

Next Service Due By 09/08/2024 or MIs Service Advisor Simon Bunce

Brief Service Description

- 1) Mot
- 2) 6k service.
- 3) Supply and fit both rear tyres.
- 4) Light in the baggage compartment.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
6k service	2.00	180.00	20.00%
Remove, refit and balance tyre (x2)	1.00	45.00	20.00%
		LABOUR TOTAL:	225.00

PARTS

Description	Qty	Total	VAT Rate
Michelin 255/40 17 PS2 N3 Tyre	2	450.00	20.00%
sump seal ring	2	3.98	20.00%
oil filter	1	20.46	20.00%
oil filter	1	17.66	20.00%
Number plate light	1	33.84	20.00%
		PARTS TOTAL:	525.94

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
Mobil 1 0W 40	13	15.77	205.01	20.00%
			OILS / LUBRICANTS TOTAL:	205.01

EXTRAS

Description	Qty	Total	VAT Rate
MOT	1	8.20	20.00%
		EXTRAS TOTAL:	8.20

Continued from previous page...

Service No 13784

to receive payment by bank transfer, our bank details can be found at the bottom of
Please use the invoice number as reference. Thank you.

Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington
Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort
code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a
period of 3 weeks and then disposed of unless prior arrangements have been made for storage or
collection.

Sub Total	964.15
MOT: Standard	45.00
Retest	0.00
+ VAT Due	192.83

Invoice Total	1,201.98
----------------------	-----------------

Total Payments	0.00
-----------------------	-------------

Total Due	1,201.98
------------------	-----------------

VAT Analysis

VAT @ 0% on 45.00 = 0.00

VAT @ 20% on 964.15 = 192.83

Date..... Signature..... VAT No. GB 946 3435 08



01296 663 824
info@rpmtechnik.co.uk
rpmtechnik.co.uk

RPM
Units
Check
Hert

RPM TECHNIK
Unit 6 and 7
Old Airfield Industri
HP23 4QR

UK Partnerships:



MANTHEY



SERVICED VEHICLE

Make Porsche
Model 911 3.6 993 Carrera Coupe 2dr
Petrol Manual (272 bhp)
Registration N323NUA
Chassis No WP0ZZZ99ZSS315484
Engine No 63S05499
Mileage 115212
Registered 01/08/1995

MERCHANT ID: *****2750
TERMINAL ID: *****9102
DATE: 15/08/2022 TIME: 15:53
BATCH: 000580-002 INVOICE: 002158
RRN: 180000405535 AUTH NO.: 966880
AMERICAN EXPRESS SALE

AID A000000025010801
*****1018 ICC

SALE AMOUNT £2955.97

VERIFIED BY PIN

Your Ref **BARKERA**

Next Service Due By 25/08/2022 or Mls Service Advisor **Maisy Marshall**

Brief Service Description

1) Works as per description.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
24k service	5.50	495.00	20.00%
Brake fluid change	1.00	90.00	20.00%
Clean and replace all brake nipples	0.30	37.50	20.00%
Investigate sun roof issue - inner sun roof coverdetached and become unglued, remove sunroof and remove inner lining, remove all existing glue from inner panel, apply high temperature glue and refit existing leather	4.00	500.00	20.00%
Remove sunroof cable gearbox and reset cable lengths as roof was maladjusted, refit new nylon foot to front of sunroof	3.00	375.00	20.00%
Remove battery, clean out boot floor, investigate reason for leak, clean terminals and wax floor & refit new battery	1.50	187.50	20.00%
Fit two new tub front vents	0.10	12.50	20.00%
		LABOUR TOTAL:	1,697.50

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
SUMPSEALRING	sump seal ring	2	1.99	3.98	20.00%
99310720305	oil filter	1	22.46	22.46	20.00%
99311032701	Air filter	1	24.46	24.46	20.00%
99320720103	oil filter	1	19.66	19.66	20.00%
14FR6LDU	Spark Plug	12	12.08	144.96	20.00%
99357247900	Pollen filter 993	2	34.60	69.20	20.00%
92811025307	Fuel Filter	1	26.15	26.15	20.00%
91163125902	Water drain tube	2	6.42	12.84	20.00%
93035191900	Bleed nipple (set)	4	16.55	66.20	20.00%
444770967	Bosch s4 battery 096	1	137.60	137.60	20.00%
893915507	battery vent pipe (90 deg) elbow	1	5.90	5.90	20.00%
				PARTS TOTAL:	533.41

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
Mobil 1 0W 40	10	15.77	157.70	20.00%
Brake fluid dot 4	1	12.00	12.00	20.00%
			OILS / LUBRICANTS TOTAL:	169.70

EXTRAS

Description	Qty	
MOT	1	
Sundries and lubricants	1	EXTRAS TO

ADVISORY

- Rear centre lamp unit faded
- A/C not cold
- Rear screen rubber/glass tatty
- Drivers door pin switch & cover tempermental/poor
- Slight play in N/S/F & O/S/F shock main shaft bearings
- Both front brake back plated corroded
- Lower part of O/S/F arch liner broken
- Oil leaks from chain housings
- Oil leaks from most rocker covers
- Slight weep from PAS bottle
- Gearbox oil change due next year
- Handbrake shoes to inspect next year

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	2,425.81
MOT: Standard	45.00
Retest	0.00
+ VAT Due	485.16

Invoice Total	2,955.97
----------------------	-----------------

Total Payments	0.00
-----------------------	-------------

Total Due	2,955.97
------------------	-----------------

VAT Analysis	
VAT @ 0% on 45.00 =	0.00
VAT @ 20% on 2,425.81 =	485.16

Date..... Signature.....

VAT No. GB 946 3435 08



01296 663 824
info@rpmtechnik.co.uk
rpmtechnik.co.uk

R
U
C
H

RPM TECHNIK
Unit 6 and 7
Old Airfield Industri
HP23 4QR

UK Partnerships:



MANTHEY - RACING



SERVICED VEHICLE

Make Porsche
Model 911 Carrera Coupe Coupe 3.6
Manual Petrol
Registration N323NUA
Chassis No WP0ZZZ99ZSS315484
Engine No 63S05499
Mileage 112898
Registered 01/08/1995

MERCHANT ID: *****2750
TERMINAL ID: *****3102
DATE: 26/08/2021 TIME: 12:50
BATCH: 000306-001 INVOICE: 001183
RRN: 180000180103 AUTH NO.: 892836
AMERICAN EXPRESS SALE
AID 400000025010801
*****1018 ICC
SALE AMOUNT £833.14

Your Ref BARKERA

Next Service Due By 25/08/2022 or MIs Service Advisor Maisy Marshall

Brief Service Description

1) 6k service. 2) MOT. 3) Investigate brake fluid leak from caliper.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Investigate brake fluid leak from caliper - clean up and replace O/S/R outter bleed nipple	1.40	137.20	20.00%
6k service	2.00	160.00	20.00%
Replace front and rear wiper blade set	0.10	9.80	20.00%
LABOUR TOTAL:			307.00

PARTS

Description	Qty	Price	Total	VAT Rate
Rear wiper blade 964/993	1	19.89	19.89	20.00%
Wiper blade set 993	1	39.74	39.74	20.00%
sump seal ring	2	0.50	1.00	20.00%
oil filter	1	20.04	20.04	20.00%
oil filter	1	17.36	17.36	20.00%
Bleed nipple (set)	1	16.55	16.55	20.00%
PARTS TOTAL:			114.58	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
Mobil 1 0W 40	13	9.00	117.00	20.00%
OILS / LUBRICANTS TOTAL:			117.00	

EXTRAS

Description	Qty	Total	VAT Rate
MOT	1	8.20	20.00%
Wheel refurb	1	110.00	20.00%
EXTRAS TOTAL:			118.20

ADVISORY

Aircon not working
Rear wiper arm has been repaired
Rear centre light cluster has gone opaque
Various small engine oil leaks

Continued from previous page...

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total
MOT: Standard Retest 0.00
+ VAT Due 131.36

Invoice Total 833.14

Total Payments 0.00

Total Due 833.14

VAT Analysis
VAT @ 0% on 45.00 = 0.00
VAT @ 20% on 656.78 = 131.36

Date..... Signature.....

VAT No. GB 946 3435 08



01296 663 824
 info@rpmtechnik.co.uk
 rpmtechnik.co.uk

RP
 Un
 Ch
 He

RPM TECHNIK
 Unit 6 and 7
 Old Airfield Industri
 HP23 4QR

UK Partnerships:



MANTHEY - RACING



SERVICED VEHICLE

Make Porsche
 Model 911 Carrera Coupe Coupe 3.6
 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 110536
 Registered 01/08/1995

MERCHANT ID: *****2750
 TERMINAL ID: *****9102
 DATE: 07/05/2021 TIME: 17:08
 BATCH: 0000219-002 INVOICE: 000851
 PRN: 1800000083279 AUTH NO.: 893378
 AMERICAN EXPRESS SALE
 AID: +000000025010801
 *****1018 ICC

SALE AMOUNT £164.64

VERIFIED BY PIN

Your Ref BARKERA

Next Service Due By 24/08/2021 or MIs Service Advisor Lydia Preston

Brief Service Description

1) Investigate starting fault, carry out battery and charge tests, check all connections, fit customer c-tek lead to battery.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Investigate starting fault, carry out battery and charge tests, check all connections, fit customer c-tek lead to battery.	1.40	137.20	20.00%
LABOUR TOTAL:			137.20

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	137.20
MOT: Standard	0.00
Retest	0.00
+ VAT Due	27.44
Invoice Total	164.64
Total Payments	0.00
Total Due	164.64

VAT Analysis
 VAT @ 20% on 137.20 = 27.44

Date..... Signature..... VAT No. GB 946 3435 08

RPM TECHNIK
Unit 6 and 7
Old Airfield Industri
HP23 4QR

01296 663 824
info@rpmtechnik.co.uk
rpmtechnik.co.uk

RPM Technik
Units 6 & 7, Old Airfield Ind Est
Cheddington Lane, Long Marston
Hertfordshire. HP23 4QR



MERCHANT ID: *****2750
TERMINAL ID: *****9102
DATE: 26/11/2020 TIME: 17:24
BATCH: 000112-003 INVOICE: 000429
RRN: 180000022197 AUTH NO.: 855706
AMERICAN EXPRESS SALE
AID: 4000000000000000



SERVICED VEHICLE

Make Porsche
Model 911 Carrera Coupe Coupe 3.6
Manual Petrol
Registration N323NUA
Chassis No WP0ZZZ99ZSS315484
Engine No 63S05499
Mileage 109558
Registered 01/08/1995

REPAIR INVOICE

Service No 9006
Invoice No 24454
Date 26/11/2020
Payment
Order No

You

Service Advisor Lydia Preston

Brief Service Description

1) Bodyworks.

LABOUR WORK CARRIED OUT

	Hours Charged	Price	Discount	Total	VAT Rate
Strip O/S/R quarter and strip door complete and release oil pipes (further strip may be required on oil pipes), remove and refit	20.00	1,960.00	10.00%	1,764.00	20.00%

LABOUR TOTAL: 1,764.00

PARTS

Description	Qty	Price	Total	VAT Rate
door membrane	1	29.23	29.23	20.00%
993 door handle gasket front	1	7.70	7.70	20.00%
993 door handle gasket rear	1	3.92	3.92	20.00%
foam ring	7	1.56	10.92	20.00%
rear wing foil 993	1	57.81	57.81	20.00%
Tapping screw	5	0.74	3.70	20.00%
Rubber pad (door shut)	1	43.57	43.57	20.00%
joint rubber	1	2.35	2.35	20.00%

PARTS TOTAL: 159.20

EXTRAS

Description	Qty	Total	VAT Rate
Repair O/S/F sill panel, paint O/S/F door, O/S/F door sill and O/S/R quarter	1	1,622.00	20.00%

EXTRAS TOTAL: 1,622.00

Continued from previous page...
payment by bank transfer, our bank details can be found at the bottom of
use the invoice number as reference.

Service No 9006

Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington
Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a
period of 3 weeks and then disposed of unless prior arrangements have been made for storage or
collection.

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total **3,545.20**

+ VAT Due **709.03**

Invoice Total	4,254.23
---------------	-----------------

Total Payments	0.00
----------------	-------------

Total Due	4,254.23
-----------	-----------------

Date..... Signature..... VAT No. GB 946 3435 08

VAT Analysis
VAT @ 20% on 3,545.20 = 709.03

RPM TECHNIK
 Unit 6 and 7
 Old Airfield Industri
 HP23 4QR



+44 (0)1296 663 824
 info@rpmtechnik.co.uk
 www.rpmtechnik.co.uk

VAT: GB 946 3435 08

RPM Independent Porsche
 Specialists Ltd
 Units 6 & 7, Old Airfield Ind Est
 Cheddington Lane, Long Marston
 Hertfordshire HP23 4QR

AMERICAN EXPRESS SALE
 SALE AMOUNT £1761.09
 VERIFIED BY PIN

SERVICED VEHICLE

Make Porsche
 Model 911 Carrera Coupe Coupe 3.6
 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 109246
 Registered 01/08/1995

SERVICE INVOICE

Service No 8623
 Invoice No 23961
 Date 24/08/2020
 Payment
 Order No

Yo

Next Service Due By 24/08/2021 or MIs Service Advisor Lydia Preston

Brief Service Description

1) Works as per description. 2) MOT.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
12k service	2.50	200.00	20.00%
Brake fluid change	1.00	80.00	20.00%
Replace missing centre caps		0.00	20.00%
Replace O/S headlamp lens	1.00	98.00	20.00%
Replace foglamp	0.25	24.50	20.00%
Replace fresh air flap motor	0.50	49.00	20.00%
Replace N/S fresh air fan cover	0.25	24.50	20.00%
LABOUR TOTAL:			476.00

PARTS

Description	Qty	Price	Total	VAT Rate
sump seal ring	2	0.50	1.00	20.00%
oil filter	1	19.46	19.46	20.00%
Pollen filter 993	2	33.61	67.22	20.00%
foglamp	1	224.38	224.38	20.00%
o/s headlamp lens	1	102.86	102.86	20.00%
Wheel centre cap	2	25.46	50.92	20.00%
fresh air flap motor	1	305.78	305.78	20.00%
Trim	1	31.51	31.51	20.00%
oil filter	1	16.84	13.75	20.00%
PARTS TOTAL:			816.88	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
Brake fluid dot 4	1	12.00	12.00	20.00%
Mobil 1 0W 40	13	9.00	117.00	20.00%
OILS / LUBRICANTS TOTAL:			129.00	

EXTRAS

Description	Qty	Total	VAT Rate
MOT	1	8.20	20.00%
EXTRAS TOTAL:			8.20

not working
upper rocker cover leaking
chain housing leaking - not bad

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	1,430.08
MOT: Standard	45.00
Retest	0.00
+ VAT Due	286.01

Invoice Total	1,761.09
----------------------	-----------------

Total Payments	0.00
-----------------------	-------------

Total Due	1,761.09
------------------	-----------------

VAT Analysis	
VAT @ 0% on 45.00 =	0.00
VAT @ 20% on 1,430.08 =	286.01

Date..... Signature..... VAT No. GB 946 3435 08



+44 (0)1296 663 824
 info@rpmtechnik.co.uk
 www.rpmtechnik.co.uk
 VAT: GB 946 3435 08

RPM Independent Porsche
 Specialists Ltd
 Units 6 & 7, Old Airfield Ind Est
 Cheddington Lane, Long Marston
 Hertfordshire HP23 4QR

TO

SERVICED VEHICLE

Make **Porsche**
 Model **911 Carrera Coupe Coupe 3.6 Manual Petrol**
 Registration **N323NUA**
 Chassis No **WP0ZZZ99ZSS315484**
 Engine No **63S05499**
 Mileage **106730**
 Registered **01/08/1995**

SERVICE INVOICE

Service No **7876**
 Invoice No **23116**
 Date **27/02/2020**
 Payment
 Order No

Your Ref **BARKERA**

Next Service Due By **21/08/2020** or MIs Service Advisor **Lydia Preston**

Brief Service Description

1) Works as per description.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Investigate rattle noise at idle from alternator/bearing area, replace belts and pulleys and sensor	3.00	270.00	20.00%
Replace exhaust silencers, straps and heatshields	6.00	540.00	20.00%
Replace fan cowling on top of engine	0.25	22.50	20.00%
Replace rear anti roll bar	0.50	45.00	20.00%
Supply and fit new driveshafts	4.00	360.00	20.00%
Free off for geometry	1.00	90.00	20.00%
Replace engine bay heater fan vaccum unit	0.50	45.00	20.00%
Replace N/S lower rocket cover	1.50	135.00	20.00%
Set ride heights for set up	2.00	180.00	20.00%
Replace rear bumper heatshields	1.00	90.00	20.00%
Replace front track rods	1.50	135.00	20.00%
Replace engine drain tubes	3.00	270.00	20.00%
Geometry setup	3.00	270.00	20.00%
LABOUR TOTAL:			2,452.50

PARTS

Description	Qty	Price	Total	VAT Rate
993 heat shield left	1	68.37	68.37	20.00%
exhaust shield screw clip	5	12.60	63.00	20.00%
heat shield bolt	8	1.94	15.52	20.00%
heat protection	1	68.37	68.37	20.00%
Cat heat shield	1	86.62	86.62	20.00%
993 heat shield right	1	68.37	68.37	20.00%
Lock nut	4	3.57	14.28	20.00%
washer	8	1.13	9.04	20.00%
993 exhaust clamp bolt	4	4.92	19.68	20.00%
seal ring	4	38.77	155.08	20.00%
Clamp	4	30.32	121.28	20.00%
993 rear silencers	1	550.00	550.00	20.00%
clamp	5	3.48	17.40	20.00%
bolt	2	0.74	1.48	20.00%
986 exhaust shield bolt	5	4.89	24.45	20.00%
bolt 964/993 various applications	2	3.38	6.76	20.00%
air duct	1	32.33	32.33	20.00%

Continued from previous page...

Service No 7876

ARB bush	2	29.05	58.10	20.00%
ARB bush clamp	2	10.81	21.62	20.00%
rear stabilizer bar	1	152.04	152.04	20.00%
Dust bell	4	28.14	112.56	20.00%
hub nut	2	23.12	46.24	20.00%
Clip	2	2.54	5.08	20.00%
Clip	2	2.32	4.64	20.00%
Clip	4	3.55	14.20	20.00%
Heat shield Washer	5	0.80	4.00	20.00%
pulley	2	19.04	38.08	20.00%
pulley	2	66.39	132.78	20.00%
Fan Belt	2	17.06	34.12	20.00%
964/993 belt sensor	1	77.53	77.53	20.00%
Vacuum Valve unit	1	73.76	73.76	20.00%
Collapsable drain tube	2	49.61	99.22	20.00%
993 lower cam cover	1	83.00	83.00	20.00%
993 lower cam cover gasket	1	19.96	19.96	20.00%
Screw	11	1.13	12.43	20.00%
cv boot clip large	4	3.30	13.20	20.00%
Driveshaft	2	652.73	1,305.46	20.00%
993 rear light bar grommet	3	0.36	1.08	20.00%
undertray spacer washer	4	2.64	10.56	20.00%
V-belt	1	14.59	14.59	20.00%
suspension nut	2	1.80	3.60	20.00%
track rod end 993	2	177.73	355.46	20.00%

PARTS TOTAL: 4,015.34

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	6,467.84
MOT: Standard	0.00
Retest	0.00
+ VAT Due	1,293.58

Invoice Total	7,761.42
---------------	----------

Total Payments	0.00
----------------	------

Total Due	7,761.42
-----------	----------

VAT Analysis
VAT @ 20% on 6,467.84 = 1,293.58

Date..... Signature..... VAT No. GB 946 3435 08

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001

RPM
TECHNIK

*** CUSTOMER ***

E

SERVICED VEHICLE

Make Porsche
 Model 911 Carrera Coupe Coupe 3.6
 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 105718
 Registered 01/08/1995

23/08/2019

Payment
 Order No

Your Ref BARKERA

Next Service Due By 21/08/2020 or MIs Service Advisor Ian Trahearn

Brief Service Description

1) 12k service. 2) Investigate brake vibration. 3) MOT.4) Replace front discs & pads. 5) Replace rear anti roll bar drop links (Bilstein).

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
12k service	2.50	162.50	20.00%
Investigate brake vibration - carry out road test to confirm fault. Inner faces of front brake discs heavily corroded and require replacing	0.50	45.00	20.00%
replace front discs and pads	1.50	97.50	20.00%
Remove front lower calipers plates, clean up and refit	1.50	135.00	20.00%
Replace rear anti roll bar drop links	1.00	90.00	20.00%
LABOUR TOTAL:			530.00

PARTS

Description	Qty	Price	Total	VAT Rate
sump seal ring	2	0.50	1.00	20.00%
oil filter	1	19.46	19.46	20.00%
oil filter	1	16.84	14.68	20.00%
Pollen filter(kit) 993	2	34.31	68.62	20.00%
Brake pad set	1	174.54	174.54	20.00%
993 front brake disc left	1	135.56	135.56	20.00%
993 front brake disc right	1	135.56	135.56	20.00%
o/s/r drop link (Bilstein)	2	40.20	80.40	20.00%
964/993 brake pad wear sensor front	2	16.00	32.00	20.00%
PARTS TOTAL:				661.82

OILS / LUBRICANTS

Description	Qty	Price	Discount	Total	VAT Rate
Mobil 1 0W 40	13	10.00	43.90%	72.93	0.00%
OILS / LUBRICANTS TOTAL:					72.93

EXTRAS

Description	Qty	Total	VAT Rate
Sundries and lubricants	1	17.00	0.00%
MOT	1	8.20	20.00%
EXTRAS TOTAL:			25.20

ADVISORY

- Various engine oil leaks
- Outer driveshaft gaitors cracking (not leaking grease)
- O/S exhaust tail pipe close to breaking off (silencer corroded)
- Cat heat shields loose/corroded
- N/S silencer strap corroded
- Rear anti roll bar rusty and bushes worn
- Slight play in n/s/f shock absorber (Bilstein)
- Oil cooler has a slight oil leak
- Fan cowling on top of engine/alternator split
- Rattle noise at idle from alternator/bearing area
- A/C not working
- Drivers seat will not adjust back/forward

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	1,289.95
MOT: Standard	45.00
Retest	0.00
+ VAT Due	240.00
Invoice Total	1,574.95
Total Payments	1,574.95
Total Due	0.00

VAT Analysis	
VAT @ 0% on 134.93 =	0.00
VAT @ 20% on 1,200.02 =	240.00

Date..... Signature..... VAT No. GB 946 3435 08



+44 (0)1296 663 824
 info@rpmtechnik.co.uk
 www.rpmtechnik.co.uk

VAT: GB 946 3435 08

RPM Ind
 Speciali
 Units 6 &
 Cheddin
 Hertford

RPM Technik
 Unit 6 and 7
 Old Airfield Industrial Es
 Long Mill Hill Herts AL9 4QR
 1296663824

Herbert ID: 18 5261852750
 Terminal ID: 219160265101

Card ID: 927 111 146
 RRU: 180000077077

Type: CREDIT

AMERICAN EXPRESS
 Number: *****1918
 Card Exp: 12/13
 Card Type: 3759
 CML: 010 20 115
 Hold: 1000
 AID: 400000002561020
 TST: 4800
 Response: APPROVED
 Approval Code: 012147

UNIQUE ID

SERVICED VEHICLE

Make **Porsche**
 Model **911 Carrera Coupe Coupe 3.6 Manual Petrol**
 Registration **N323NUA**
 Chassis No **WP0ZZZ99ZSS315484**
 Engine No **63S05499**
 Mileage **106730**
 Registered **01/08/1995**

Your Ref **BARKERA**

Next Service Due By **21/08/2020** or **Mis** Service Ad

Brief Service Description

1) Works as per description.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Investigate rattle noise at idle from alternator/bearing area, replace belts and pulleys and sensor	3.00	270.00	20.00%
Replace exhaust silencers, straps and heatshields	6.00	540.00	20.00%
Replace fan cowling on top of engine	0.25	22.50	20.00%
Replace rear anti roll bar	0.50	45.00	20.00%
Supply and fit new driveshafts	4.00	360.00	20.00%
Free off for geometry	1.00	90.00	20.00%
Replace engine bay heater fan vaccum unit	0.50	45.00	20.00%
Replace N/S lower rocket cover	1.50	135.00	20.00%
Set ride heights for set up	2.00	180.00	20.00%
Replace rear bumper heatshields	1.00	90.00	20.00%
Replace front track rods	1.50	135.00	20.00%
Replace engine drain tubes	3.00	270.00	20.00%
Geometry setup	3.00	270.00	20.00%

LABOUR TOTAL: 2,452.50

PARTS

Description	Qty	Price	Total	VAT Rate
993 heat shield left	1	68.37	68.37	20.00%
exhaust shield screw clip	5	12.60	63.00	20.00%
heat shield bolt	8	1.94	15.52	20.00%
heat protection	1	68.37	68.37	20.00%
Cat heat shield	1	86.62	86.62	20.00%
993 heat shield right	1	68.37	68.37	20.00%
Lock nut	4	3.57	14.28	20.00%
washer	8	1.13	9.04	20.00%
993 exhaust clamp bolt	4	4.92	19.68	20.00%
seal ring	4	38.77	155.08	20.00%
Clamp	4	30.32	121.28	20.00%
993 rear silencers	1	550.00	550.00	20.00%
clamp	5	3.48	17.40	20.00%
bolt	2	0.74	1.48	20.00%
986 exhaust shield bolt	5	4.89	24.45	20.00%
bolt 964/993 various applications	2	3.38	6.76	20.00%
air duct	1	32.33	32.33	20.00%

Continued from previous page...

Service No.

ARB bush	2	29.05	58.10	20.00%
ARB bush clamp	2	10.81	21.62	20.00%
rear stabilizer bar	1	152.04	152.04	20.00%
Dust bell	4	28.14	112.56	20.00%
hub nut	2	23.12	46.24	20.00%
Clip	2	2.54	5.08	20.00%
Clip	2	2.32	4.64	20.00%
Clip	4	3.55	14.20	20.00%
Heat shield Washer	5	0.80	4.00	20.00%
pulley	2	19.04	38.08	20.00%
pulley	2	66.39	132.78	20.00%
Fan Belt	2	17.06	34.12	20.00%
964/993 belt sensor	1	77.53	77.53	20.00%
Vacuum Valve unit	1	73.76	73.76	20.00%
Collapsable drain tube	2	49.61	99.22	20.00%
993 lower cam cover	1	83.00	83.00	20.00%
993 lower cam cover gasket	1	19.96	19.96	20.00%
Screw	11	1.13	12.43	20.00%
cv boot clip large	4	3.30	13.20	20.00%
Driveshaft	2	652.73	1,305.46	20.00%
993 rear light bar grommet	3	0.36	1.08	20.00%
undertray spacer washer	4	2.64	10.56	20.00%
V-belt	1	14.59	14.59	20.00%
suspension nut	2	1.80	3.60	20.00%
track rod end 993	2	177.73	355.46	20.00%

PARTS TOTAL: 4,015.34

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	6,467.84
MOT: Standard	0.00
Retest	0.00
+ VAT Due	1,293.58
Invoice Total	7,761.42
Total Payments	7,761.42
Total Due	0.00

VAT Analysis
VAT @ 20% on 6,467.84 = 1,293.58

Date..... Signature..... VAT No. GB 946 3435 08

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001



*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU

17:22:53 02/10/19
 Receipt 2627

NTO: ***10221 TID: ****4666

AMERICAN EXPRESS

*****1018

8000000025010801

SALE

CHIP
 £104.40

PIN VERIFIED
 APPROVED

SERVICED VEHICLE

Make Porsche
 Model 911 Carrera Coupe Coupe 3.6
 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 137054
 Registered 01/08/1995

Your Ref BARKERA

Next Service Due By 21/08/2020 or Mls Service Advisor Lydia Marshall

Brief Service Description

1) Brake fluid change.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Brake fluid change	1.00	75.00	20.00%
LABOUR TOTAL:			75.00

OILS / LUBRICANTS

Description	Qty	Total	VAT Rate
Brake fluid dot 4	1	12.00	20.00%
OILS / LUBRICANTS TOTAL:			12.00

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	87.00
MOT: Standard	0.00
Retest	0.00
+ VAT Due	17.40
Invoice Total	104.40
Total Payments	104.40
Total Due	0.00

VAT Analysis
 VAT @ 20% on 87.00 = 17.40

Date..... Signature..... VAT No. GB 946 3435 08

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001



*** CUSTOMER COPY ***
 RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU
 17:12:56 21/06/19
 Receipt 2228
 TID: 4666
 VISA DEBIT
 *****1267
 SALE £1,872.94
 PIN VERIFIED
 APPROVED
 AUTH CODE: 021757
 PLEASE DEBIT BY ACCOUNT
 PLEASE RETAIN RECEIPT

SERVICED VEHICLE

Make Porsche
 Model Porsche 911 Carrera Coupe
 Coupe 3.6 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 105063
 Registered 01/08/1995

Your Ref BARKERA

Next Service Due By 30/08/2019 or Mls Service

Brief Service Description

1) Wheel refurb. 2) Replace tyres. 3) Investigate heater fault (heat stays on into drivers footwell).

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Remove/refit wheels for refurb	1.00	90.00	20.00%
Remove, refit and balance tyre (x4)	2.00	80.00	20.00%
Investigate heater fault - carry out diagnosis and the re-circ vacuum line found to be detached (re-connect). Right hand mixing flap motor also found to be faulty - replace motor and test	2.00	180.00	20.00%

LABOUR TOTAL: 350.00

PARTS

Description	Qty	Price	Total	VAT Rate
fresh air flap motor	1	208.10	208.10	20.00%
Michelin 205/50 17 PS2 N3 Tyre	2	127.19	254.38	20.00%
Michelin 255/40 17 PS2 N3 Tyre	2	165.65	331.30	20.00%

PARTS TOTAL: 793.78

EXTRAS

Description	Qty	Total	VAT Rate
Wheel refurbs	1	400.00	20.00%
Sundries and lubricants	1	17.00	20.00%

EXTRAS TOTAL: 417.00

Continued from previous

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference. Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08. HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub T
MOT: Stand
Retest

+ VAT Due	1,872.94
Invoice Total	1,872.94
Total Payments	1,872.94
Total Due	0.00
VAT Analysis	
VAT @ 20% on 1,560.78 = 312.16	

VAT No. GB 946 3435 08

Date..... Signature.....

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001



*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 TRING YOU

17:14:22 03/09/18
 Receipt 1051

VISA DEBIT

.....1267

SALE £389.55

PIN VERIFIED

APPROVED

SERVICED VEHICLE

Make Porsche
 Model Porsche 911 Carrera Coupe
 Coupe 3.6 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 102445
 Registered 01/08/1995

Your Ref BARKERA

Next Service Due By 30/08/2019 or Mls Service Advisor Craig Humphrey

Brief Service Description

1) Washer fluid leak - Replace headlight washer pump and washer relay.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Investigate washer fluid leak - replace headlamp washer pump and relay	0.50	42.50	0.00%
LABOUR TOTAL:			42.50

PARTS

Description	Qty	Price	Total	VAT Rate
Gasket	2	0.64	1.28	20.00%
Pump	1	238.83	238.83	20.00%
washer bottle pump seal	1	2.29	2.29	20.00%
Washer relay	1	46.80	46.80	20.00%
PARTS TOTAL:			289.20	

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

All goods shall remain the property of the seller until paid for in full. All used parts will be kept for a period of 3 weeks and then disposed of unless prior arrangements have been made for storage or collection.

Sub Total	331.70
MOT: Standard	0.00
Retest	0.00
+ VAT Due	57.85
Invoice Total	389.55
Total Payments	389.55
Total Due	0.00

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001



*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU

14:02:25 24/07/18

Receipt 0009

TID:466b

VISA DEBIT
 *****1267

SALE £229.50

PIN VERIFIED

APPROVED

AUTH CODE 024033

UNRECORDED

SERVICED VEHICLE

Make Porsche
 Model 911 Carrera Coupe Coupe 3.6
 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 101125
 Registered 01/08/1995

Your Ref BARKERA

Next Service Due By 26/08/2018 or MIs Service Advisor Ian Trahearn

Brief Service Description

1) Investigate roof not working.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Investigate roof not working - strip down roof trims to get to mechanisms and found rear height adjusters without fixings. Retrieve fixings, rebuild mechanism and set up heights. Also had to clean up/polish 2 plastic guide plates which were marked	2.25	191.25	20.00%
		LABOUR TOTAL:	191.25

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total 191.25
 MOT: Standard 0.00
 Retest 0.00
 + VAT Due 38.25

Invoice Total 229.50

Total Payments 0.00

Total Due 229.50

VAT Analysis
 VAT @ 20% on 191.25 = 38.25

Date..... Signature..... VAT No. GB 946 3435 08

JZM
KINGS LANGLEY

M:***62841
TID:***5304 5403
SCH ID:918199484861775
HANDSET:1

VISA DEBIT
AID: A0000000031010
VISA DEBIT

*****1267
PAN SEQ NO. 00
ICC
SALE AMOUNT £1,561.82
TOTAL £1,561.82

Chassis No WP0ZZZ99ZSS315484
Engine No 63S05499
Mileage 100641
Registered 01/08/1995

Hertfordshire WD4 8JE
W www.jzmporsche.com
Fennyers, Chelmsford, Essex, CM3 5TQ, England



JZM Ltd Unit 1 L
T 01923 269 788 F 0
Registered as JZM Limited. Registered

SERVICE INVOICE

Service No 7040
Invoice No 6379
Date 18/07/2018
Payment DEBIT / CREDIT CARD
Order No

upe 3.6

Your Ref BARKERA2

Next Service Due By or MIs Service Advisor Chele

Brief Service Description

CARRY OUT MOT AND SUPPLY CERTIFICATE
CARRY OUT 6,000 MILE SERVICE TO MANUFACTURES SPECIFICATIONS AND ROAD TEST
CARRY OUT AIRBAG CHECK
SUPPLY AND FIT SCUTTLE PANEL
RESEAT BATTERY TERMINALS
SUPPLY AND FIT REAR PADS, DISCS AND SENSORS
CHANGE X2 TAIL PIPE CLAMPS
SUPPLIED CLIPS ON DROP LINK BUSHES,
LABOUR WORK CARRIED OUT

	Total	VAT Rate
Labour Standard	172.00	20.00%
Labour Standard	43.00	20.00%
Labour Standard	172.00	20.00%
Labour Additional	107.50	20.00%
LABOUR TOTAL:		494.50

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
90012311830	SUMP WASHERS	2	0.65	1.30	20.00%
CON1	SCREENWASH	1	2.57	2.57	20.00%
99357240300	SCUTTLE TRIM	1	92.66	92.66	20.00%
92811142700	EXHAUST CLAMP 993	2	29.03	58.06	20.00%
90007425202	BOLT EX 993/964	2	4.72	9.44	20.00%
99902512501	WASHER EX/BOLT 964/993	4	1.03	4.12	20.00%
99908405202	LOCK NUT EX 964/993	2	3.29	6.58	20.00%
99361236502	SENSOR	2	12.83	25.66	20.00%
99335204102	BRAKE DISC	2	131.93	263.86	20.00%
96535293904	BRAKE PADS REAR C4	1	115.78	115.78	20.00%
99361236502	SENSOR	2	12.83	25.66	20.00%
PARTS TOTAL:					605.69

OILS / LUBRICANTS

Description	Qty	Total	VAT Rate
1 LTR ENG OIL EDGE 5W/40	12	126.60	20.00%
OILS / LUBRICANTS TOTAL:			126.60

EXTRAS

Description	Qty	Total	VAT Rate
Consumables	1	8.95	20.00%

Retail disposal	1	8.95	20.00%
Access Charge	1	24.50	20.00%
EXTRAS TOTAL:			42.40

Soon Data protection laws in the UK will be changing. Therefore we want to make sure that you are still happy to receive occasional email or text updates from JZM Porsche Ltd Porsche Ltd about your Service, Mot reminders, Market reports and promotions and any other opportunities. Please note that you can change your mind and unsubscribe at any time.

I agree and give my consent for JZM Porsche Ltd to have my contact details for the purpose above, JZM will not pass this information on to any other 3rd Parties.

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect, a customers statutory rights. All goods shall remain the property of the seller until paid for in full. Please note anything stored without special arrangement maybe disposed of after 1 month.

JZM Bank Details: Any payments made direct to our Bank account can you please quote your Surname & invoice number
Barclays Bank
A/c No : 83871754
Sort Code: 20-05-03

Sub Total	£1,269.19
Less Discount	1.00
Sub Total	£1,268.19
MOT: Standard	40.00
Retest	0.00
+ VAT Due	253.63
Invoice Total	£1,561.82
Total Payments	1,561.82
Total Due	£0.00

*** CUSTOMER COPY ***

RPM
UNIT 6 & 7
AIRFIELD INDUSTRIAL E
CHEDDINGTON LANE
THANK YOU

17:38:42 14/05/18

Receipt 0609

1101 1101

VISA DEBIT

1267

SALE

14 998 129



SERVICED VEHICLE

Make Porsche
Model Porsche 911 Carrera Coupe
Coupe 3.6 Manual Petrol
Registration N323NUA
Chassis No WP0ZZZ99ZSS315484
Engine No 63S05499
Mileage 100349
Registered 01/08/1995

REPAIR INVOICE

Service No 4214.01
Invoice No 18929
Date 30/04/2018
Payment
Order No

Service Advisor Craig Humphrey

Brief Service Description

1) Repair rust to windscreen area.

LABOUR WORK CARRIED OUT

	Total	VAT Rate
Line 1	0.00	20.00%
LABOUR TOTAL:		0.00

PARTS

Description	Qty	Price	Total	VAT Rate
wing to scuttle seal 993	2	16.26	32.52	20.00%
993 front bumper seal left	1	20.00	20.00	20.00%
993 front bumper seal right	1	20.00	20.00	20.00%
cover frame	1	58.50	58.50	20.00%
cover strip	1	44.81	44.81	20.00%
PARTS TOTAL:			175.83	

EXTRAS

Description	Qty	Total	VAT Rate
Replace windscreen	1	600.00	20.00%
Repair scuttle panel	1	320.00	20.00%
Repair paint scuttle panel	1	220.00	20.00%
Paint bonnet	1	330.00	20.00%
Paint wings	1	540.00	20.00%
Paint A pillars	1	150.00	20.00%
Paint and materials	1	720.00	20.00%
Sundries	1	20.00	20.00%
EXTRAS TOTAL:			2,900.00

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Date..... Signature..... VAT No. GB 946 3435 08

Sub Total 3,075.83

+ VAT Due 615.16

Invoice Total 3,690.99

Total Payments 0.00

Total Due 3,690.99

VAT Analysis	
VAT @ 20% on 3,075.83 =	615.16

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001



SERVICED VEHICLE

Make Porsche
 Model Porsche 911 Carrera Coupe
 Coupe 3.6 Manual Petrol
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 100349
 Registered 01/08/1995

SERVICE INVOICE

Service No 4214.02
 Invoice No 18986
 Date 14/05/2018
 Payment
 Order No

Your Ref BARKERA

Next Service Due By 26/08/2018 or MIs Service Advisor Craig Humphrey

Brief Service Description

1) Repair rust to windscreen area. 2) Replace battery.

LABOUR WORK CARRIED OUT

	Hours Charged	Total	VAT Rate
Remove and refit front bumper	4.00	232.00	20.00%
Remove and refit front wing fittings	2.00	116.00	20.00%
Remove and refit bonnet and fittings	1.50	87.00	20.00%
Remove and refit scuttle fittings	2.00	116.00	20.00%
LABOUR TOTAL:			551.00

PARTS

Description	Qty	Price	Total	VAT Rate
edge protection	2	18.46	36.92	20.00%
Washer Jet	1	31.09	31.09	20.00%
Grille	1	23.39	23.39	20.00%
993 front bumper seal left	1	25.48	25.48	20.00%
993 front bumper seal right	1	22.31	22.31	20.00%
plastic nut	2	0.15	0.30	20.00%
Support clip 964 rear sharkfin	1	2.38	2.38	20.00%
self tapping screw for undertray etc	4	1.48	5.92	20.00%
Breather hose cap	2	3.66	7.32	20.00%
Wing Support Washer	2	2.40	4.80	20.00%
Bosch S3 battery 72AH	1	128.51	128.51	20.00%
PARTS TOTAL:			288.42	

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total	839.42
MOT: Standard	0.00
Retest	0.00
+ VAT Due	167.88

Invoice Total 1,007.30

Total Payments 0.00

Total Due 1,007.30

VAT Analysis	
VAT @ 20% on 839.42 = 167.88	

Date..... Signature..... VAT No. GB 946 3435 08

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001

*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU

16:15:25 29/08/17

Receipt 0886

TID: ...10221

TID: ...4666

VISA DEBIT

*****1259

#000000031010

CHIP

SALE

£1,519.57

OICE

360.01

7293

2/08/2017

SERVICED VEHICLE

Make/Model Porsche
 Porsche
 3.6 Manu
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS315484
 Engine No 63S05499
 Mileage 98428
 Registered 01/08/1995

Order No

Your Ref BARKERA

Next Service Due By 26/08/2018 or Mls Service Advisor Craig Humphrey

Brief Service Description

1) Replace rear tyres. 2) Replace front wiper blades and adjust washer jets. 3) Remove and refit steering rack for overhaul.

LABOUR WORK CARRIED OUT

	Hours Charged	Price	Discount	Total	VAT Rate
Remove refit tyre balance wheel (x2)	2.00	40.00		40.00	20.00%
Replace front wiper blades and adjust washer jets	0.40	30.00	10.00%	27.00	20.00%
Remove and refit steering rack for overhaul	6.00	450.00	10.00%	405.00	20.00%
				LABOUR TOTAL:	472.00

PARTS

Description	Qty	Price	Discount	Total	VAT Rate
steering rack gaiter 993	2	4.29		8.58	20.00%
Wiper blade set 993	1	34.34		34.34	20.00%
Pirelli 255/40 17 Pzero N3	2	155.00		310.00	20.00%
suspension nut	2	1.60		3.20	20.00%
993 Recon Steering Rack (exchange)	1	320.00		320.00	20.00%
911/964/993 etc Wheel Nut (aluminium)	8	6.90	27.54%	40.00	20.00%
steering rack column rubber	1	21.52		21.52	20.00%
993 wiper blade rubber buffer	1	3.76		3.76	20.00%
Manual	1	21.92		21.92	20.00%
				PARTS TOTAL:	763.32

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate	
Pentosin power steering fluid	1	15.99	15.99	20.00%	
				OILS / LUBRICANTS TOTAL:	15.99

EXTRAS

Description	Qty	Price	Total	VAT Rate	
Sundries and lubricants	1	15.00	15.00	20.00%	
				EXTRAS TOTAL:	15.00

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Date..... Signature.....

VAT No. GB 946 3435 08

Sub Total	
MOT: Standard Retest	253.26
+ VAT Due	1,519.57
Invoice Total	0.00
Total Payments	1,519.57
Total Due	
VAT Analysis	
VAT @ 20% on 1,266.31 = 253.26	

Tel: +44 (0)1296 663 824
 Email: info@rpmtechnik.co.uk
 Web: www.rpmtechnik.co.uk
 Independent Porsche Specialists
 Established 2001

*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU

15:06:44 18/07/17
 Receipt 0712

NID: ***10221 TID: ****4666

VISA DEBIT
 *****1259

80000000031010 CHIP

SALE £1,115.99 017

PIN VERIFIED
 APPROVED

SERVICED VEHICLE

Make/Model Porsche
 Porsche 911 Ca
 3.6 Manual Petr
 Registration N323NUA
 Chassis No WP0ZZZ99ZSS3
 Engine No 63S05499
 Mileage 96579
 Registered 01/08/1995

Your Ref BARKERA

Next Service Due By 18/07/2018 or Mls Service Advisor Craig Humphrey

Brief Service Description

1) 48k service. 2) Brake fluid change. 3) MOT. 4) Replace n/s number plate lamp. 5) Replace n/s/f side light bulb.

LABOUR WORK CARRIED OUT

	Price	Discount	Total	VAT Rate
48k service	390.00	10.00%	351.00	20.00%
Brake fluid change	65.00	10.00%	58.50	20.00%
Replace n/s number plate lamp and n/s/f side light bulb	7.50	10.00%	6.75	20.00%

LABOUR TOTAL: 416.25

PARTS

Description	Qty	Price	Total	VAT Rate
sump seal ring	4	0.50	2.00	20.00%
Fuel filter	1	22.26	20.66	20.00%
Spark Plug	12	7.98	92.16	20.00%
Air filter	1	22.49	20.07	20.00%
Pollen filter(kit) 993	2	34.31	62.40	20.00%
Oil filter 993 oil tank(large)	1	14.68	13.36	20.00%
oil filter	1	19.42	19.42	20.00%
Number plate light	1	22.85	22.85	20.00%
12V 5W festoon bulb	1	0.99	0.99	20.00%
12 volt 4 watt bulb	1	0.45	0.45	20.00%
Bleed nipple	1	14.46	14.46	20.00%

PARTS TOTAL: 268.82

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
Mobil 1 0W 40	13	10.00	117.00	20.00%
Mobil PTX 75/90 gear oil	3.6	17.02	61.27	20.00%
Brake fluid dot 4	1	12.00	12.00	20.00%

OILS / LUBRICANTS TOTAL: 190.27

EXTRAS

Description
Sundries and lubricants

Qty
1
Price
15.00

EXTRAS TOTAL

ADVISORY

- Air con not working
- Wipers smearing and washers require adjusting
- Power steering cap seal broken
- Rear tyres worn to 2/3mm
- Front oil cooler has small oil leak
- Light oil leak from chest covers/chain housings
- Slight rattle from n/s silencer pipe heat shield
- Rear discs rusty on inner edges
- Steering rack leaking under n/s gaiter

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total	890.34
MOT: Standard	45.00
Retest	0.00
+ VAT Due	180.65

Invoice Total 1,115.99

Total Payments 0.00

Total Due 1,115.99

VAT Analysis
VAT @ 0% on 45.00 = 0.00
VAT @ 20% on 890.34 = 178.05

Date..... Signature.....

VAT No. GB 946 3435 08

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk
 HERTS | BEDS | BUCKS | SERVICING | SALES | TRACK

*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU



17:02:47 24/01/17
 Receipt 0051
 MID: ***10221 TID: ****4666
 VISA DEBIT
 *****1259
 R000000031010 CHIP
 SALE £706.62
 PIN VERIFIED
 Mileage 94880
 Registered 01/08/1995

INV

SERVICE
 Make/Mod
 Registratio
 Chassis No
 Engine No
 Mileage
 Registered

SERVICE INVOICE
 Service No 1637
 Invoice No 15674
 Date 24/01/2017
 Payment
 Order No

Your Ref BARKERA

Next Service Due By 22/07/2017 or MIs Service Advisor Craig Humphrey

Brief Service Description

1) Investigate alarm fault, carry out extended tests. Remove alarm control to send away for testing. No fault found with control unit, supplied new unit as good will. Alarm fault still apparent. Replaced alarm system with aftermarket unit.

LABOUR WORK CARRIED OUT

	Price	Discount	Total	VAT Rate
Investigate alarm fault, remove control unit for testing	399.70	50.00%	199.85	20.00%
LABOUR TOTAL:			199.85	

EXTRAS

Description	Qty	Price	Total	VAT Rate
Fit Hornet Max 1 alarm system	1	389.00	389.00	20.00%
EXTRAS TOTAL:			389.00	

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total 588.85
 MOT: Standard 0.00
 Retest 0.00
 + VAT Due 117.77

Invoice Total 706.62

Total Payments 0.00

Total Due 706.62

VAT Analysis
 VAT @ 20% on 588.85 = 117.77

Date..... Signature..... VAT No. GB 946 3435 08

*** CUSTOMER COPY ***

RPM
UNIT 6 & 7
AIRFIELD INDUSTRIAL E
CHEDDINGTON LANE
THANK YOU

15:06:56 15/12/16

Receipt 2441

TIID: ...13221 TIID: ...4666

VISA DEBIT

*****1259

0000000031010 CHIP

SALE £366.08

PIN VERIFIED
APPROVED

Fax: 01296 660099
Website: www.rpmspecialists.co.uk

VICING SALES TRACK



SERVICED VEHICLE

Make/Model Porsche
Porsche 911 Carrera Coupe Coupe
3.6 Manual Petrol
Registration N323NUA
Chassis No WP0ZZZ99ZSS315484
Engine No 63S05499
Mileage 93609
Registered 01/08/1995

SERVICE INVOICE

Service No 1582
Invoice No 15501
Date 15/12/2016
Payment
Order No

Next Service Due By 22/07/2017 or MIs Service Advisor Craig Humphrey

Brief Service Description

1) Investigate alarm fault - cleaned up door switches, tested wiring in door, replaced n/s door contact rubber and solenoid. Cleared faults with tester. Alarm is working correctly at time of testing.

LABOUR WORK CARRIED OUT

	Price	Discount	Total	VAT Rate
Investigate alarm fault - replace n/s door solenoid	263.90	10.00%	237.51	20.00%
LABOUR TOTAL:			237.51	

PARTS

Description	Qty	Price	Total	VAT Rate
Actuator	1	65.54	65.54	20.00%
rubber cap int light door switch	1	2.02	2.02	20.00%
PARTS TOTAL:			67.56	

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total 305.07
MOT: Standard 0.00
Retest 0.00
+ VAT Due 61.01

Invoice Total 366.08

Total Payments 0.00

Total Due 366.08

VAT Analysis
VAT @ 20% on 305.07 = 61.01

Date..... Signature..... VAT No. GB 946 3435 08

Telephone: 01296 663824
 Email: info@rpmtechnik.co.uk
 HERTS BEDS BUCKS SE

*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU



17:13:31 02/12/16
 Receipt 2406

IID: ...10221 TID: ...9666

VISA DEBIT
 *****1259
 A0000000031010 CHIP
 SALE £182.81

PIN VERIFIED
 APPROVED

911 Carrera Coupe Coupe
 al Petrol
 A
 :99ZSS315484
 99

SERVICE INVOICE

Service No 1521
 Invoice No 15425
 Date 02/12/2016
 Payment
 Order No

Registered 01/08/1995

Your Ref BARKERA

Next Service Due By 22/07/2017 or MIs Service Advisor Craig Humphrey

Brief Service Description

1) Investigate alarm fault - going off upto 20 times a day - Carry out diagnostic checks. 7 faults in memory for various different things. Erase fault memory and none returned. Check through system and find only remove control coded to off, recoded to on. Lock vehicle and leave to test. Alarm did not go off for 3 days, took on roadtest and alarm still not going off.

LABOUR WORK CARRIED OUT

	Price	Discount	Total	VAT Rate
Investigate alarm fault	152.60	10.00%	137.34	20.00%
LABOUR TOTAL:			137.34	

EXTRAS

Description	Qty	Price	Total	VAT Rate
Sundries and lubricants	1	15.00	15.00	20.00%
EXTRAS TOTAL:			15.00	

We are happy to receive payment by bank transfer, our bank details can be found at the bottom of the invoice. Please use the invoice number as reference.

Thank you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total	152.34
MOT: Standard	0.00
Retest	0.00
+ VAT Due	30.47

Invoice Total	182.81
----------------------	---------------

Total Payments	0.00
----------------	------

Total Due	182.81
------------------	---------------

VAT Analysis	
VAT @ 20% on 152.34 = 30.47	

Date..... Signature..... VAT No. GB 946 3435 08

*** CUSTOMER COPY ***

RPM
UNIT 6 & 7
AIRFIELD INDUSTRIAL E
CHEDDINGTON LANE
THANK YOU

01296 660099
site: www.rpmspecialist.co.uk

SALES | TRACK



11:34:24 15/10/16

Receipt 2229

NTD: ***10221 TID: ***4666

VISA DEBIT

*****1259

8000000031010

CHIP

SALE £2,092.58

PTN VERIFIED

SERVICED VEHICLE

Make/Model Porsche
Porsche 911 Carrera Coupe Coupe
3.6 Manual Petrol
Registration N323NUA
Chassis No WP0ZZZ99ZSS315484
Engine No 63S05499
Mileage 93259
Registered 01/08/1995

SERVICE INVOICE

Service No 1154
Invoice No 15127
Date 15/10/2016
Payment
Order No

Next Service Due By 22/07/2017 or MIs Service Advisor Craig Humphrey

Brief Service Description

1) Replace door top seals. 2) Replace door frame seals, window seals and powdercoat frames.

LABOUR WORK CARRIED OUT

	Price	Discount	Total	VAT Rate
Replace door top trims	57.40	10.00%	51.66	20.00%
Replace door frame seals	882.70	10.00%	794.43	20.00%

LABOUR TOTAL: 846.09

PARTS

Description	Qty	Price	Total	VAT Rate
Door Top Seal	1	79.85	79.85	20.00%
Door Top Seal	1	79.85	79.85	20.00%
Door Seal	1	158.94	158.94	20.00%
Door Seal	1	158.94	158.94	20.00%
End Cap	1	1.12	1.12	20.00%
End Cap	1	1.12	1.12	20.00%
Door membrane	2	25.22	50.44	20.00%
Joint rubber	1	29.27	29.27	20.00%
Joint rubber	1	29.27	29.27	20.00%
rubber seal	1	7.46	7.46	20.00%
Sealing frame	1	45.97	45.97	20.00%
trim plug	2	0.22	0.44	20.00%
Window location rail	1	107.45	107.45	20.00%
glass channel seal	2	24.93	49.86	20.00%
Pan-head screw	2	1.38	2.76	20.00%

PARTS TOTAL: 802.74

EXTRAS

Description	Qty	Price	Total	VAT Rate
Sundries and lubricants	1	15.00	15.00	20.00%
Powdercoating	2	40.00	80.00	20.00%

EXTRAS TOTAL: 95.00

To receive payment by bank transfer, our bank details can be found at the bottom of
please use the invoice number as reference.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington
Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total	1,743.83
MOT: Standard	0.00
Retest	0.00
+ VAT Due	348.75

Invoice Total	2,092.58
---------------	----------

Total Payments	0.00
----------------	------

Total Due	2,092.58
-----------	----------

VAT Analysis
VAT @ 20% on 1,743.83 = 348.75

Date..... Signature..... VAT No. GB 946 3435 08

*** CUSTOMER COPY ***

RPM
UNIT 6
AIRFIELD INDUSTRIAL E
CHEDDINGTON LANE
THANK YOU

11:33:19 22/07/16
Receipt 1923

TID: ...10221 TID: ...4666

VISA DEBIT
*****1259

SALE £502.70

PIN VERIFIED
APPROVED



SERVICED VEHICLE

Make/Model Porsche
Porsche 911 Carrera Coupe Coupe
3.6 Manual Petrol
Registration N323NUA
Chassis No WP0ZZ99ZSS315484
Engine No 63S05499
Mileage 92852
Registered 01/08/1995

SERVICE INVOICE

Service No 820
Invoice No 14706
Date 22/07/2016
Payment
Order No

Next Service Due By 22/07/2017 or MIs Service Advisor Craig Humphrey

Brief Service Description

1) 6k service. 2) MOT. 3) Adjust trim on front bumper. 4) Replace side repeaters. 5) Replace n/s number plate lamp.

LABOUR WORK CARRIED OUT

	Price	Discount	Total	VAT Rate
993 6K service	140.00	10.00%	126.00	20.00%
Replace side repeaters	14.00	10.00%	12.60	20.00%
Adjust trim on front bumper	21.00	10.00%	18.90	20.00%
Replace n/s number plate lamp	14.00	10.00%	12.60	20.00%
LABOUR TOTAL:			170.10	

PARTS

Description	Qty	Price	Total	VAT Rate
Clear Side Repeater Kit	1	10.00	10.00	20.00%
iris blue touch up stick	1	12.58	12.58	20.00%
sump seal ring	2	0.50	1.00	20.00%
Oil filter 993 Engine (small)	1	17.36	17.36	20.00%
Oil filter 993 oil tank(large)	1	13.36	13.36	20.00%
Number plate light	1	22.85	22.85	20.00%
PARTS TOTAL:			77.15	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
Mobil 1 0W 40	13	10.00	117.00	20.00%
OILS / LUBRICANTS TOTAL:			117.00	

EXTRAS

Description	Qty	Price	Total	VAT Rate
Sundries and lubricants	1	15.00	15.00	20.00%
EXTRAS TOTAL:			15.00	

ADVISORY

Air con not very cold
Cigar lighter not working
o/s/f wheel arch liner cracked but secure

to receive payment by bank transfer, our bank details can be found at the bottom of
Please use the invoice number as reference.

you.

RPM Independent Porsche Specialists Ltd, Unit 6 & 7, Old Airfield Industrial Estate, Cheddington
Lane, Long Marston, Tring, HP23 4QR VAT GB 946 3435 08

HSBC/ Branch Leighton Buzzard / Sort code: 40-28-12 Account No: 81497766

Sub Total	379.25
MOT: Standard	45.00
Retest	0.00
+ VAT Due	78.45

Invoice Total	502.70
----------------------	---------------

Total Payments	0.00
-----------------------	-------------

Total Due	502.70
------------------	---------------

VAT Analysis	
VAT @ 0% on 45.00 = 0.00	
VAT @ 20% on 379.25 = 75.85	

Date..... Signature..... VAT No. GB 946 3435 08

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk



HERTS | BEDS | BUCKS | SERVICING | SALES | TRACK

Issued By : RPM Porsche Specialists

Invoice

Invoice No. **12749**
 Account No. **BAR021**
 Order Ref.
 Invoice Date. **30/11/2015**
 Payment Method. **Pending**
 Date of Work. **01/12/2015**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	91333

1) Replace alarm siren and board. 2) Replace drive belts.

Labour Description	Qty	Unit Price	Price
Replace alarm siren and board	3	70.00	210.00
Replace drive belts	0.5	70.00	35.00
Labour Sub Total			245.00

Parts Description	Qty	Unit Price	Price
Alarm siren PA2000	1	85.00	85.00
Alarm board and remote PA2000	1	205.00	205.00
Fan Belt	2	11.08	22.16
Narrow V-belt	2	14.31	28.62
V-belt	1	13.07	13.07
Parts Sub Total			353.85

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

Net Subtotal	598.85
VAT at 20%	119.76
Total Due	718.61

Thanks.

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmspecialists.co.uk Website: www.rpmspecialists.co.uk
 HERTS BEDS BUCKS SERVICING SALES TRACK

*** CUSTOMER COPY ***

RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU



16:59:31 01/12/15
 Receipt 1135

010 ...10221 T10 ...4666
 VISA DEBIT
 *****1259
 80000000031010
 SALE £1,282.49

PIN VERIFIED

VOICE

Invoice No. **12717**
 Invoice Unit No. **BAR021**
 Invoice Ref.
 Invoice Date. **19/11/2015**
 Payment Method. **Card**
 Date of Work. **19/11/2015**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZ99ZSS315484	3600	91333

1) Investigate non start - replace starter motor. 2) Investigate alarm fault - requires siren.

Labour Description	Qty	Unit Price	Price
Replace starter motor	2	70.00	140.00
Investigate alarm fault	0.5	70.00	35.00
Labour Sub Total			175.00

Parts Description	Qty	Unit Price	Price
recovery	1	50.00	50.00
964/993 Recon starter Motor (exchange)	1	220.00	220.00
undertray securing bolt	2	2.38	4.76
Shield Retaining clip	2	2.57	5.14
Parts Sub Total			279.90

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

Thanks.

PAID IN FULL

Sundries	10.00
Lubricants	5.00
Net Subtotal	469.90
VAT at 20%	93.98
Sub Total	563.88
Receipt	-563.88
Balance Due	0.00

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmspecialists.co.uk Website: www.rpmspecialists.co.uk
 HERTS BEDS BUCKS | SERVICING | SALES | TRACK

RPM
 PORSCHE SPECIALIST

Issued By : RPM Porsche Specialists

INVOICE

Invoice No. **12749**
 Account No. **BAR021**
 Order Ref. **30/11/2015**
 Invoice Date. **Card**
 Payment Method. **01/12/2015**
 Date of Work.

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	91333

1) Replace alarm siren and board. 2) Replace drive belts.

Labour Description	Qty	Unit Price	Price
Replace alarm siren and board	3	70.00	210.00
Replace drive belts	0.5	70.00	35.00
Labour Sub Total			245.00

Parts Description	Qty	Unit Price	Price
Alarm siren PA2000	1	85.00	85.00
Alarm board and remote PA2000	1	205.00	205.00
Fan Belt	2	11.08	22.16
Narrow V-belt	2	14.31	28.62
V-belt	1	13.07	13.07
Parts Sub Total			353.85

Net Subtotal	598.85
VAT at 20%	119.76
Sub Total	718.61
Receipt	-718.61
Balance Due	0.00

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

PAID IN FULL

Thanks.

Telephone: 01296 663824 Fax: 01296 663825
 Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk
 HERTS BEDS BUCKS SERVICING SA

Anselm
 *** CUSTOMER COPY ***
 RPM
 UNIT 6 & 7
 AIRFIELD INDUSTRIAL E
 CHEDDINGTON LANE
 THANK YOU
 16:27:56 14/08/15
 Receipt 0788
 NTD ...10221 TID ...4666
 MASTERCARD
 *****1957



INVOICE

Invoice No. **12051**
 Account No. **BAR021**
 Order Ref.
 Invoice Date. **14/08/2015**
 Payment Method. **Card**
 Date of Work. **01/09/2015**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	0

1) Supply suspension parts for 993 works.

£3,969.97 TAKEN VIA CARD ON 14-8

Labour Description	Qty	Unit Price	Price
--------------------	-----	------------	-------

Parts Description	Qty	Unit Price	Price
Bilstein B12 Suspension kit	1	1,095.00	1,095.00
993 suspension top mount front	2	139.69	279.38
993 rear suspension top mount	2	127.13	254.26
Rear drop link 993	2	143.23	286.46
Powerflex front wishbone bush 964/993 (pair)	1	55.56	55.56
993 rear upper control arm	2	157.09	314.18
993 rear upper control arm	2	157.09	314.18
993 lower suspension track arm	2	181.10	362.20
Sun Roof Liner	1	332.08	332.08

Parts Sub Total 3,293.30

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

Thanks.



Sundries	10.00
Lubricants	5.00
Net Subtotal	3,308.30
VAT at 20%	661.67
Sub Total	3,969.97
Receipt	-3,969.97
Balance Due	0.00

*** CUSTOMER COPY ***

RPM
UNIT 6 & 7
AIRFIELD INDUSTRIAL E
CHEDDINGTON LANE



Telephone: 01296 663824 Fax: 01296 663801
Email: info@rpmtechnik.co.uk Web: www.rpmtechnik.co.uk
HERTS | BEDS | BUCKS | SERVICES

globalpayments

globalpay

INVOICE

Invoice No. **11767**
Account No. **BAR021**
Order Ref.
Invoice Date. **21/07/2015**
Payment Method. **Card**
Date of Work. **20/07/2015**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	87861

1) 12k service 2) MOT.

Labour Description	Qty	Unit Price	Price
Carry out MOT test			
12k service	2.5	65.00	162.50
Labour Sub Total			162.50

Parts Description	Qty	Unit Price	Price
Oil filter 993 Engine (small)	1	14.70	14.70
Oil filter 993 oil tank (large)	1	11.32	11.32
Pollen filter 993	2	30.83	61.66
Mobil 1 0W 40	13	10.00	130.00
sump seal ring	2	0.50	1.00
993 drain plug	1	14.89	14.89
Parts Sub Total			233.57

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

Thanks.

PAID IN FULL

Sundries	10.00
Lubricants	5.00
Net Subtotal	411.07
VAT at 20%	82.21
MOT	45.00
Sub Total	538.28
Receipt	-538.28
Balance Due	0.00

INVOICE

Invoice No. **11767**
 Account No. **BAR021**
 Order Ref.
 Invoice Date. **21/07/2015**
 Payment Method. **Card**
 Date of Work. **20/07/2015**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	87861

Important Information / Advisory Notices

A/C condensers weeping
 Aircon not cold
 Both rear toe arms split
 Brake fluid moisture 2 % - OK
 Exhaust tip clamps corroded / cracking
 Rear exhaust flange nuts bolts corroded
 Slight oil leaks from both chain housings
 Small undertray corner missing (still secure)
 Tab broken / missing from near side pollen filter (still secure)
 Sills on top of doors coming off
 Steering wheel slightly right hand down
 Bump stops perished
 Lower arms perishing
 rear upper link arm bushes worn
 Front shock shaft pitted

Telephone: 01296 663824 Fax: 01296 660099
Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk

HERTS | BEDS | BUCKS | SERVICING | SALES | TRACK



Issued By : RPM Porsche Specialists

ESTIMATE

Estimate Number: **4706**
Account Number: Bar021
Order Ref:
Estimate Date: 15/06/2015
Estimate Valid to : 15/07/2015
Page Number: 1

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	

1) Fit Bilstein suspension. 2) Geo

Description	Qty	Unit Price	Price
Replace front and rear suspension for Bilstein	8	70.00	560.00
Brake Bleed	0.5	70.00	35.00
Remove and refit lower arms	0.5	70.00	35.00
Fit powerflex lower arms	1.5	70.00	105.00
Replace all rear track arms	0.5	70.00	35.00
Geometry setup	2	65.00	130.00
Labour Sub Total			900.00

Parts description	Qty	Unit Price	Price
Bilstein B12 Suspension kit	1	1,095.00	1,095.00
993 suspension top mount front	2	139.69	279.38
993 rear suspension top mount	2	127.13	254.26
Rear drop link 993	2	143.23	286.46
Brake line 993 front caliper	1	18.25	18.25
Brake line 993 front caliper	1	16.00	16.00
Brake fluid	1	12.00	12.00
Powerflex front wishbone bush 964/993 (pair)	1	55.56	55.56
993 rear upper control arm	2	157.09	314.18
993 rear upper control arm	2	157.09	314.18
993 lower suspension track arm	2	181.10	362.20
964 bump stop	2	12.51	25.02
993 rear bump stop	2	11.52	23.04
Geometry setup	1	90.00	90.00
Parts Sub Total			3,145.53

RPM Independent Porsche Specialists Ltd, Units 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston
Tring, Hertfordshire, HP23 4QR VAT GB 946 3435 08
Bank: HSBC / Branch Leighton Buzzard / Sort Code 40-28-12 / Account No. 81497766

Telephone: 01296 663824 Fax: 01296 660099
Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk

HERTS | BEDS | BUCKS | SERVICING | SALES | TRACK



Issued By : RPM Porsche Specialists

ESTIMATE

Estimate Number: **4706**
Account Number: Bar021
Order Ref:
Estimate Date: 15/06/2015
Estimate Valid to : 15/07/2015
Page Number: 2

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	

I agree to pay for all work and parts required for the repairs described above at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. Any additional work found to be necessary must be authorised by myself prior to commencement. All goods shall remain the property of the seller until paid for in full.

I have read and accept your terms and conditions.

Nothing herein is designed to nor will it affect a customers statutory rights

Signed _____ Date _____

SUNDRIES	10.00
LUBRICANTS	5.00
LABOUR & PARTS	4,060.53
VAT at 20%	812.11
ESTIMATE TOTAL	4,872.64

Information relating to this Estimate

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk

HERTS BEDS BUCKS SERVICING SALES TRACK



RPM Porsche
 RPM Porsche
 TRING

53110221 28137766
 27/10/14 16:08 3270

VISA DEBIT ICC
 A0000000031010
 *****1242
 Exp: 10/15 Start: 09/12 00

10099
 BAR021

SALE

27/10/2014

od. Card

24/10/2014

Total £1,488.92...

Issued By : RPM Po

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	84238

1) Replace caps, leads and rotors. 2) Replace lower cam covers. 3) Replace oil tank sender seal. 4) Drain oil and clean off all leaks, refill and carry out oil level check.

Labour Description	Qty	Unit Price	Price
Replace caps, leads and rotors	4	70.00	252.00
Replace lower cam covers	2.5	70.00	157.50
Replace oil tank sender seal	0.5	70.00	31.50
Drain oil and clean off all leaks, refill and carry out oil level check	0.5	70.00	31.50
Labour Sub Total Less Discount Of 10%			472.50

Parts Description	Qty	Unit Price	Price
Dist cap 964/993	2	90.38	180.76
Rotor Arm 964/993	2	37.66	75.32
Ign lead set 993	1	312.00	312.00
993 lower cam cover	2	67.39	134.78
993 lower cam cover gasket	2	16.54	33.08
Allen head Bolt 993 cam covers	22	0.56	12.32
Gasket 964/993 oil level sender unit	1	5.05	5.05
Parts Sub Total			753.31

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

Thanks.

PAID IN FULL

Sundries	10.00
Lubricants	5.00
Net Subtotal	1,240.81
VAT at 20%	248.16
Sub Total	1,488.97
Receipt	-1,488.97
Balance Due	0.00

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmtechnik.co.uk Website: www.rpmtech
 HERTS BEDS BUCKS SERVICING SALES TRACK

RPM Porsche
 RPM Porsche
 TRING



Issued By: R

53110221 28137766
 17/09/14 17:12 3151

UISA DEBIT ICC
 A0000000031010

*****1242
 Exp: 10/15 Start: 09/12 00

SALE

Total £558.31

INVOICE

No. **9819**
 : No. **BAR021**
 ef.
 Date. **17/09/2014**
 : Method. **Card**
 Vork. **16/09/2014**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	84161

1) Wax chassis ends. 2) Replace rear bumper brackets. 3) Repair rear heatshield - all rear heatshields needs replacing. 4) Replace spoiler curtain.

Labour Description	Qty	Unit Price	Price
Replace rear bumper brackets	2	70.00	140.00
Replace spoiler curtain	0.5	70.00	35.00
Repair rear heatshield	0.1	70.00	7.00
Wax chassis ends	0.25	70.00	17.50
Labour Sub Total			199.50

Parts Description	Qty	Unit Price	Price
Support	1	19.90	19.90
Support	1	19.90	19.90
Bumper Support 993	1	59.17	59.17
Bumper Support 993	1	58.90	58.90
993 rear bumper heat protection bracket	2	5.65	11.30
Bumper bracket washer 993	2	1.39	2.78
Tapping screw	4	0.26	1.04
Bolt	2	0.26	0.52
Plain washer	2	0.26	0.52
Spoiler curtain	1	59.12	59.12
Number plate light	1	17.62	17.62
Parts Sub Total			250.77

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

Thanks.

PAID IN FULL

Sundries	10.00
Lubricants	5.00
Net Subtotal	465.27
VAT at 20%	93.04
Sub Total	558.31
Receipt	-558.31
Balance Due	0.00

RPM Independent Porsche Specialists Ltd, Units 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston
 Tring, Hertfordshire, HP23 4QR VAT GB 946 3435 08
 Bank: HSBC / Branch Leighton Buzzard / Sort Code 40-28-12 / Account No. 81497766

Telephone: 01296 663824
 Email: info@rpmtechnik.co.uk

HERTS BEDS BUCKS SERV

RPM Porsche
 RPM Porsche
 TRING



53110221 28137766
 18/07/14 15:59 2972

MasterCard ICC
 80000000041010
 *****6017
 Exp: 11/14 Start: 12/11 03

pecialists

Total £438.55
 Verified by PIN

Invoice

Invoice No. **9491**
 Account No. **BAR021**
 Order Ref.
 Invoice Date. **18/07/2014**
 Payment Method. **Card**
 Date of Work. **17/07/2014**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	83762

1) MOT. 2) 6k service. 2) Investigate belt squeak. 3) Investigate lights behind dash not working. 4) Investigate fault with alarm, no siren.

Labour Description	Qty	Unit Price	Price
Carry out MOT test			
993 6K service	1.5	65.00	87.75
Adjust alternator belt	0.25	70.00	15.75
Replace dash light bulb	0.25	70.00	15.75
Investigate fault with alarm system - no fault found	0.5	70.00	31.50

Labour Sub Total Less Discount Of 10% 150.75

Parts Description	Qty	Unit Price	Price
Mobil 1 0W 40	13	10.00	130.00
Oil filter 993 oil tank (large)	1	11.32	11.32
Oil filter 993 Engine (small)	1	14.70	14.70
sump seal ring	2	0.50	1.00

Parts Sub Total 157.02

We are happy to receive payment by bank transfer and our bank details can be found at the bottom of the page. Please use the invoice number for the reference.

Thanks.



Sundries	10.00
Lubricants	5.00
Net Subtotal	322.77
Surcharge	5.19
VAT at 20%	65.59
MOT	45.00
Sub Total	438.55
Receipt	-438.55
Balance Due	0.00



Issued By: RPM Porsche Specialists

Invoice

Invoice No. **9491**
Account No. **BAR021**
Order Ref.
Invoice Date. **18/07/2014**
Payment Method. **Card**
Date of Work. **17/07/2014**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	83762

Important Information / Advisory Notices

- ✓ Underseal O/S/R 1/4 due to weld repair
- Suggest underseal oil tank due to rust
- N/S/F and O/S/F shock shaft pitted and scored
- Screw missing O/S/F bumper and loose
- Oil cooler weeping and A/C condensers
- Screw missing N/S/F wheel arch liner
- O/S/R and N/S/R upper link arm bushes worn x 2
- Both rear toe arms split
- ✓ Oil sender leaking (seal)
- Both front bump stops perished
- ✓ Ignition lead set
- possibly requires spark plugs
- ✓ Oil leak from LH lower rocker cover
- Front lower arms perishing
- ✓ Rear bumper support bars heavily corroded and one is missing
- ✓ Rear bumper heat shields rattling and loose
- ✓ Spoiler curtain broken

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk



HERTS BEDS BUCKS SERVICING SALES TRACK

Issued By : RPM Porsche Specialists

ESTIMATE

Estimate Number: **3357**
 Account Number: Bar021
 Order Ref:
 Estimate Date: 18/07/2014
 Estimate Valid to : 17/08/2014
 Page Number: 2

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	

✓ Ign lead set 993		1	312.00	312.00
✓ Spark Plug		12	7.68	92.16
✓ Rotor Arm 964/993		2	37.66	75.32
✓ Dist cap 964/993		2	90.38	180.76
✓ 993 lower cam cover		1	67.39	67.39
✓ Allen head Bolt 993 cam covers		11	0.56	6.16
Powerflex Front wishbone bush (pair)		1	65.24	65.24
Powerflex front wishbone bush 964/993 (pair)		1	55.56	55.56
✓ Spoiler curtain		1	59.12	59.12
✓ Support		1	57.44	57.44
✓ Support		1	57.71	57.71
✓ Support		1	19.41	19.41
✓ Support		1	19.41	19.41
✓ misc heat shield fixings		1	25.00	25.00
Fan Belt		2	11.08	22.16
964 centre console tray (rear)		1	14.21	14.21
964 centre console handbrake tray		1	11.30	11.30
rubber insert 964 centre console rear section		1	4.42	4.42
993 wiper blade rubber buffer		1	3.07	3.07
Wiper blade set 993		1	30.60	30.60
			Parts Sub Total	3,495.16

I agree to pay for all work and parts required for the repairs described above at your retail charge. It is understood that any estimate given is provisional and all repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. Any additional work found to be necessary must be authorised by myself prior to commencement. All goods shall remain the property of the seller until paid for in full. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect a customers statutory rights
 Signed _____ Date _____

SUNDRIES	10.00
LUBRICANTS	5.00
LABOUR & PARTS	4,875.16
VAT at 20%	975.01
ESTIMATE TOTAL	5,850.17

Information relating to this Estimate

£70 per hour

RPM Independent Porsche Specialists Ltd, Units 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston
 Tring, Hertfordshire, HP23 4QR VAT GB 946 3435 08
 Bank: HSBC / Branch Leighton Buzzard / Sort Code 40-28-12 / Account No. 81497766

Telephone: 01296 663824 Fax: 01296 660099
 Email: info@rpmtechnik.co.uk Website: www.rpmtechnik.co.uk



HERTS BEDS BUCKS SERVICING SALES TRACK

Issued By : RPM Porsche Specialists

ESTIMATE

Estimate Number: **3357**
 Account Number: Bar021
 Order Ref:
 Estimate Date: 18/07/2014
 Estimate Valid to : 17/08/2014
 Page Number: 1

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	

→ 1) Underseal as required TBC. 2) Fit front dampers, top mounts, and bump stops. 3) Replace rear suspension link arms. 4) Replace oil cooler

Description	Qty	Unit Price	Price
Fit front dampers, top mounts, and bump stops	2.5	70.00	175.00
Replace rear suspension link arms	3	70.00	210.00
Replace oil cooler	2	70.00	140.00
Change oil level gasket	0.5	70.00	35.00
✓ Replace spark plugs, caps, rotors and ignition leads	3.5	70.00	245.00
✓ Replace lower cam cover	1	70.00	70.00
Re bush from lower arms	3	70.00	210.00
✓ Replace spoiler curtain	1	70.00	70.00
✓ Change all rear bumper mount brackets	1.5	70.00	105.00
✓ secure heatshields	0.5	70.00	35.00
Change belt set	1	70.00	70.00
Labour Sub Total			1,365.00

Parts description	Qty	Unit Price	Price
993 front damper	1	299.00	299.00
993 front damper	1	299.00	299.00
964/993 bump stop	2	12.51	25.02
993 suspension top mount front	2	139.69	279.38
Brake line 993 front caliper	1	15.65	15.65
Brake line 993 front caliper	1	18.25	18.25
Brake fluid dot 4	1	12.00	12.00
oil cooler 964/993	1	380.57	380.57
993 rear upper control arm	2	153.24	306.48
993 rear upper control arm	2	157.07	314.14
993 lower suspension track arm	2	181.09	362.18
✓ Gasket 964/993 oil level sender unit	1	5.05	5.05

RPM Independent Porsche Specialists Ltd, Units 6 & 7, Old Airfield Industrial Estate, Cheddington Lane, Long Marston
 Tring, Hertfordshire, HP23 4QR VAT GB 946 3435 08
 Bank: HSBC / Branch Leighton Buzzard / Sort Code 40-28-12 / Account No. 81497766

CUSTOMER

CAR DETAILS

NAME: _____
 ADDR: _____
 POSTCODE: _____

MAKE: Porsche
 MODEL: 993
 REG NO: AJ323UVA
 MILEAGE: 82089ms
 CHASSIS NO: _____
 FUEL: E 1/4 1/2 3/4 F



Car-Tech & Care
 Porsche & Performance Car Specialist

Unit 10 • Station Road Business Park • Station Road
 Brompton-on-Swale • North Yorks DUO 75N • Tel: 01748 810788
 Email: car-techandcare@live.com
 Sino-Brit Technology and Culture Development Company Ltd. Reg No: 7933499

DATE: 14-09-13
 INVOICE NO: 546

SERVICE / REPAIRS DESCRIPTION

£ P

PARTS / MATERIALS DESCRIPTION

QTY RATE £ P

Car out to address 65 00
TO PORSCHE ATTACHTOR
BELT 32 00

V-BELT (FRU) 1 4-15
V-BELT (ATTACHTOR) 2 15-65

TOTAL LABOUR CHARGES £

97 00

TOTAL PARTS & MATERIALS £

~~4-15~~
 19 80

TOTAL OILS & LUBRICANTS £

97 00

SERVICE RECOMMENDATIONS/ATTENTION REQUIRED

THANK YOU FOR YOUR CUSTOM

MOT CERT NO:

NEXT SERVICE DUE:

I have read and accept your terms and conditions of business. I agree to pay for all work and materials prior to collection of the vehicle unless satisfactory credit arrangements have been established. I understand any estimate is provisional. Any additional work must be authorised by myself prior to commencement.

Customer Signature

LABOUR	97 00
SUBTOTAL	
VAT %	
MOT TEST	
TOTAL £	116 80

PERFORMANCE PORSCHE

Issued By : Performance-Porsche Ltd 0800 988 2133

INVOICE

Invoice No. **1437**
 Account No. **W00004**
 Order Ref.
 Invoice Date. **31/07/2013**
 Payment Method. **Pending**
 Date of Work. **31/07/2013**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
N323NUA	PORSCHE 911	WP0ZZZ99ZSS315484	3600	81,610

To carry out work in accordance with Porsche Cars GB Limited.

To carry out an annual Mot

To carry out a major service inc 11 litres of 10w-40 Porsche approved semi synthetic oil, 2 x oil filters, air filter, pollen filter, 12 x spark plugs and all top up fluid, lubricants and greases.

Additional maintenance. Replace fuel filter. (every 48,000 miles).

Additional maintenance. Carry out a brake fluid change. (every 3 yeras).

Additional maintenance. Replace gearbox oil. (every 48,000 miles)

Labour working on front end panel gaps inc removal of arch liners etc.

Thank you for using Performance-Porsche Limited.

VAT No - 144 7814 01

Labour Description	Qty	Unit Price	Price
Mot	1	45.00	45.00
Major service	1	315.00	315.00
Replace fuel filter	1	28.80	28.80
Change brake fluid	1	55.00	55.00
Drain gearbox oil and fill with new	1	55.00	55.00
Additional labour charges	3	45.00	135.00
Labour Sub Total			633.80

Parts Description	Part No	Qty	Unit Price	Price

Net Subtotal	633.80
VAT at 20%	117.76
Total Due	751.56

Perfectionists In All Things Porsche



Performance Porsche Ltd:
 Unit 14, SDH Holdings Industrial Estate,
 West Street, Sowerby Bridge, Halifax, HX6 3BS

www.performance-porsche.co.uk

Registered Address:

Central Place, Clayton, Bradford, BD14 6AZ
 Registered in England. Number 7891064

freephone: 0800 988 2133



Hamilton & Palmer

Designers, Manufacturers & Installers of Vehicle Security Systems

F1 Chaucer Business Park

Watery Lane

Kemsing, Sevenoaks

Kent

TN15 6PL

Tel 01732 - 760022 Fax 01732 - 760033

Email accounts@hamilton-palmer.co.uk

PERFORMANCE PORSCHE
 UNIT 14 S D H INDUSTRIAL ESTATE
 WEST STREET
 SOWERBY BRIDGE
 WEST YORKSHIRE HX6 3BS

DETAILS

PA2000 CONTROL BOARD



Account Comments

PAYMENT RECEIVED WITH THANKS

DELIVERY ADDRESS

WOOD

HAMILTON & PALMER INST L

UNIT F1

CHAUCER BUSINESS PARK,

M**29054

TID****2190

MASTERCARD

**** * 0317

DOC KEYED

EATHER

DEL SALE

CUS CARDHOLDER COPY

ORD PLEASE KEEP THIS RECEIPT
FOR YOUR RECORDS

DOC

ACC

AMOUNT £174.00

CUSTOMER NOT PRESENT

THANK YOU

11:46 23/08/13

AUTH CODE: 630834

1	130.00	130.00
---	--------	--------

Sub Total	130.00
Carriage Charge	15.00
Net Total	145.00
VAT	29.00
Invoice Total	174.00



PERFORMANCE PORSCHE

Issued By : Performance-Porsche Ltd 0800 988 2133

Invoice No. **1064**
 Account No. **W00004**
 Order Ref.
 Invoice Date. **27/03/2012**
 Registration **N323 NUA**
 Make & Model **Porsche 911**
 Mileage

To carry out work in accordance with Porsche Cars GB Limited.

To remove 3 x auxiliary belts and supply and fit 3 x new.

To remove fuel tank sender unit, and thoroughly clean all connections and pipes, refit and test.

To realign the front PU (bumper) FOC

To refix the bonnet badge with new fixings.

Labour Description	Qty	Unit Price	Price
Total labour charges	2	40.00	80.00
Labour Sub Total			80.00

Parts Description	Part No	Qty	Unit Price	Price
3 auxiliary belts and Porsche fixing kit for bonnet badge		1	35.25	35.25
Parts Sub Total			35.25	

Net Subtotal 115.25

Total Due 115.25

Perfectionists In All Things Porsche



Performance Porsche Ltd;
 Unit 14, SDH Holdings Industrial Estate,
 West Street, Sowerby Bridge, Halifax, HX6 3BS

www.performance-porsche.co.uk

Registered Address:

Central Place, Clayton, Bradford, BD14 6AZ
 Registered in England, Number 7891064

freephone: 0800 988 2133

TOM FERGUSON

MOTOR ENGINEERS LIMITED

18 SALTMEADOWS ROAD • GATESHEAD • TYNE & WEAR • NEB 3AH

TEL: 0191 490 0777 FAX: 0191 477 0904

WEB: WWW.TOMFERGUSON.COM

INVOICE NUMBER: 0445.

CUSTOMER	MAKE 993	DATE 17.8.2010.
	REG. NO. N323NOA	MILES 78582
	CHASSIS NO.	
DESCRIPTION	PARTS	
YEARLY MAINTENANCE.	GAS STRUTS.	
	60.00.	
Replace all four hood stays		
	PART	60.00
	LABOUR	120.00.
	LUBRICANTS	
<p>I have read and agree to the Conditions of Business displayed and authorise you to carry out the above work and subsequent repairs found on inspection to the limit specified by me.</p> <p>Authorised Signature <u>Paul Cash</u></p> <p>Vehicle Report _____</p> <p>_____</p> <p>_____</p> <p>_____</p>	PETROL	
	SUB-LET	
	CARRIAGE	
	MOT TEST	
	SUB-TOTAL	180.00
	VAT	31.50
	TOTAL	211.50

TOM FERGUSON

MOTOR ENGINEERS LIMITED

18 SALTMEADOWS ROAD • GATESHEAD • TYNESIDE • NE8 3AH

TEL: 0191 4900777 FAX: 0191 4770904

WEB: WWW.TOMFERGUSONMOTORENGINEERS.COM

INVOICE NUMBER: 98MM

CUSTOMER	MAKE 993 .	DATE 18.8.2009.
	REG. NO. N323NUA.	MILES 777.27.
	CHASSIS NO.	
DESCRIPTION	PARTS	
Major service	Oil filter x 2	27.00.
Replace brake fluid	Antifreeze	20.00
Replace clutch fluid	Pollen filters	40.00.
<p>I have read and agree to the Conditions of Business displayed and authorise you to carry out the above work and subsequent repairs found on inspection to the limit specified by me.</p> <p>Authorised Signature <u>Paul Cook</u></p> <p>Vehicle Report _____</p> <p>_____</p> <p>_____</p> <p>_____</p>	PART	817.00.
	LABOUR	250.00.
	LUBRICANTS	700.00
	PETROL	
	SUB-LET	
	CARRAIGE	
	MOT TEST	
	SUB-TOTAL	437.00
VAT	65.55	
TOTAL	502.55	

Porsche Centre Newcastle

Official Porsche Centre
 Silverlink Park, Wallsend
 Newcastle, NE28 9ND
 Telephone: 0191 295 1234
 Fax: 0191 295 3486
 Email: info@porschenewcastle.co.uk
 Web: www.porsche.co.uk/newcastle

CASH SALE INVOICE

Invoice Name & Address

Customer Name & Address

You were served by: **Danielle Morley** Operator: **DM**

Account No.	Document Number	Date & Tax Point	Repair Date	Order Number	
C1202	12004490	09/10/2007			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
Porsche 993	WPOZZZ99ZSS315484		77253	15:03	1
Reference No.	Reg No.	Reg Date.	VSF No.	W.I.P. No.	Job No.
	N323NUA	01/08/1995		W 18443	3749

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
A	S18 Carry out 12000 mile service to manufacturer's specification PORSCHE CLUB MEMBER				240.57	S
X	P993.110.327.01 AIRFILTER 993	1	17.90	EACH	16.11	S
X	P993.572.479.00 POLLEN FILTER 993	2	28.40	EACH	51.12	S
X	P000.044.000.87 SCREENWASH FLUID	1	2.86	EACH	2.58	S

E. & O. E.		V	Rate	Service/Goods	V.A.T.		
Parts	69.81	S	17.50	310.38	54.32	Net	310.38
Surcharge	0.00					V.A.T.	54.32
Labour	318.13					Total	364.70
Sublet	0.00					Paid	364.70
Menus	0.00					Owing	0.00



PORSCHE

- = Requires Urgent Attention
- = Advise
- = Visually OK

WIP No 18443

Wty Yes No Type _____ Expires _____

Last Service _____ MOT Date 1/8/8 MOT Insurance Expiry Date _____ Mileage _____

Wheels and Tyres						NB Legal depth UK = 1.6mm (At 3mm you have 1.4mm of legal tread left)		Red	Green	Advise	Follow up
Depth in mm	inner	mid	outer	PSI	Make, size, speed	Condition of Wheels / Tyres					
Right Front	5.5	6.3	6.4	36	205/50				✓		
Left Front	5.6	6.1	6.2	36	Pirelli 2R 17 N3				✓		
Right Rear	3.9	3.9	4.4	36	255/40	(alloy chipped)			✓		
Left Rear	4.1	3.7	3.7 3.6	36					✓		
Spare			3.6								

Wheel Alignment Requires Adjustment Yes No

Brakes and Hubs										
Brake Discs	Min Rec	Actual	Rec Change	Technicians Comments/ Recommendations	Brake Pads	Pad Thickness mm			Rec Change	Technicians Comments/ Recommendations
						New	Actual	Usable		
Right Front		32.1		NEW BRAKES OK	Right Front					(OK)
Left Front		32.1			Left Front					
Right Rear		23.2			Right Rear					
Left Rear		23.2			Left Rear					

Handbrake Travel/Operation		✓		
Pipes & Hoses/Cables		✓		
Wheel Brg/Hub Wear/Noise		✓		
Steering/Suspension		✓		
Drive Shaft/Joints/Boots		✓		

External		Technicians Comments/Recommendations	
Excess Engine Smoke	Advise Emission Check <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Exhaust System/Condition		✓	
Clutch Operation		✓	
Glass/Mirrors/Damage		✓	

Lights/Electrics (specify)		Technicians Comments/Recommendations	
External		✓	
Internal		✓	
Wipers/Washers/Horn		✓	

Under Bonnet		Technicians Comments/Recommendations	
Engine Oil Level/Fluid Levels		✓	
Alternator Condition/Noise		✓	
Leaks: Oil/Fluid/Coolant		✓	

Technician JH DL JP Signature [Signatures] Date 08/10/07

Service Advisor Signature _____ Centre NEWCASTLE

Received by Customer (Signature) _____ Time _____ Date _____



PORSCHE

Porsche Centre Newcastle

Official Porsche Centre
Silverlink Park, Wallsend
Newcastle, NE28 9ND
Telephone: 0191 295 1234
Fax: 0191 295 3486
Email: info@porscheneewcastle.co.uk
Web: www.porsche.co.uk/newcastle

CASH SALE INVOICE

Customer Name & Address

You were served by: Caroline Kinnear Operator: CK

Table with 5 columns: Account No., Document Number, Date & Tax Point, Repair Date, Order Number. Includes details for account C1202, document 12000174, date 24/08/2006, and vehicle details for a Porsche 993.

Main invoice table with columns: Description of Goods / Services, Qty., Unit Price, Unit Des., Net Total, V. Includes line items for S18 service, various parts like ALUM. SEALI, OIL FILTER, WINDOW CLE, HELIX 10W40 TOPUP, and BRAKE DISC.

Summary table with columns: V, Rate, Service/Goods, V.A.T., Net, V.A.T., Total, Paid, Owing. Shows a total of 758.02.

MATERIALS USED

PART NUMBER	DESCRIPTION	QTY	RATE	£	p
	CLUTCH	1		464	08
	FLYWHEEL (DUAL MASS)	1		416	73

Specialists in
Porsche
and
High Performance
Cars



CUSTOMER

1976

Invoice Number

RLR (North East) Ltd.
Tel 01642 751911 (2 Lines) Fax 01642 751993 E-mail rlr@talk21.com
Dukesway Teesside Industrial Estate Thornaby Cleveland TS17 9LT
Website www.rlracing.co.uk
Directors William G Brough / Simon Leonard / Duncan McNaughton
Registered in England No. 3726706 VAT Registration No. 698 3257 80

PHONE	When Ready	Invoice Date
07976 260246	YES/NO	16/08/05

MAKE/MODEL	REG. No.	CHASSIS No.	Received am	CASH <input type="checkbox"/>
PORSCHE 993 C2	N323 NUA		pm	CREDIT <input type="checkbox"/>
SPEEDO	FUEL	Engine No.	Promised am	WARRANTY <input type="checkbox"/>
075367	E ¼ ½ ¾ F		pm	INTERNAL <input type="checkbox"/>

No.	REPAIR OPERATIONS		
1	REMOVE UNDERTRAYS, CHECK FOR OIL LEAK.	FOC	
2	REMOVE GEARBOX AND REPLACE FLYWHEEL		
3	AND COMPLETE CLUTCH. REFIT GEAR BOX		
4	AND UNDERTRAYS.	360	00

Customer's Description of Fault:	LABOUR	360	00
Tester's Recommendations: I have read and accept your terms of business. I agree to pay for all work and materials prior to collection of the vehicle unless satisfactory credit arrangements have been established.	PARTS	880	81
	OILS		
	SUB TOTAL	1240	81
	VAT 17.5 %	217	14
	MOT TEST		
	TOTAL DUE £	1457	95

OILS	PARTS £	880	81
Thank you for your custom	OILS £		

Next Service Due: Customer's Signature

MATERIALS USED

PART NUMBER	DESCRIPTION	QTY	RATE	£	p
1	GASKET	1		17	85
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
	OILS		PARTS £	17	85
	Thank you for your custom		OILS £		

Specialists in
Porsche
and
High Performance
Cars

RLR
(NORTH EAST)

CUSTOMER

1933

Invoice Number

RLR (North East) Ltd.
Tel 01642 751911 (2 Lines) Fax 01642 751993 E-mail rlr@talk21.com
Dukesway Teesside Industrial Estate Thornaby Cleveland TS17 9LT
Website www.rlracing.co.uk
Directors William G Brough / Simon Leonard / Duncan McNaughton
Registered in England No. 3726706 VAT Registration No. 698 3257 80

PHONE

When Ready

Invoice Date

YES/NO

05/07/05

MAKE/MODEL

REG. No.

CHASSIS No.

Received am

CASH CREDIT

SPEEDO

FUEL

Engine No.

Promised am

WARRANTY INTERNAL

No.

REPAIR OPERATIONS

1 Carry out 24,000m's SERVICE, Carry out
2 full check over of Car
3
4

375 00

5 Check for oil leak on o/s Rocker Cover.
6 REMOVE REAR SILENCER + HEATER PIPES, REMOVE
7 COVER + CLEAN UP FACES. REPLACE GASKET. Refit
8 + CHECK OVER.
9
10

160 00

Customer's Description of Fault:

LABOUR

535 00

Tester's Recommendations:

I have read and accept your terms of business. I agree to pay for all work and materials prior to collection of the vehicle unless satisfactory credit arrangements have been established.

PARTS

17 85

OILS

SUB TOTAL

532 85

VAT %

96 74

MOT TEST

TOTAL DUE £

649 59

Next Service Due:

Customer's Signature



PORSCHE

Dick Lovett Limited
Official Porsche Centre

Portwall Lane, Redcliffe Way
BRISTOL BS1 6NG
Telephone 0117 900 3320
Telefax 0117 900 3335
Website www.dicklovett.co.uk

REPAIR INVOICE

Page Number : 2

- Invoice To -
Service Cash Account

Invoice Number : 354539/wsh/071
Repair Order No.: 0266251
Date : 27/06/2003
Invoice Type : Chargeable/Retail
Stock Number : 1055713
Vehicle : 911
Registration No : N323NUA
Chassis No : 99SS315484
Date of Regn. : 01/08/1995
Mileage : 69,963

Customer Number: 999998

Order/Claim Number:

Part No./ Op Code	Description	Value	Quantity		Nett	VR
92811025306	FUEL FILTER	19.76	1	12.00	17.39	1
99310090100	MAINTENANCE SE	75.00	1	12.00	66.00	1
99990101741	WINDOW CLEANER	3.13	1	12.00	2.75	1
RESPONSE	BRAKE FLUID DOT 4	8.50	1	12.00	7.48	1
Total Parts					93.62	
--- OTHER CHARGES ---						
	Castrol GTX magnatec engine oil	59.00		12.00	51.92	1
Total Other					51.92	

Nett Total	VR	VAT %	Value	Total VAT
384.29	1	17.50	0.00	67.25

67.25

*DON'T FORGET TO LOOK OVER OUR EXTENSIVE RANGE OF PORSCHE
*GIFT IDEAS ON DISPLAY, THE IDEAL GIFT FOR ANY ENTHUSIAST.

Your Service Contact is : Sarah Breddy

Consumables.....	14.50
Total Labour	224.25
Total Parts	93.62
Total Other Charges.....	51.92
Total	384.29

Less Insurance Excess

Total VAT	67.25
Invoice Total	451.54
Due:.... Cash	



Registered Office: Ashworth Road, Bridgemoor
Swindon SN5 7UR
Registered in England No. 414098
VAT Registration No. 576 1316 37



PORSCHE

Dick Lovett Limited
Official Porsche Centre

Portwall Lane, Redcliffe Way
BRISTOL BS1 6NG
Telephone 0117 900 3320
Telefax 0117 900 3335
Website www.dicklovett.co.uk

REPAIR INVOICE

Page Number : 1

Invoice To -
Service Cash Account

Driver

Invoice Number : 354539/wsh/071
Repair Order No.: 0266251
Date : 27/06/2003
Invoice Type : Chargeable/Retail
Stock Number : 1055713
Vehicle : 911
Registration No : N323NUA
Chassis No : 99SS315484
Date of Regn. : 01/08/1995
Mileage : 69,963

Customer Number: 999998

Order/Claim Number:

Part No./ Op Code	Description	Value	Quantity	Nett	VR
	--- LABOUR ---				
	Carried out 72,000 service			195.00	1
	Carried out Status Report				
	Tyre Report:-				
	All tyres 7.0 mm				
	Note:-				
	Clutch heavy				
	O/S no. plate lamp inop				
	Fan belt switch faulty				
	Air/con resistor failed and oil cooler resistor failed				
	front bumper has to be removed to repair				
	1X floor grommet missing				
	Brake fluid change required			29.25	1
SB	Service booklet not supplied			0.00	1
	Status report carried out			0.00	1
	Investigate air bag light coming on after 1/2 mile of driving.			0.00	1
	Fault shows warning lamp				
	(int) - Erased - Keep monitored.				
	--- PARTS ---				
	Total Labour			224.25	

* Continued *



Registered Office: Ashworth Road, Bridgemoor
Swindon SN5 7UR
Registered in England No. 414098
VAT Registration No. 576 1316 37

TAG 212186 (01/02)