

Maintenance Record (Please tick the appropriate box)

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced
 Date 29.8.07
 Job No. 37046
 Mileage 17578
 Performed at customer's cost.

PORSCHE
 Porsche Centre West London
 Great West Road, Chiswick
 London W4 4LZ
 020 8742 7000
 Stamp

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced
 Date 27.08.2009
 Job No. 10556
 Mileage 24,006
 Performed at customer's cost.

PORSCHE
 Porsche Centre West London
 Great West Road, Chiswick
 London W4 4LZ
 020 8742 7000
 Stamp


Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced
 Date 10.9.13
 Job No. 14890
 Mileage 31533
 Performed at customer's cost.

PORSCHE
 Operations Centre PRG
 Bath Road, Calcot, Reading
 Berkshire RG31 7SG
 0118 930 3911
 Stamp


Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced
 Date 05/03/2015
 Job No. 26453
 Mileage 42563
 Performed at customer's cost.

PORSCHE
 Porsche Centre West London
 Great West Road, Chiswick
 London W4 4LZ
 020 8742 7000
 Stamp

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced
 Date 04/03/16
 Job No. _____
 Mileage 48751
 Performed at customer's cost.

C. N. MOTORS
 By The Way Farm, London Road
 Ashford, Middx, TW14 8RW
 Tel: 01784 246221 Fax: 01784 244943
 VAT Reg. No: 853 6835 04

 Stamp
 + MOT

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced
 Date 16-12-16
 Job No. 26470
 Mileage 52243
 Performed at customer's cost.


PARAGON
 Tel: 01825 830424
 www.paragon-gb.com
 Five Ashes East Sussex

Maintenance Record (Please tick the appropriate box)

oil + filter

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced

Date 13-12-17
 Job No. 27744
 Mileage 58947
 Performed at customer's cost.

PARAGON
 01825 830424
 Five Ashes
 East Sussex TN20 6HY
 www.paragongb.com
 Stamp

Water Pump.

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced

Date 4-6-18
 Job No. 28241
 Mileage 61993
 Performed at customer's cost.

PARAGON
 01825 830424
 Five Ashes
 East Sussex TN20 6HY
 www.paragongb.com
 Stamp

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced

Date 7-12-18
 Job No. 28816
 Mileage 64526
 Performed at customer's cost.

PARAGON
 01825 830424
 Five Ashes
 East Sussex TN20 6HY
 www.paragongb.com
 Stamp

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced

Date 06/12/2019
 Job No. 29757
 Mileage 70052
 Performed at customer's cost.

PARAGON
 01825 830424
 Five Ashes
 East Sussex TN20 6HY
 www.paragongb.com
 Stamp

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced

Date 20-12-2017
 Job No. 73695
 Mileage 73275
 Performed at customer's cost.

PORSCHE CENTRE CHESTER
 CHESHIRE OAKS
 CHESHIRE
 CH65 9LF
 0145 945 4911
 0151 357 1616
 Stamp

Minor maintenance
 Major maintenance
 Spark plug replacement
 Drive belt checked/replaced

Date 16/06/2013
 Job No. 1867
 Mileage 7545
 Performed at customer's cost.



Record of Brake Fluid Change

The brake fluid must be changed every 2 years.

Brake fluid change

PORSCHE

Porsche Centre West London
Great West Road, Chiswick
London W4 4LZ
020 8742 7000

Date 29.8.07

Job No. 37046

Mileage 17548
Performed at customer's cost.

Stamp

Brake fluid change

PORSCHE

Porsche Centre West London
Great West Road, Chiswick
London W4 4LZ
020 8742 7000

Date 27-08-2009

Job No. 10556

Mileage 24,006
Performed at customer's cost.

Stamp

Brake fluid change

PORSCHE

Group Operations Centre PRG
Bath Road, Calcot, Reading
Berkshire RG31 7SG
0118 930 3911

Date 10.9.13

Job No. 14890

Mileage 3533
Performed at customer's cost.

Stamp

Brake fluid change

PORSCHE

Porsche Centre West London
Great West Road, Chiswick
London W4 4LZ
020 8742 7000

Date 05/03/2015

Job No. 26453

Mileage 42563
Performed at customer's cost.

Stamp

Brake fluid change


PARAGON

Tel: 01825 830424
www.paragon-gb.com
Five Ashes - East Sussex

Stamp

Date 16-12-16

Job No. 26470

Mileage 52243
Performed at customer's cost.

Brake fluid change

PARAGON

01825 830424
Five Ashes
East Sussex TN20 6HY
www.paragon-gb.com

Stamp

Date 7-12-18

Job No. 28816

Mileage 64526
Performed at customer's cost.

Record of Brake Fluid Change

The brake fluid must be changed every 2 years.

Brake fluid change

Date 06/12/2019
Job No. 29757
Mileage 76,052
Performed at customer's cost.

PARAGON
01825 830424
Five Ashes
East Sussex TN20 6HY
www.paragongb.com
Stamp

Brake fluid change

Date _____
Job No. _____
Mileage _____
Performed at customer's cost. Stamp

Brake fluid change

Date 20.12.2019
Job No. 57693
Mileage 73275
Performed at customer's cost.



PORSCHE CENTRE CHESTER
CHESHIRE OAKS
CHESHIRE
CH63 9LF
0161 845 4911
0161 397 1876
Stamp

Brake fluid change

Date _____
Job No. _____
Mileage _____
Performed at customer's cost. Stamp

Brake fluid change

Date 16/06/23
Job No. 1867
Mileage 75455
Performed at customer's cost.



AMS
PORSCHE

Brake fluid change

Date _____
Job No. _____
Mileage _____
Performed at customer's cost. Stamp

Independent Porsche Specialists
 Unit 2-3 Claggy Road, Kimpton, Hertfordshire, SG4 8QB
 Tel: +44 (0)1438 833909 Email: info@amsporsche.com
 Registered Company Number: 12301290
 VAT Number: 383 487 065

Invoice 1867
 Invoice Date: 16/06/2023
 Account No: KRO001
 Order Ref:
 Payment Date:
 Payment Method:

Registration	Make	Model	Chassis Number	Mileage
LK55 CVP	Porsche	911 Carrera 4 S	WP0ZZZ99Z6S732144	75455

Perform Minor Service - Fixed Menu Pricing
 Renew coolant crossover pipes and bleed system.

Labour	Qty	Unit	D	Sub Total
Minor Service (Fixed Menu Pricing)	1	215 00		215 00
Renew Coolant Crossover Pipes	3.75	85 00		318 75
Renew Rigid Caliper Brake Lines / Flexis - Bleed System	3	85 00		255 00
Renew Brake Discs and Pads (All Round)	3	85 00		255 00
Renew Air Conditioning Condensers and Regas	2.5	85 00		212 50
Renew Coolant Pump	2	85 00		170 00
Four Wheel Alignment	2	85 00		170 00
Renew Front Shock Absorbers	3	85 00		255 00

Parts	Part No.	Qty	Unit	D	Sub Total
Engine Oil Mobil 1 Super 3000 5W/40	MOBIL 1 SUPER	1	0 00		0 00
Oil Filter	996 107 020 55	1	0 00		0 00
Crush Washer	900 123 106 30	1	0 00		0 00
Pollen Filter	997 571 219 01	1	0 00		0 00
Screenwash	SCREENWASH	1	0 00		0 00
Key Battery	CR2032	1	0 00		0 00
Coolant Pipe	997 106 711 03	1	49 35		49 35
Coolant Pipe	997 106 720 03	1	51 24		51 24
Coolant Hose	997 106 627 03	1	32 06		32 06
Coolant Hose	997 106 623 03	1	25 20		25 20
Coolant Hose	997 106 624 03	1	25 20		25 20
Coolant Hose	997 106 728 03	1	31 96		31 96
Coolant Distributor	997 106 752 04	1	99 78		99 78
Coolant Distributor	997 106 751 04	1	99 78		99 78
Coolant Sleeve	997 106 551 03	2	20 53		41 06
Coolant	COOLANT	1	25 00		25 00
Caliper Brake Line	997 355 587 02	1	21 77		21 77
Caliper Brake Line	997 355 588 02	1	21 77		21 77
Caliper Brake Line	996 355 585 01	1	15 11		15 11
Caliper Brake Line	996 355 586 01	1	15 11		15 11
Goodrich Braided Hoses (Set)	GOODRICH	1	69 50		69 50
Brake Fluid	BRAKE FLUID	1	25 00		25 00
Shock Absorber Porsche OEM	997 343 047 26	2	657 03		1314 06
Top Mount C4S	997 343 015 02	2	67 50		135 00

Bank Details: AMS Porsche Ltd Lloyds Bank Sort Code: 30-98-97 Account: 82341268
 Warranty Terms 1 Year / 10000 Miles (Conditions Dependent) Unless Otherwise Stated Warranty
 Is Non Transferrable



Independent Porsche Specialists
 Unit 2-3 Claggy Road, Kimpton, Hertfordshire, SG4 8QB
 Tel: +44 (0)1438 833909 Email: info@amsporsche.com
 Registered Company Number: 12301290
 VAT Number: 383 487 065

Invoice 1867
 Invoice Date: 16/06/2023
 Account No: KRO001
 Order Ref:
 Payment Date:
 Payment Method:

Bump Stop	996 343 301 02	2	18 20	36 40
Dust Shield	996 343 509 01	2	21 19	42 38
Road Spring (Pair)	997 343 533 39	1	268 57	268 57
Air Con Condenser	997 573 911 02	2	115 90	231 80
Air Con Seal	999 707 434 41	4	5 43	21 72
Air Con Gas	AIR CON GAS	1	50 00	50 00
Chain Tensioner Seal	900 123 147 30	2	1 06	2 12
Oil Tandem Pump	997 107 022 05	1	297 02	297 02
Coolant Pump	997 106 011 06	1	130 95	130 95
Coolant Pipe	996 106 233 56	1	15 73	15 73
Brake Disc O/S/F OEM SEBRO	996 351 409 04	1	96 03	96 03
Brake Disc N/S/F OEM SEBRO	996 351 410 04	1	96 03	96 03
Brake Disc O/S/R OEM SEBRO	996 352 406 02	1	108 82	108 82
Brake Disc N/S/R OEM SEBRO	996 352 405 02	1	108 82	108 82
Brake Pad Front OEM TEXTAR	996 351 949 13	1	55 90	55 90
Brake Pad Rear OEM TEXTAR	997 351 939 07	1	88 98	88 98
Wear Sensor	997 612 680 01	2	11 50	23 00
Wear Sensor	997 612 676 02	2	11 50	23 00
Cleaning Consumables / Sundries	CONSUMABLES	1	25 00	25 00

Advisories

Rear tyres worn close to legal limit
 Minor IMS / RMS oil leak

Labour	1,851 25
Parts	3,820 22
SubTotal	5,671 47
VAT (20%)	1,134 28
Total	6,805 75
Balance	6,805 75

D&G Porsche Specialist

NE6 4LT

Thank You

M: *****49708

TID: *****6289

TABLE: 58287536

HANDSET: 1

S954



WWW.DG-PORSCHE.CO.UK

01

Job No: MWJ102158

Booking Date: 20 Mar 2023

Mileage: 75351

Vehicle Information

J77RVM

Make/Model: PORSCHE 911

Body Type: COUPE

Engine Size: 3.8L (3824cc)

Fuel Type: PETROL

Manufacture: 2005

PAN SEQ NO. 00

PIN VERIFIED

Thank you

20/03/23 11:55

AUTH CODE: 35

TXN 0014

Lcom

CUSTOMER COPY
PLEASE RETAIN RECEIPT

Quantity	Unit Price	Total (ex. VAT)
----------	------------	-----------------

Carry bore scope inspection. All bores in good condition. Light polishing marks on some cylinders but nothing of concern.

1.66

£75.30

£125.00

Labour Total Ex Vat: £125.00

Sub Total: £125.00

VAT: £25.00

Total (inc. VAT): £150.00

BACS Details - Account Reference: D&G Motor Engineers LTD Account Number: 40664584 Sort Code: 09-01-28

D&G Porsche Specialists, Unit 2, Ambrose Place, Riverside court, Newcastle Upon Tyne, Tyne & Wear, NE6 4LT

Tel: 0191 3406454 | Email: enquiries@dg-porsche.co.uk | Website: WWW.DG-PORSCHE.CO.UK

VAT No: 172810222 | Company No: 06412851

PORSCHE CENTRE CHESTER

LONGLOOMS ROAD
ELLESMERE PORT

MID: **65677
TID: ****1331
AID: A0000000031010
Visa

VISA DEBIT

**** * 7185
ICC PAN SEQ 3
SALE

CARDHOLDER COPY

PLEASE KEEP THIS RECEIPT
FOR YOUR RECORDS

AMOUNT £660.12

Verified by PIN

THANK YOU
10:25 21/12/21



Porsche Centre Chester
Cheshire Oaks, Chester CH65 9LF
Tel: 0151 373 4899 Fax: 0151 357 1616
Email: info@porschechester.co.uk
Web: www.porschechester.co.uk

Registered Office: Rybrook Motors Limited
4 Athene Court, Athene Drive, Liscard Park, Warwick CV34 6PT
Registered in England No. 4550225 UK Registered No. MB7 1269 60

CASH SALE INVOICE

Email: mmjarvis@hotmail.com

Bobbett
bbett Inv. Created By: Louis Smith

Member	Date & Tax Point	Order Number	Warranty Claim No.	Route	
	21/12/2021	1061162			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
911 Carrera 4S	WP0ZZZ99Z6S732144	68606787	73275	10:14	1
Reference No.	Reg No.	Reg Date	VSB No.	W.I.P. No.	Job No.
	J77RVM	02/11/2005		W 57693	74198

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
A 03240000 Carried out Minor maintenance Service				298.30	S
X P99757121901 PARTICLE FILTER	1.00	63.29	1 0.00	63.29	S
X P99610722553 OIL-FILTER ELEMENT	1.00	19.96	1 0.00	19.96	S
X P90012310630 SEALING RING	1.00	1.36	1 0.00	1.36	S
X Z153668 MOBIL1 0w40 PETROL 1	1.00	15.00	1 0.00	15.00	S
X P00004400204 WINDOW CLEANER OUTER	1.00	8.33	1 0.00	8.33	S
X P00004430530 Brake fluid Classic	1.00	26.58	EACH 0.00	26.58	S
P LOIL BULK MOBIL 1 OIL 0w4	8.00	14.66	1 0.00	117.28	S
			Menu Subtotal:	550.10	
A VHC Carried out Free Visual Health Check				0.00	S
			Menu Subtotal:	0.00	
T WASH Complimentary wash and vac carried out				0.00	S
			Menu Subtotal:	0.00	
T PAS We hope that you are completely satisfied with your experience at Porsche Chester and we would be very grateful if to could spare the time to complete the survey that will arrive via email, your feedback is very important to us. Thank you for your time.				0.00	S

V	Rate	Service/Goods	VAT

© AD
E & O E



PORSCHE

Porsche Centre Chester
Cheshire Oaks, Chester CH65 9LF
Tel: 0151 373 4899 Fax: 0151 357 1616
Email: info@porschechester.co.uk
Web: www.porschechester.co.uk

Registered Office: Rybrook Motors Limited
6 Adessa Court, Adessa Drive, Tactbrook Park, Warwick, CV34 6PT
Registered in England No: 4350225 VAT Registered No: BR/126980

CASH SALE INVOICE

Invoice Name & Address:

Customer Name & Address:

You were served by: Kevin Bobbett
Inv. Printed By: Kevin Bobbett

Email: mmjarvis@hotmail.com

Inv. Created By: Louis Smith

Account No.	Document Number	Date & Tax Point	Order Number	Warranty Claim No.	Route
C0002	1061162	21/12/2021			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
911 Carrera 4S	WP0ZZZ99Z6S732144	68606787	73275	10:14	2
Reference No.	Reg No.	Reg Date	VSB No.	W.I.P. No.	Job No.
	J77RVM	02/11/2005		W 57693	74198

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
Menu Subtotal:				0.00	

	V	Rate	Service/Goods	VAT	Net	
Parts		251.80			550.10	
Surcharge	S	20.00	550.10	110.02	V.A.T.	110.02
Labour		298.30			Total	660.12
Sublet		0.00			Paid	0.00
Menus		0.00			Owing	660.12

© AD
E & O E

Condition report functions as a technical test report for assessing a used vehicle. The condition of the vehicle must be documented in this condition report in accordance with the "Long-life guarantee" section (point 3) in the "Guarantee and maintenance booklet".

A Vehicle data


VIN: WP0ZZZ99Z6S732144 Date of first registration: 02/11/2005 Internal vehicle ident. no. (if applicable):
 Model/type: 911 Carrera 4S Mileage: 73275 mls Vehicle reg. no.: J77RVM
 Customer name: Mr Jarvis Date: 21/12/2021 Workshop order no.: 57693

Each test point has a tickbox for documenting the test result.

OK Defective N/A

B Body/paintwork inspection

B Bulge **D** Dent **R** Corrosion **X** Rust penetration **S** Chipping damage **K** Scratches **U** Leaks **C** Crack



- 1 Body/Cabriolet hood
- 2 Gap dimensions
- 3 Condition of paintwork/film/decorative film
- 4 Doors/lids
- 5 Mirror housing
- 6 Front/rear/side trim panels
- 7 Front bumper
- 8 Rear bumper
- 9 Spoiler
- 10 Roof shells
- 11 Sunroof
- 12 Wheel rims
- 13 Windscreen, side windows, rear window
- 14 Check that water drains are not blocked
- 15 Side skirts/inner side members
- 16 Underbody
- 17 Underbody protection
- 18 Underbody panelling

No Are there any signs of prior damage to the vehicle?

Yes Is the vehicle in its original condition?

Notes/info:

Yes Is the vehicle generally well-maintained?

No Tequipment/Exclusive options installed?

C Certification

Your Porsche Centre hereby confirms that the condition report was correctly completed on 21/12/2021

21/12/2021

Date

Service technician and/or Foreman/Workshop manager

Date/location

Date

Customer

Print

PORSCHE

Minor Maintenance Cayman (987), Cayman S (987) Boxster (987), Boxster S (987) 911 Carrera (997), 911 Carrera S (997)

Vehicle identification no. _____

Working instruction
for order no.

--

Minor maintenance

at 30.000, 90.000, 150.000, 210.000 km / 20.000, 60.000, 100.000, 140.000 miles etc.
(working position 03 24 00 ..)

For a description of the various models, see Technical Manual

Note: If the mileage for a regular service is not reached, minor maintenance must be carried out after 2, 6, 10.... years.

The term "checking" includes all necessary subsequent work such as adjusting, readjusting, correcting and topping up, but does not include repairing, replacing and reconditioning parts or assemblies.

Diagnosis system: read out fault memory; reset maintenance interval	✓
Change engine oil and oil filter	✓
Vehicle underside and engine compartment: visual inspection for leaks (oils and fluids) and abrasion (lines and hoses)	✓
Underbody panels: visual inspection for completeness, installation and damage	✓
Coolant hoses: check condition	✓
Radiator and air inlets: visual inspection for external contamination and blockage	✓
Coolant: check the level and antifreeze protection	✓
Particle filter: replace filter element	✓
Brake system: visual inspection of the brake pads and brake discs for wear	✓
Brake hoses and lines: visual inspection for leaks, damage, routing and corrosion	✓
Drive shafts: visual inspection of the boots for leaks and damage	✓
Tyres: check condition and tyre pressure	✓
Check the door locks, lid locks and safety hook of the front lid to ensure that they are secure and functioning properly	✓
Vehicle lighting: check operation	✓
All headlights: check setting	✓
Horn: check operation	✓
Windscreen wiper/washer system, headlight washer: check fluid level and nozzle settings, pay attention to antifreeze agent in winter months, check wiper blades	✓
Electrical equipment, warning and indicator lights: check operation	✓
Replace spark plugs: see Additional maintenance	✓

Continued overleaf

PORSCHE

Minor Maintenance Cayman (987), Cayman S (987) Boxster (987), Boxster S (987) 911 Carrera (997), 911 Carrera S (997)

Vehicle identification no. _____

Working instruction
for order no.

--

Additional maintenance for spark plugs

(working position 03 81 00 ..)

Replace spark plugs every 90.000 km / 60.000 miles or every 4 years

Additional maintenance for drive belt

(working position 03 60 00 ..)

Check drive belt	at 60.000 km / 40.000 miles or after 4 years	<input type="checkbox"/>
Check drive belt	at 150.000 km / 100.000 miles or after 10 years	<input type="checkbox"/>
Check drive belt	at 240.000 km / 160.000 miles or after 16 years	<input checked="" type="checkbox"/>

Additional maintenance – convertible top

(working position 03 70 00 ..)

Maintain and care for convertible top (911 Carrera only) every 30.000 km / 20.000 mls or every 2 years

Additional maintenance every 90.000 km / 60.000 miles or every 6 years

(working position 03 83 00 ..)

Replace drive belt

Additional maintenance every 180.000 km / 120.000 miles or every 12 years

(working position 03 88 00 ..)

Manual transmission: change oil	<input type="checkbox"/>
Automatic transmission: change ATF and ATF filter	<input type="checkbox"/>
Automatic transmission: change oil in final drive	<input type="checkbox"/>
Four-wheel final drive Replace oil	<input type="checkbox"/>

Every 2 years

File Status Report for long-life guarantee	<input type="checkbox"/>
Change brake fluid	<input type="checkbox"/>
Check roll-over protection system (911Cabriolet only)	<input type="checkbox"/>

Every 4 years

Replace tyre sealant

After 4 years, then every 2 years

Check battery for tire pressure monitoring system

After 4, 8, 10 years, then every 2 years

Inspect airbag system	<input checked="" type="checkbox"/>
Ancillary unit mounts and running gear: visual inspection of all rubber mounts for damage	<input checked="" type="checkbox"/>

Signature (fitter): *[Signature]*

Test drive:

Remote control, front seats, foot and parking brakes (also actuation travel), engine, clutch, steering, transmission, ParkAssist, automatic speed control, PSM switch, PASM switch, Sport switch, heating, air-conditioning system and instruments: check operation	<input checked="" type="checkbox"/>
Oils, fluids: visual inspection for leaks	<input checked="" type="checkbox"/>

Signature (final check): _____



Dave Griffiths Racing Ltd

Unit 4 Lower Edgebold Farm, Shrewsbury, Shropshire SY5 8NY

Vehicle: Porsche 997 C4S
Registration: J77 RVM

Invoice No IN1150

Mileage: 70831
Invoice Date: 05-06-2020

Work Done

1. Customer complained of battery warning light on dashboard
2. Vehicle relayed to DGR
3. Started engine and checked charging rate at the battery, showing 11.2v
4. Carried out alternator test, found no output from the alternator
5. Replaced alternator with Bosch unit
6. Starting engine and checked charging rate, now charging at 14.2v
7. Carried out road test, all working correctly

Qty	Item	Price		VAT	Total
1.00	Bosch Alternator 150Amp	441.45	0.00	88.29 (20.00%)	441.45
1.50	Labour	70.00	0.00	21.00 (20.00%)	105.00

Net Total 546.45
Discount 0.00
Total VAT 109.29
Grand Total (GBP) 655.74

Tel: 01743 860908 Email: enquires@davegriffithsracing.com

www.davegriffithsracing.com

Bank transfer payments to: Acc no. 06265452 Sort. 12 24 82
VAT No. 883 4015 23 Company Registration No. 4700 239

PARAGON

The Natural Choice for Porsche

01825 830424 - service@paragongb.com - www.paragongb.com

Paragon, Five Ashes, East Sussex, TN20 GHY

INVOICE TO

SERVICED VEHICLE

Make **Porsche**
Model **Porsche 911 Carrera 4 S Coupe
3824 Manual Petrol**
Registration **LK55CVP**
Chassis No **WP0ZZZ99Z6S732144**
Engine No **66606787**
Mileage **66660**
Registered **02/11/2005**

SERVICE INVOICE

Service No **29185**
Invoice No **21828**
Date **07/05/2019**
Payment
Order No

Your Ref **BARNETTR**

Next Service Due By or Mis Service Advisor **Pete Twyman**

Brief Service Description

TYRES

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
235/35/19 MICHELIN N2	PORSCHE RATED FRONT TYRE	2	194.67	389.34	20.00%
305/30/19 MICHELIN N2	PORSCHE RATED REAR TYRE	2	269.67	539.34	20.00%
TYRE DISPOSAL	OLD TYRE DISPOSAL	4	2.00	8.00	20.00%
997 803 521.00.A03	COVER	1	59.65	59.65	20.00%
				PARTS TOTAL	996.33

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect, a customers statutory rights. All goods shall remain the property of the seller until paid for in full.

Registered in England No. 4278087

VAT No. 621 6163 68

Sub Total **996.33**
MOT: Standard **0.00**
Retest **0.00**
+ VAT Due **199.27**

Invoice Total **1,195.60**

Total Payments **0.00**

Total Due **1,195.60**

VAT Analysis
VAT @ 20% on 996.33 = 199.27

Date _____ Signature _____

VAT No. 621 6163 68

PARAGON

The Natural Choice for Porsche

01825 830424 · service@paragongb.com · www.paragongb.com

Paragon, Five Ashes, East Sussex, TN20 6HY

INVOICE TO

SERVICED VEHICLE

Make **Porsche**
Model **Porsche 911 Carrera 4 S Coupe
3824 Manual Petrol**
Registration **LK55CVP**
Chassis No **WP0ZZZ99Z6S732144**
Engine No **68606787**
Mileage **64526**
Registered **02/11/2005**

SERVICE INVOICE

Service No **28816**
Invoice No **21467**
Date **07/12/2018**
Payment
Order No

Your Ref **BARNETTR**

Next Service Due By or M/s Service Advisor **Pete Twyman**

Brief Service Description

40K BF MOT

LABOUR WORK CARRIED OUT

	Total	VAT Rate
997 (Gen 2) 40K SERVICE inc SPARK PLUGS	495.00	20.00%
BRAKE FLUID CHANGE	71.50	20.00%
M.O.T TEST	0.00	20.00%
REPLACE HEADLIGHT LEVELLING LINK RODS	55.00	20.00%
CLEAR BULK HEAD DRAINS & RADIATOR AIR INTAKES	55.00	20.00%
LABOUR TOTAL	676.50	

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
997 100 956 00	SERVICE KIT 997	1	96.11	96.11	20.00%
999 703 267 40	GROMMET	1	0.89	0.89	20.00%
996 104 445 02	COVER PLATE	1	14.74	14.74	20.00%
900 385 009 01	TORX SCREW	1	0.30	0.30	20.00%
997 602 104 02	IGNITION COIL (LATE STYLE MODIFIED)	4	46.30	185.20	20.00%
997 341 375 01	STRUT SENSOR	1	15.88	15.88	20.00%
997 331 375 03	STRUT	1	22.67	22.67	20.00%
997 361 203 02	WHEEL NUT	2	5.73	11.46	20.00%
PARTS TOTAL				347.25	

OILS / LUBRICANTS

Description	Qty	Total	VAT Rate
MOBIL 1 ENGINE OIL 0w40	10	99.90	20.00%
BRAKE FLUID DOT 4	1	6.50	20.00%
OILS / LUBRICANTS TOTAL		106.40	

Continued from previous page

Service No 28816

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect a customer's statutory rights. All goods shall remain the property of the seller until paid for in full.

Registered in England No 4278087

VAT No 621 6163 68

Sub Total	1,130.15
MOT Standard	54.85
Retest	0.00
+ VAT Due	226.03

Invoice Total	1,411.03
---------------	----------

Total Payments	0.00
----------------	------

Total Due	1,411.03
-----------	----------

VAT Analysis

VAT @ 0% on 54.85 = 0.00

VAT @ 20% on 1,130.15 = 226.03

Date

Signature

VAT No 621 6163 68

PARAGON

The Natural Choice for Porsche

01825 830424 · service@paragongb.com · www.paragongb.com
Paragon, Five Ashes, East Sussex, TN20 6HY

SERVICED VEHICLE

Make **Porsche**
Model **Porsche 911 Carrera 4 S Coupe
3824 Manual Petrol**
Registration **LK55CVP**
Chassis No **WP0ZZ99Z6S732144**
Engine No **68606787**
Mileage **61993**
Registered **02/11/2005**

SERVICE INVOICE

Service No **28241**
Invoice No **20887**
Date **04/06/2018**
Payment
Order No

Next Service Due By **13/12/2018** or Mis Service Advisor **Barrett Sutherland**

Brief Service Description

RECOVERY

LABOUR WORK CARRIED OUT

	Total	VAT Rate
REPLACE WATER PUMP FILL & BLEED COOLING SYSTEM	302 50	20 00%
LABOUR TOTAL	302 50	

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
997 106.011.06	WATER PUMP	1	273 64	273 64	20 00%
996 106.340.54	GASKET	1	7 44	7 44	20 00%
996 106.326.50	GASKET	1	4 50	4 50	20 00%
996 102.151.66	POLY BELT 986/996 987/C/997 GEN1	1	35 38	35 38	20 00%
	PARTS TOTAL			320 96	

OILS / LUBRICANTS

Description	Qty	Total	VAT Rate
ANTIFREEZE MOBIL ULTRA	6	57 36	20 00%
	OILS / LUBRICANTS TOTAL	57 36	

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect, a customers statutory rights. All goods shall remain the property of the seller until paid for in full.

Registered in England No. 4278087

VAT No. 621 6163 68

Sub Total **680 82**
MOT: Standard **0 00**
Retest **0 00**
+ VAT Due **136 17**

Invoice Total 816 99

Total Payments **0 00**

Total Due 816 99

VAT Analysis
VAT @ 20% on 680 82 = 136 17

Date _____ Signature _____

VAT No 621 6163 68

PARAGON

The Natural Choice for Porsche

01825 830424 · service@paragongb.com · www.paragongb.com

Paragon, Five Ashes, East Sussex, TN20 6HY

SERVICED VEHICLE

Make **Porsche**
Model **Porsche 911 Carrera 4 S Coupe
3824 Manual Petrol**
Registration **LK55CVP**
Chassis No **WP0ZZZ99Z6S732144**
Engine No **68606787**
Mileage **58947**
Registered **02/11/2005**

SERVICE INVOICE

Service No **27744**
Invoice No **20422**
Date **13/12/2017**
Payment
Order No
Telephone
Email **robinpods@hotmail.com**

Next Service Due By **13/12/2018** or Mls Service Advisor **Barrett Sutherland**

Brief Service Description

OIL MOT

LABOUR WORK CARRIED OUT

	Total	VAT Rate
OIL & FILTER CHANGE & GENERAL CHECKOVER	137.50	20.00%
M.O.T TEST	0.00	0.00%
LABOUR TOTAL	137.50	

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
996.107.020.55	OIL FILTER 996/997	1	21.36	21.36	20.00%
LLB566	BULB STOP/TAIL OFFSET	1	2.79	2.79	20.00%
PARTS TOTAL				24.15	

OILS / LUBRICANTS

Description	Qty	Price	Total	VAT Rate
MOBIL 1 ENGINE OIL 0w40	10	9.99	99.90	20.00%
OILS / LUBRICANTS TOTAL			99.90	

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect a customer's statutory rights. All goods shall remain the property of the seller until paid for in full.

Registered in England No. 4278087

VAT No. 621 6163 68

Sub Total **261.55**
MOT: Standard **54.85**
Retest **0.00**
+ VAT Due **52.31**

Invoice Total 368.71

Total Payments **0.00**

Total Due 368.71

VAT Analysis
VAT @ 0% on 54.85 = 0.00
VAT @ 20% on 261.55 = 52.31

Date Signature

VAT No. 621 6163 68

PARAGON

The Natural Choice for Porsche

01825 830424 · service@paragongb.com · www.paragongb.com
Paragon, Five Ashes, East Sussex, TN20 6HY

SERVICED VEHICLE

Make/Model: **Porsche**
Porsche 911 Carrera 4 S Coupe 3824
Manual Petrol

Registration: **LK55CVP**

Chassis No: **WP0ZZZ99Z6S732144**

Engine No: **68606787**

Mileage: **58007**

Registered: **02/11/2005**

SERVICE INVOICE

Service No: **27512**

Invoice No: **20205**

Date: **03/10/2017**

Payment:

Order No:

Next Service Due By: **23/11/2017** or Mile: Service Advisor: **Pete Twyman**

Brief Service Description

CV BOOTS

LABOUR WORK CARRIED OUT

	Total	VAT Rate
REPLACE O/S/F DRIVE SHAFT GAITERS	220 00	20 00%
LABOUR TOTAL		220 00

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
996 349 291 00	DUST BELLOWS	1	30 00	30 00	20 00%
996 349 293 00	DUST BELLOWS	1	30 00	30 00	20 00%
				PARTS TOTAL	60 00

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect a customer's statutory rights. All goods shall remain the property of the seller until paid for in full.

Registered in England No: 4278087

VAT No: 621 6163 68

Sub Total **280 00**
MOT Standard **0 00**
Retest **0 00**
+ VAT Due **56 00**

Invoice Total 336 00

Total Payments **0 00**

Total Due 336 00

VAT Analysis
VAT @ 20% on 280 00 = 56 00

Date

Signature

VAT No: 621 6163 68

PARAGON

The Natural Choice for Porsche

SERVICED VEHICLE

Make/Model **Porsche**
Porsche 911 Carrera 4 S Coupe 3824
Manual Petrol

Registration **LK55CVP**
Chassis No **WP0ZZZ99Z6S732144**
Engine No **68606787**
Mileage
Registered **02/11/2005**

SERVICE INVOICE

Service No **27102**
Invoice No **19805**
Date **05/06/2017**
Payment
Order No

Next Service Due By **23/11/2017** or Mis Service Advisor **Pete Twyman**

Brief Service Description

SILL SWITCHES

LABOUR WORK CARRIED OUT

	Total	VAT Rate
REPLACE SILL SWITCHES CHECK OIL & TYRE LEVELS	55.00	20.00%
LABOUR TOTAL	55.00	

PARTS

Part Number	Description	Qty	Price	Total	VAT Rate
997 613 105 02 A05	SWITCH	1	62.22	62.22	20.00%
PARTS TOTAL				62.22	

I agree to pay for all work and parts required for the above repairs at your retail charge. All repairs are undertaken on a cash basis unless prior arrangements for credit have been approved. I have read and accept your terms and conditions. Nothing herein is designed to nor will it affect a customer's statutory rights. All goods shall remain the property of the seller until paid for in full.

Sub Total 117.22
MOT Standard 0.00
Retest 0.00
+ VAT Due 23.44

Invoice Total 140.66

Total Payments 0.00

Total Due 140.66

VAT Analysis
VAT @ 20% on 117.22 = 23.44

Date

Signature

VAT No. 621 6163 68