



PORSCHE

Porsche Centre West London Great West Road London W4 4LZ

Porsche Centre West
London

Great West Road
Chiswick
London
W4 4LZ

Telephone: 0208 7427000

Reg No	Registration Date	VIN	Mileage	Contact Person	Quote No.	Quote Date
FL61WXE		WP0ZZZ98ZCU790237 0		Caltian Partington	768965	01/06/2023

Job Details	Variant	Quantity	Total
Major Service - Every 120K Miles / 180K Kms or every 12 Years	Maintenance M.Y 2012 (Main Work) 1 x SEALING RING 1 x PARTICLE FILTER 1 x TOPUP/BAG 1 x WINDOW CLEANER OUTER 7.5 x ENGINE OIL 1 x Oil filter insert 1 x seal ring	1	£921.96
Op Codes: 03160006			
Add. Maintenance - Every 60K Miles / 90K Kms or every 6 Years	Replace Drive Belt / Air Filter Cartridge (Composite Work) Includes Rear Wall Flap Remove And Install 1 x RIBBED V-BELT 1 x AIR CLEANER CARTRIDGE	1	£313.95
Op Codes: 03830056			
Add. Maintenance - Every 120K Miles / 180K Kms or every 12 Years	Drain And Refill Transmission Oil Manual Transmission G87.40 (Composite Work) Support Plate Remove And Reinstall 3.2 x TRANSMISSION OIL MANUAL TRANSMISSION 5TH	1	£296.94
Op Codes: 03880050			
Add. Maintenance - After 4, 8, 10th Year, Then Every 2 Years	Check Air Bag, Engine Mounts, Suspension and Running Gear Visual Insp. Of All Rubber Mounts For Signs Of Damage (Composite Work)	1	£86.40
Op Codes: 03540050			
Brake Fluid Change - 03510060		1	£185.00
Op Codes:			
Environmental charge		1	£6.00
Op Codes:			
Total (Inc. VAT)			£1,810.25



PORSCHE

Nett Price (Ex. VAT)	£1,508.55
VAT	£301.70
Total	£1,810.25

~~EPORSCH~~
EPORSCH LIMITED

UNIT 1 BROOKSIDE HOUSE

takepayments

M**25090 TID****8016

AID : A0000000031010

VISADEBIT

VISA DEBIT

**** * 8026

ICC PAN.SEQ 00



ing and Sales

SALE

CARDHOLDER COPY

PLEASE KEEP THIS RECEIPT lose
FOR YOUR RECORDS

~~AMOUNT~~ ~~RG42 3XW~~ ~~6112 00~~

*** Invoice ***

Invoice No: 031694
Invoice Date: 16/04/2021
Order No:
Customer:

Labour

Fit supplied front & rear brake discs & pads.
Fit supplied spark plugs.
Investigate coolant leak around engine area & report
Carry out rev range report with PIWIS 3

<u>Quantity</u>	<u>Rate</u>	<u>Disc</u>	<u>Net</u>
			224.00
			80.00
			26.40

Sub Total 330.40

Parts

98761267602 Wear sensor rear - re-used
99761275600 Wear Sensor L
99761275900 Wear Sensor R

0.00	18.86		
1.00	29.96	34%	19.77
1.00	29.96	34%	19.77

Sub Total 39.54

Vehicle: FGZ100
Make: PORSCHE CAYMAN R
VIN: WP0ZZZ98ZCU790237
Mileage: 19652

THANK YOU FOR YOUR CUSTOM.

Invoice Totals

<u>Description</u>	<u>Amount</u>
Vatable Items	369.94
VAT @ 20.00%	73.98
Zero Rated Items	0.00
Discount Applied	24.46
Total Invoice Value	443.92

This cash invoice is due for payment

Title to the goods supplied remain with this company until payment
for them has been satisfactorily received - E & O E



PORSCHE

Porsche Centre Portsmouth
Lakeside Business Park, Western Road
Portsmouth PO6 3PQ
Telephone 023 9221 2350
Fax: 023 9221 2351
Email: info@porscheportsmouth.co.uk
Web: www.porsche.co.uk/portsmouth
VAT Registration No. GB 243 6111 93

CASH SALE INVOICE

Name & Address:

You were served by: Ben Labercombe

Doc. Printed By: Ben Labercombe

Doc. Created By: Joshua Triggs

Account No.	Document No.	Date	Order No.	Warranty Claim No.	Route
c8400040	84431397	26/03/2021			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
			0	12:32	1
Reference	Reg No.	Reg Date	VSB No.	W.I.P. No.	Job No.
				P 25974	0

FOR ALL PARTS ENQUIRIES PLEASE CALL 02392 212355.
SPECIALLY ORDERED PARTS CANNOT BE RETURNED FOR CREDIT

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
P P99635140501 ✓ 07BF01 846621/BRAKE	1.00	143.90	EACH 6	122.32	
P P99635140601 ✓ 07BF01 846621/BRAKE	1.00	143.90	EACH 6	122.32	
P P99735193906 ✓ N/STK 846621/SET, BRA	1.00	150.60	EACH 9	128.01	
P P98735240301 ✓ N/STK 846621/BRAKE D	2.00	135.26	EACH 6	229.95	
P P98735293901 ✓ 01DG03 846621/SET, BR	1.00	105.00	EACH 9	89.25	
P P99635208602 02CE08 846621/DAMPIN ✓	4.00	11.24	EACH 7	38.22	
P NOTIF y Deposit	-1.00	730.07	EACH A	-730.07	

	V	Rate	Service/Goods	VAT	Net	
Parts		0.00			0.00	
Surcharge		0.00				
Labour		0.00				
Sublet		0.00				
Menus		0.00				
					Net	0.00
					V.A.T.	0.00
					Total	0.00

PORSCHE

Porsche Centre Portsmouth
 Lakeside Business Park Western Road
 Portsmouth PO6 3PQ
 Telephone 023 9221 2350
 Fax 023 9221 2351
 Email info@porscheportsmouth.co.uk
 Web www.porsche.co.uk/portsmouth
 VAT Registration No. GB 243 6111 93

Lakeside Business Park
 Western Road
 Portsmouth
 PO6 3PQ

Mastercard
 *****1066

SALE
 KEYED CNP
 Please debit my account
 Amount: £962.27
TOTAL: £962.27

CASH SALE INVOICE

CONFIRMED

Please keep receipt for your records
 PLID: 33661497

You were served by: **Labercombe**
 Doc. Printed By: **Ben Labercombe**

Doc. Created By: **Joshua Triggs**

Account No.	Document No.	Date	Order No.	Warranty Claim No.	Route
c8400040	84431372	25/03/2021			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
			0	09:22	1
Reference	Reg No.	Reg Date	VSB No.	W.I.P. No.	Job No.
				P 25974	0

FOR ALL PARTS ENQUIRIES PLEASE CALL 02392 212355.
 SPECIALLY ORDERED PARTS CANNOT BE RETURNED FOR CREDIT

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
P P99635108802	4.00	9.88	EACH 7	33.60	
P P99635208600	4.00	11.24	EACH 7	38.22	
P NOTIF	1.00	730.07	EACH A	730.07	
02DJ02 DAMPING PANEL ✓					
02BH08 DAMPING PANEL ✓					
y Deposit					

Parts	801.89	V	Rate	Service/Goods	VAT	Net	801.89
Surcharge	0.00	S	20.00	801.89	160.38	V.A.T.	160.38
Labour	0.00					Total	962.27
Sublet	0.00						
Menus	0.00						

EPORSCH LIMITED

UNIT 1 BROOKSIDE HOUSE
PAYZONE - TAKING CARE OF
M**25090 TID***8016
AID : A0000000031010
VISADEBIT

g and Sales

VISA DEBIT

**** * 0178
ICC PAN.SEQ 00

SALE

CARDHOLDER COPY

PLEASE KEEP THIS RECEIPT
FOR YOUR RECORDS

AMOUNT £171.05

Verified by PIN

THANK YOU
17:28 28/08/19 40IF1:00 hose O/S/F.

AUTH CODE: 485961

***** Invoice *****

Invoice No: 030914
Invoice Date: 28/08/2019
Order No:
Customer: MUM001

<u>Quantity</u>	<u>Rate</u>	<u>Net</u>
		87.00
		29.00

Sub Total 116.00

1.00 26.54 26.54

Sub Total 26.54

Parts

99710662703 water hose supply right

Vehicle: FL61WXE
Make: PORSCHE CAYMAN R
VIN: WP0ZZZ98ZCU790237
Mileage: 19443

THANK YOU FOR YOUR CUSTOM.

Invoice Totals	
<u>Description</u>	<u>Amount</u>
Vatable Items	142.54
VAT @ 20.00%	28.51
Zero Rated Items	0.00
Total Invoice Value	171.05

This cash invoice is due for payment

Title to the goods supplied remain with this company until payment
for them has been satisfactorily received - E & O E

**** CARDHOLDER COPY ****

Porsche Portsmouth

Lakeside
Business Park
Western Road
Portsmouth
PO6 3PQ

Visa Debit
*****178
SALE
KLYLD CNP

Please debit my
account
Amount: £5.36
TOTAL: £5.36

CONFIRMED

Please keep receipt
for your records
PTID: 33537491
MID: **65879
TID: ****4226
Date: 24/04/2019
Time: 11:36:28
Authcode: 728532
Ref: 62152

Thank you
for your custom



PORSCHE

Porsche Centre Portsmouth

Lakeside Business Park, Western Road
Portsmouth PO6 3PQ
Telephone: 023 9221 2350
Fax: 023 9221 2351
Email: info@porscheportsmouth.co.uk
Web: www.porsche.co.uk/portsmouth
VAT Registration No. GB 243 6111 93

CASH SALE INVOICE

Customer Name & Address:

a Triggs
riggs

Doc. Created By: Joshua Triggs

No.	Date	Order No.	Warranty Claim No.	Route
1	24/04/2019			

Chassis No.	Engine No.	Mileage	Time	Page
		0	11:37	1

Reference	Reg No.	Reg Date	VSB No.	W.I.P. No.	Job No.
				P 62152	0

FOR ALL PARTS ENQUIRIES PLEASE CALL 02392 212355.
SPECIALLY ORDERED PARTS CANNOT BE RETURNED FOR CREDIT

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
P NOTIF y P99653723700	1.00	4.47	EACH A	4.47	

	V	Rate	Service/Goods	VAT	Net	
Parts	S	20.00	4.47	0.89	4.47	
Surcharge						0.89
Labour						
Sublet						
Menus						
Total					5.36	

** CARDHOLDER COPY **

Porsche Portsmouth

Lakeside
Business Park
Western Road
Portsmouth
PO6 3PQ



PORSCHE

Porsche Centre Portsmouth

Lakeside Business Park, Western Road
Portsmouth PO6 3PQ
Telephone: 023 9221 2350
Fax: 023 9221 2351
Email: info@porscheportsmouth.co.uk
Web: www.porsche.co.uk/portsmouth
VAT Registration No. GB 243 6111 93

CASH SALE INVOICE

Visa Debit
*****018
SALE
KEYED CNP
Please debit my
account
Amount: £223.76
TOTAL: £223.76

Customer Name & Address:

CONFIRMED

Please keep receipt
for your records
PIID: 33567132

You were served by: Joshua Triggs
Doc. Printed By: Joshua Triggs

Doc. Created By: Ashley Wilson

Account No.	Document No.	Date	Order No.	Warranty Claim No.	Route
c8400040	84420216	18/04/2019			
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
			0	13:54	1
Reference	Reg No.	Reg Date	VSB No.	W.I.P. No.	Job No.
				P 61707	0

FOR ALL PARTS ENQUIRIES PLEASE CALL 02392 212355.
SPECIALLY ORDERED PARTS CANNOT BE RETURNED FOR CREDIT

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
P P98755525100A03 N/STK 844710/AS LOCK	1.00	55.14	EACH 1	49.63	
P P91109593221B9A FCC 844710/PAINT TOU	1.00	14.40	EACH 5	12.96	
P P98751281901 FCC 844710/PROTECTIV	2.00	10.54	EACH 5	18.98	
P P00004460722 FCC 844710/HUB CAP S	1.00	113.34	EACH 11	102.01	
P P99959171240 02EH08 Expansion riv	6.00	0.33	EACH 8	1.79	
P P99755387100 N/STK 844714/FLEECE	1.00	1.22	EACH 2	1.10	

	V	Rate	Service/Goods	VAT	Net	
Parts	S	186.47	186.47	37.29	186.47	
Surcharge		0.00				
Labour		0.00				
Sublet		0.00				
Menus		0.00				
					Total	223.76

exelwheels ltd

www.exelwheels.co.uk

The Ultimate Wheel & Tyre Service

mob: 07885 259571

SALES INVOICE

Customer Details

Date 11 April 2019

Inv No 112260

Order Ref AM01

Description	Qty	Unit Price	Sub Total	Vat	Total
Porsche 987 Cayman R					
Refurbish 19" alloys <i>Genuine original Porsche Spyder wheels Painted gloss black with primer inside and silver outer lip</i>	4	£129.17	£516.67	£103.33	£620.00
Additional works <i>Welding to rim edge to ensure perfect 50% discount as goodwill</i>	2	£6.25	£12.50	£2.50	£15.00
Supply & fit new set of tyres <i>Michelin PS2 N2 rated 235/35/19 F and 265/35/19 R</i>	1	£600.00	£600.00	£120.00	£720.00

Full loan wheels service inclusive to Bracknell

All Wheel Nuts/Bolts must be checked for tightness within 30 miles.

This is for your safety and others

Thank you for your business

Sub Total £1,129.17

VAT £225.83

Total Due £1,355.00

PAID DEPOSIT £720 FOR TYRES 11/4/19 AND BALANCE £635 4/5/19

Exel Wheels Ltd Reg in England Company No: 7320125 VAT No: 994 9111 78

Reg Office: Hereward Offices, Cherry Holt Rd, Bourne, Lincs PE10 9LA

Hillcrest Specialist Cars

Whitehouse Garage
 High Street
 Nettlebed
 Oxfordshire
 RG9 5DB
 01491 641 060 Porsche Dept: 01491 642 911

Invoice

Invoice No: 103536
 Invoice Date: 25/07/2014
 Order No: 203897
 Customer: LINC01

	<u>Quantity</u>	<u>Rate</u>	<u>Net</u>
Labour			
Check charging system. Replaced battery.			55.00
Parts			
Battery Bosch 110 S4	1.00	105.00	105.00

Vehicle: FL61 WXE
 Make: PORSCHE CAYMAN R
 VIN: WPOZZZ98ZCU790237
 Mileage: 8861
 Technician:

THANK YOU FOR YOUR CUSTOM.

Title to the goods supplied remain with this company until payment for them has been satisfactorily received - E & O E

Invoice Totals	
<u>Description</u>	<u>Amount</u>
Vatable Items	160.00
VAT @ 20.00%	32.00
Zero Rated Items	0.00
Total Invoice Value	192.00

This cash invoice is due for payment



Accounts & Office:
 11 St. Machar Road, Aberdeen, AB24 2UU
 Tel: 01224 497000 Fax: 01224 497018
 e-mail: info@kenwayautotrade.co.uk

Depots:
 60-70 Virginia Street, Aberdeen, AB11 5AY
 Tel: 01224 597080
 e-mail: info@kenwayautotrade.co.uk

Broadfold Road, Bridge of Don, Aberdeen AB23 8EE
 Tel: 01224 821163 Fax: 01224 826230
 e-mail: bod@kenwayautotrade.co.uk

Balunie Drive, Dundee, DD4 8UU
 Tel: 01382 735820 Fax: 01382 735829

KENWAY TYRES

Grouptyre
 National Strength

INVOICE

DOCUMENT TO:

DELIVERY ADDRESS: (IF DIFFERENT)

DD5 3BY

Cash Sales - Depot 4
 Balunie Drive
 Baluniefield
 Dundee DD4 8UU
 TEL 01382 735820

MAKE/MODEL **REG. No.** **Mileage**
 FL61WXE 6998

DATE	ACCOUNT NO.	DOCUMENT NO.	JOB/ADVICE NO.	OPERATOR	ORDER NO.	DELIVERY
20/03/14	CASH04	4CA69644	4JC00404	RYAN MURRIE.		FITTED

PRODUCT CODE	DESCRIPTION	QTY	PRICE	VALUE
26535194APIL2	(94Y) PI "P ZERO" N2	2	222.91	445.82
KWVALCAP	CAR TUBELESS VALVE FITTED(A)	2	1.88	3.76
CASINGCAP	ENVIRONMENTAL DISPOSAL CAR (A)	2	1.14	2.28
KWBALAPST	ALLOY BALANCE STICK/ON WITH TY	2	7.61	15.22
DISCOUNT1	5% PROMOTIONAL DISCOUNT	-2	11.14	-22.28

26535194APIL2 Class: C1, Fuel Code: E, Wet Grip: A, Noise DB: 72, Noise: 2

533.76 paid by CASH

This invoice refers to Advice Note 4JC00404

WHEEL NUTS SHOULD BE RE-CHECKED FOR TIGHTNESS AFTER 50 MILES

RATE	AMOUNT TAXABLE	VAT TOTAL	TOTAL GOODS	TOTAL VAT	TOTAL
20%	444.80	88.96	444.80	88.96	533.76

VAT ANALYSIS VAT Reg. No. 384 6541 26

RETENTION OF TITLE: It is a Condition of Sale that these goods remain the property of Kenway Tyres Ltd until the account has been paid and all cheques cleared.

PORSCHE

Intermediate maintenance (A markets*)

Cayman (987), Cayman S (987)

Boxster (987), Boxster S (987)

911 Carrera (997), 911 Carrera S (997)

as of 2010 model

Vehicle Ident. No. WPOZZ98ZCU3910237

Working instruction for
order no.

16413.

Intermediate maintenance

at 30,000, 90,000, 150,000, 210,000 km etc./20,000, 60,000, 100,000, 140,000 miles etc.

(Labour operation 03 14 00 ..)

For a description of the various models, see Technical Manual

Note: If the mileage for a regular service is not reached, intermediate maintenance must be carried out after 2, 6, 10..... years.

The term 'checking' includes all necessary subsequent work, such as adjusting, readjusting, correcting and topping up, but does not include repairing, replacing and reconditioning parts or assemblies.

Diagnostic system: read out fault memory; reset maintenance interval	✓
Change engine oil and oil filter	✓
Vehicle underbody and engine compartment: visual inspection for leaks (oils and fluids) and chafing damage (lines and hoses)	✓
Underbody panels: visual inspection for completeness, secure installation and damage	✓
Coolant hoses: check condition	✓
Radiators and air inlets: visual inspection for external contamination and blockage	✓
Coolant: check level and antifreeze	✓
Particle filter: replace filter element	✓
Brake system: visual inspection of brake pads and brake discs for wear (without removing and fitting wheels)	✓
Brake hoses and lines: visual inspection for leaks, damage, routing and corrosion	✓
Drive shafts: visual inspection of the boots for leaks and damage	✓
Tyres: check condition and tyre pressure	✓
Check the door locks, lid locks and safety hooks of the front lid to ensure that they are secure and functioning properly	✓
Vehicle lighting: check operation	✓
All headlights: check adjustment	✓
Horn: check operation	✓
Windscreen wiper/washer system, headlight cleaning system: check fluid level and nozzle settings, check window cleaner or antifreeze, depending on time of year; check wiper blades	✓
Electrical equipment, warning and indicator lights: check operation	✓
Battery: check functional state and fluid level	✓
Replace spark plugs: see Additional maintenance	NA

* Applies to vehicles in the following countries:

Andorra	France	Malta	Spain
Austria	Germany	Monaco	Sweden
Belgium	Greece	Netherlands	Switzerland
Bosnia and Herzegovina	Hungary	Norway	
Croatia	Iceland	Poland	
Czech Republic	Ireland	Portugal	
Denmark	Italy	Serbia and Montenegro	
England	Liechtenstein	Slovakia	
Finland	Luxembourg	Slovenia	

Continued overleaf

Copyright by
Dr. Ing. h. c. F. Porsche AG
After Sales Engineering
Printed in Germany - 03/09

PORSCHE

Intermediate maintenance (A markets*)
Cayman (987), Cayman S (987)
Boxster (987), Boxster S (987)
911 Carrera (997), 911 Carrera S (997)
as of 2010 model

Vehicle Ident. No. W0ZZZ98ZCU790257

Working instruction for
order no.

16413.

Additional maintenance for spark plugs

(Labour operation 03 81 00 ..)

Replace spark plugs

every 90,000 km/60,000 miles or every 4 years

Additional maintenance for drive belt

(Labour operation 03 60 00 ..)

Check drive belt

every 60,000 km/40,000 miles or every 4 years

Check drive belt

every 150,000 km/100,000 miles or every 10 years

Check drive belt

every 240,000 km/160,000 miles or every 16 years

Additional maintenance for convertible top

(Labour operation 03 70 00 ..)

Service and maintain convertible top (911 Carrera only)

every 30,000 km/20,000 miles or every 2 years

Additional maintenance every 90,000 km/60,000 miles or every 6 years

(Labour operation 03 83 00 ..)

Air cleaner: replace filter element

Replace drive belt

Electronically controlled all-wheel drive (Carrera 4 only): change oil

PDK transmission: change clutch fluid

Additional maintenance every 180,000 km/120,000 miles or every 12 years

(Labour operation 03 88 00 ..)

Manual transmission: change oil

All-wheel final drive: change oil (911 Carrera/S only)

PDK transmission: change transmission oil

Every 2 years

Prepare condition report for long-life guarantee

Change brake fluid

Every 4 years

Replace tyre sealant

After 4 years, then every 2 years

Check Tyre Pressure Monitoring system battery

After 4, 8, 10 years, then every 2 years

Visual inspection of airbag units

Ancillary unit mounts and suspension: visual inspection of all rubber mountings and boots for damage

Signature (mechanic): [Signature]

Test drive:

Remote control, front seats, footbrake and handbrake (also actuation travel), engine, clutch, steering, transmission, ParkAssist, cruise control, PSM switch, PASM switch, Sport switch, heating, air conditioning and Instruments: check operation

Oils, fluids: visual inspection for leaks

Signature (final check): [Signature]

Copyright by

Dr. Ing. h. c. F. Porsche AG

After Sales Engineering

Printed in Germany - 03/09

Porsche Centre num.

Tel: 01482 911918

Porsche Centre

Retailer ID: 2071

PORSCHE

LONG-LIFE GUARANTEE

Condition report

Centre: Porsche Centre Hull

The condition report functions as a technical test report for assessing a used vehicle. The condition of the vehicle must be documented in this condition report in accordance with the "Long-life guarantee" section (point 3) in the "Guarantee and maintenance booklet".

A Vehicle data


VIN: WPOZZZ98ZCU790237 Date of first registration: 23/09/2011 Internal vehicle ident. no. (if applicable):
Model/type: Cayman R Mileage: 19805 mls Vehicle reg. no.: FL61WXE
Customer name: CIUFFETELLI Date: 16/09/2021 Workshop order no.: 16413

Each test point has a tickbox for documenting the test result.

OK Defective N/A

B Body/paintwork inspection

B Bulge D Dent R Corrosion X Rust penetration S Chipping damage K Scratches U Leaks C Crack



- 1 Body/Cabriolet hood
- 2 Gap dimensions
- 3 Condition of paintwork/film/decorative film
- 4 Doors/lids
- 5 Mirror housing
- 6 Front/rear/side trim panels
- 7 Front bumper
- 8 Rear bumper
- 9 Spoiler
- 10 Roof shells
- 11 Sunroof
- 12 Wheel rims
- 13 Windscreen, side windows, rear window
- 14 Check that water drains are not blocked
- 15 Side skirts/inner side members
- 16 Underbody
- 17 Underbody protection
- 18 Underbody panelling

No Are there any signs of prior damage to the vehicle?

Yes Is the vehicle in its original condition?

Notes/info:

Yes Is the vehicle generally well-maintained?

No Tequipment/Exclusive options installed?

C Certification

Your Porsche Centre hereby confirms that the condition report was correctly completed on 16/09/2021 PORSCHE CENTRE HULL

Date/location

16/09/2021

Date

[Signature]
Service technician and/or Foreman/Workshop manager

Print

Date

Customer



Mobile No: 07834600077
 Telephone No: 07854272255
 Tech Inspection ID: 35284
 Appointment Date: 16/09/2021
 Reg No / VIN: FL61WXE / **WP0ZZZ98ZCU790237**
 Variant: 987781 Cayman R (2012) MA1.21 6 Speed Manual
 Mileage: 19805
 Next Service Date: 16/09/2021

Porsche Centre Hull
 Alder Road
 Bridgehead South Business Park
 Hessle
 HU13 0GW
 Telephone: 01482 911918

Area	Urgen t	Advis.	OK	N/A	Additional Details	Auth?	Comp?
Wheels & Tyres							
Tyre Pressures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
OSF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tread (Inner): 5.5 Tread (Middle): 6.8 Tread (Outer): 6.7 Size: 235/35/19 Manufacturer: MICHELIN Speed: 91Y N-Rating: N2 Reason: OK DOT Code: 0319		
OSR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tread (Inner): 6.0 Tread (Middle): 6.9 Tread (Outer): 6.7 Size: 265/35/19 Manufacturer: MICHELIN Speed: 94Y N-Rating: N2 Reason: OK DOT Code: 4918		
NSR	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tread (Inner): 6.1 Tread (Middle): 6.9 Tread (Outer): 6.9 Size: 265/35/19 Manufacturer: MICHELIN Speed: 94Y N-Rating: N2 Reason: OK DOT Code: 4918		
NSF	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Tread (Inner): 5.5 Tread (Middle): 6.8 Tread (Outer): 6.8 Size: 235/35/19 Manufacturer: MICHELIN Speed: 91Y N-Rating: N2 Reason: OK DOT Code: 0319		
Spare	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Tread (Inner): N/A Tread (Middle): N/A Tread (Outer): N/A Size: N/A Manufacturer: N/A Speed: N/A N-Rating: N/A Reason: N/A DOT Code: N/A		
Inflation Kit Present / Check Expiry Date	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Tyre gel out of date - 02/15		
Alignment Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>			
Brakes							
Front Brake Pads / Discs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Pad Depth (mm): New Comments: Discs new		
Rear Brake Pads / Discs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Pad Depth (mm): New Comments: Discs new		
Brake Pipes / Hoses / Cables	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Handbrake Travel / Operation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Underside							
Shock Absorbers / Road Springs	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Steering / Joints / Drive Shaft / Gaiters	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Exhaust / Catalyst	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Fluid Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Engine / Transmission	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Levels							
Air Con	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Coolant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Brake Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Engine Oil Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Screen Wash Level	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Power Steering	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Battery	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Controls							
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Wash / Wipe	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Front Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			
Rear Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>			

Area	Urgen t	Advis.	OK	N/A	Additional Details	Auth? Comp?
Door, Boot, Bonnet Opening	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Exterior						
Bodywork / Interior	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Windscreen	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Number Plates	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Door Mirrors	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Wiper Blades	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Miscellaneous						
Other	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
Additional Comments						

Technician
James Darnbrough

Service Advisor
Grace Leonard

Customer Signature

We have carried out a visual inspection of your Porsche whilst it in our care today.

The purpose of the visual inspection of your Porsche is to ensure its condition is kept at the optimum operating level and we report any that visually fall below, our duty of care to you.

The report is provided to you for reference. It details the condition of your Porsche at the time of inspection providing you with the necessary information on repairs recommended both today and in the future, with the associated costs.

A copy of this report has been retained for our records.

Should you wish to proceed with repairs identified for the future (those ticked in the Advisory column), we will be happy to re-inspect the items marked Advisory and replace/advise on their condition accordingly.

All prices quoted for recommended rectification, will be valid for 30 days from the date of inspection.

Porsche Visual Health Check - maintaining performance, by keeping you informed.

Please note: The Porsche Health Check is a visual inspection, any dates for expected follow-up work provided are for general guidance only. The accuracy could vary depending on a number of factors such as vehicle mileage, road conditions, driving style. If an item is left blank, it has not been checked; core items will be checked as part of this Health Check; all other items will be checked at the technicians' discretion

Porsche Centre Hull

Alder Road, Bridgehead South
Business Park
Hessle, East Yorkshire HU130GW
01482 911918



PORSCHE

Porsche Centre Hull

Alder Road
Bridgehead South Business Park
Hessle
East Yorkshire
HU13 0GW
T: 01482 911918
E: info@porschehull.co.uk
W: porschehull.co.uk

Cashier: 61 S.

Transaction 100990

Total £630.95
DEBIT CARD SALE £630.95

CASH SALE INVOICE

Customer

17-Sep-2021 11:24:19A
£630.95 | Method: EMV
Visa Debit XXXXXXXXXXXX4204
Reference ID: FSMWPJ0QYGBEA
Auth ID: 659663
MID: *****6779
AID: A0000000031010
PIN VERIFIED

Online: <https://eu.clover.com/p/FSMWPJ0QYGBEA>

Porsche Centre Hull Privacy Policy
<https://eu.clover.com/privacy/m/qggctxxeqhw11>

Clover Privacy Policy
<https://eu.clover.com/privacy>

Chassis No.		Engine No.		Reg Date	
WPOZZZ98ZCU790237		RB42585		23/09/2011	
Account No.	YSB No.	W.I.P. No.	Job No.	Mileage	Time
c00002		W 16413	3518	19805	15:40
Invoice Date	Next MOT Date	You Were Served By		Invoice Printed By	
2023		Richard Gawthorne		Richard Gawthorne	

may have been

Page No. 1

Services	Qty.	Unit Price	Unit	Disc	Net Total	V
ck	0.30			%	0.00	S
tain parts replaced.	0.00			%	0.00	S
urpose of environmentally						
responsibly.						
Menu Subtotal:					0.00	
A 03140000	1.60			%	216.00	S
Carried out Intermediate maintenance Service						
A 03510053	0.47			%	63.45	S
Carried out brake fluid service						
X P90012310630	1.00	1.25	EACH	10.00	1.13	S
SEALING RING						
X P99757121901	1.00	63.29	EACH	10.00	56.97	S
PARTICLE FILTER						
X P00004400204	1.00	8.33	EACH	10.00	7.50	S
WINDOW CLEANER OUTER						
X P00004330521	1.00	21.16	EACH	10.00	19.05	S
ENGINE OIL - 0W40 TA						
X P00004321086	0.05	356.41	EACH	0.00	17.82	S
30 Litre Brake fluid						
X P0PB115466A	1.00	18.62	EACH	10.00	16.76	S
Oil filter insert						

V	Rate	Service/Goods	VAT

© E & O E





Porsche Centre Hull

Alder Road
 Bridgehead South Business Park
 Hessle
 East Yorkshire
 HU13 0GW
 T: 01482 911918
 E: info@porschehull.co.uk
 W: porschehull.co.uk

Invoice No. _____

CASH SALE INVOICE

* Information:

Make & Model		Chassis No.		Engine No.		Reg Date		
Cayman R		WPOZZZ98ZCU790237		RB42585		23/09/2011		
Reg No.	Customer Order No		Account No.	VSb No.	W.I.P. No.	Job No.	Mileage	Time
FL61WXE			c00002		W 16413	3518	19805	15:40
Document No	Date & Tax Point	Next Service Date	Next MOT Date	You Were Served By		Invoice Printed By		
61505303	16/09/2021	16/09/2023		Richard Gawthorne		Richard Gawthorne		

Please note: Additional mileage may have been incurred due to road test.

Description of Goods / Services							Qty.	Unit Price	Unit	Disc	Net Total	V	
I	VHC	Carry out Visual Health Check					0.30				%	0.00	S
T	ENV1	Customer does not wish to retain parts replaced. Porsche will dispose of environmentally responsibly.					0.00				%	0.00	S
Menu Subtotal:											0.00		
A	03140000	Carried out Intermediate maintenance Service					1.60				%	216.00	S
A	03510053	Carried out brake fluid service					0.47				%	63.45	S
X	P90012310630	SEALING RING					1.00	1.25	EACH	10.00		1.13	S
X	P99757121901	PARTICLE FILTER					1.00	63.29	EACH	10.00		56.97	S
X	P00004400204	WINDOW CLEANER OUTER					1.00	8.33	EACH	10.00		7.50	S
X	P00004330521	ENGINE OIL - 0W40 TA					1.00	21.16	EACH	10.00		19.05	S
X	P00004321086	30 Litre Brake fluid					0.05	356.41	EACH	0.00		17.82	S
X	POPB115466A	Oil filter insert					1.00	18.62	EACH	10.00		16.76	S

V	Rate	Service/Goods	VAT

E & O. E.



PORSCHE

Porsche Centre Hull

Alder Road
Bridgehead South Business Park
Hessle
East Yorkshire
HU13 0GW
T: 01482 911918
E: info@porschehull.co.uk
W: porschehull.co.uk

CASH SALE INVOICE

Address:

Customer Contact Information:

Make & Model		Chassis No.		Engine No.		Reg Date	
Cayman R		WPOZZZ98ZCU790237		RB42585		23/09/2011	
Reg No.	Customer Order No	Account No.	VSB No.	W.I.P. No.	Job No.	Mileage	Time
FL61WXE		c00002		W 16413	3518	19805	15:40
Document No	Date & Tax Point	Next Service Date	Next MOT Date	You Were Served By		Invoice Printed By	
61505303	16/09/2021	16/09/2023		Richard Gawthorne		Richard Gawthorne	

Page No. 2

Please note: Additional mileage may have been incurred due to road test.

Description of Goods / Services	Qty.	Unit Price	Unit	Disc	Net Total	V
X POPB115499A SEALING RING	1.00	8.69	EACH	10.00	7.83	S
X OIL50 Mobil 1 FS 0W-40	7.50	17.67	EACH	10.00	119.28	S

Parts	246.34	V	Rate	Service/Goods	VAT	Net	525.79
Surcharge	0.00	S	20.00	525.79	105.16	V.A.T.	105.16
Labour	279.45					Total	630.95
Sublet	0.00					Paid	0.00
Menus	0.00					Owing	630.95

© F&P

E & O.E.





Porsche Centre Reading
 Bath Road, Calcot, Reading
 Berkshire RG31 7SG
 Telephone: 0118 930 3911
 Telephone: 0118 971 1611 (Trade Parts)
 Fax: 0118 925 2898 (Sales)
 Fax: 0118 971 1612 (Trade Parts)
 Email: info@porschereading.co.uk
 Web: www.porsche.co.uk/reading

Cash Invoice

Address	Account No. C0002	Driver Name & Address
	Document Number 13632679	
	Date & Tax Point 21/10/2019	
	Order Number	

Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
Cayman R	WPOZZZ98ZCU790237	MA121	19486	14:48	1
Reference No.	Reg No.	Reg Date.	VSB No.	W.I.P. No.	Job No.
PP/21/NK	FL61WXE	23/09/2011		W 28649	653276

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
A	03160006				365.70	S
	Carried out Major Service					
X	P00004400204 WINDOW CLEANER OUTER	1.00	7.50	EACH	7.50	S
X	P90012310630 SEALING RING	1.00	1.10	EACH	1.10	S
X	P99610731351 SEALING RING	1.00	6.90	EACH	6.90	S
X	P99757121901 PARTICLE FILTER	1.00	56.32	EACH	56.32	S
X	ZMOBIL1 MOBIL1 FS OW40 1LTR	1.00	17.50	EACH	17.50	S
X	ZNOR2897333500 SOLVENT CLEANER 500m	1.00	8.50	EACH	8.50	S
X	P9A110722400 OIL-FILTER INSERT	1.00	17.52	EACH	17.52	S
P	LNL0W40 TANK Mobil 1 New Lif	7.70	16.89	EACH	130.05	S
	Subtotal:				611.09	
A	BFC				106.40	S
	Carried out Brake Fluid Change					
X	P00004321082 1 Litre Brake fluid	1.00	26.24	EACH	26.24	S
	Subtotal:				132.64	
A	03540050				57.00	S
	Additional maintenance after 4, 8, 10 years then every 2 years .					
	£68.40INC					
	Subtotal:				57.00	
Z	NOTE				0.00	S

E & O E	V	Rate	Service/Goods	V.A.T.

Customer's Signature Date Time

Head Office & Registered Office
 Porsche Retail Group Ltd Bath Road Calcot, Reading, Berkshire RG31 7SG
 Reg No 220221 VAT No 479 4101 33



PORSCHE

Porsche Centre Reading

Bath Road, Calcot, Reading
Berkshire RG31 7SG
Telephone: 0118 930 3911
Telephone: 0118 971 1611 (Trade Parts)
Fax: 0118 925 2898 (Sales)
Fax: 0118 971 1612 (Trade Parts)
Email: info@porschereading.co.uk
Web: www.porsche.co.uk/reading

Cash Invoice

Invoice Name & Address

Account No.

C0002

Document Number

13632679

Date & Tax Point

21/10/2019

Order Number

Driver Name & Address

Make & Model

Chassis No.

Engine No.

Mileage

Time

Page

Cayman R

WP0ZZZ98ZCU790237

MA121

19486

14:48

2

Reference No.

Reg No.

Reg Date.

VS No.

W.I.P. No.

Job No.

PP/21/NK

FL61WXE

23/09/2011

W 28649

653276

Description of Goods / Services		Qty.	Unit Price	Unit Des	Net Total	V
X	Supplied only spark plugs at customer request. P99917013090 SPARK PLUG	6.00	14.98 EACH		89.88	S
				Subtotal:	89.88	
P	LC Supplied loan car. CUSTOMER HAS BEEN ADVISED OF INSURANCE DETAILS Any damage, including wheel or windscreen damage, fines and traffic contraventions will be charged. Car must be returned with replenished fuel.				0.00	S
				Subtotal:	0.00	
Z	FREE Carried out wash & vacuum				0.00	S
Z	DETAIL No Warranty				0.00	S
X	CENV Environmental Dispos	1.00	5.00 EACH		5.00	S
				Subtotal:	5.00	
Z	RT41 YOUR TECHNICIAN TODAY WAS NATHAN KEEN				0.00	Z

E & O E

V	Rate	Service/Goods	V.A.T.

Customer's

Signature

Date

Time

Head Office & Registered Office
Porsche Retail Group Ltd Bath Road, Calcot, Reading, Berkshire RG31 7SG
Reg No. 220221 VAT No. 479 4101 33



Porsche Centre Reading

Bath Road, Calcot, Reading
 Berkshire RG31 7SG
 Telephone: 0118 930 3911
 Telephone: 0118 971 1611 (Trade Parts)
 Fax: 0118 925 2898 (Sales)
 Fax: 0118 971 1612 (Trade Parts)
 Email: info@porschereading.co.uk
 Web: www.porsche.co.uk/reading

Cash Invoice

Account No. C0002		Driver Name & Address	
Document Number 13632679			
Date & Tax Point 21/10/2019			
Order Number			

Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
Cayman R	WP0ZZZ98ZCU790237	MA121	19486	14:48	3

Reference No.	Reg No.	Reg Date.	VS No.	W.I.P. No.	Job No.
PP/21/NK	FL61WXE	23/09/2011		W 28649	653276

Description of Goods / Services	Qty.	Unit Price	Unit Des	Net Total	V
Subtotal:				0.00	

Any Queries Please Contact: James Sheriff

E & O E		V	Rate	Service/Goods	V.A.T.	Net	
Parts	366.51	S	20.00	895.61	179.12	895.61	
Surcharge	0.00					179.12	
Lab/Oil/Tyres	529.10					1074.73	
Sublet	0.00					0.00	
Menus	0.00					1074.73	
						Total	1074.73
						Paid	0.00
						Owing	1074.73

Customer's Signature Date Time

The Porsche Steps-Check

Porsche Centre Reading

0118 9303911



PORSCHE

Contact Telephone Number Mobile: 07782 324897

Wip Number 28649

Reg. Number FL61WXE

Vehicle Cayman R

Mileage 19,482

MOT Due _____

Service Due 20/10/2019

	Comments/Recommendations	Fitted Price Inc Vat	Auth
STEP 1: Additional Service Item			
<input checked="" type="checkbox"/> Brake Fluid			
<input checked="" type="checkbox"/> PDK Oil Change			
<input checked="" type="checkbox"/> Air Bag Check			
<input checked="" type="checkbox"/> Front Diff Oil			
<input checked="" type="checkbox"/> Spark Plugs	Due- customer request to leave on passengers seat.	107.86	Y
<input checked="" type="checkbox"/> Drive Belt			
<input checked="" type="checkbox"/> Aircon Service			
STEP 2: External Inspection - T			
<input checked="" type="checkbox"/> Bodywork			
<input checked="" type="checkbox"/> Trim			
<input checked="" type="checkbox"/> Glass			
<input checked="" type="checkbox"/> Mirrors/mirror housing			
<input checked="" type="checkbox"/> Lights			
<input checked="" type="checkbox"/> Washers and Wipers	Wiper Blades Front Need Replacing as smearing screen due to worn rubber wiper blades. parts= front wiper blades.		N
<input checked="" type="checkbox"/> Door Locking			
<input checked="" type="checkbox"/> Number Plate Condition			
STEP 3: Tyre Check - Service A			
<input checked="" type="checkbox"/> Left Front Tyre	6.0 MM - 31% worn		
<input checked="" type="checkbox"/> Right Front Tyre	6.5 MM		
<input checked="" type="checkbox"/> Left Rear Tyre	7.0 MM - 15% worn		
<input checked="" type="checkbox"/> Right Rear Tyre	7.0 MM - 15% worn		
<input checked="" type="checkbox"/> Spare or Tyre Inflation Kit	Canister - Expired EXP: 21-02-2015		N
<input checked="" type="checkbox"/> Wheel alignment recommended?			
STEP 4: Under Bonnet - Techni			
<input checked="" type="checkbox"/> Coolant Level & Condition			
<input checked="" type="checkbox"/> Brake Fluid Level & Condition			
<input checked="" type="checkbox"/> Drive Belt Condition			
<input checked="" type="checkbox"/> Engine Bay General			
<input checked="" type="checkbox"/> Battery Condition			
<input checked="" type="checkbox"/> Screen wash Level			
<input checked="" type="checkbox"/> Engine Oil Level			
<input checked="" type="checkbox"/> Power Steering Fluid Level			
<input checked="" type="checkbox"/> Other/miscellaneous	Ducts and drains require clean.		N
STEP 5: Internal Check - Techni			
<input checked="" type="checkbox"/> Windscreen and Headlight wash/wipe operation			
<input checked="" type="checkbox"/> Horn			
<input checked="" type="checkbox"/> Interior Lights			
<input checked="" type="checkbox"/> Instruments			
<input checked="" type="checkbox"/> Foot and Handbrake operation			
<input checked="" type="checkbox"/> Warning Lights			
<input checked="" type="checkbox"/> Seat belts/buckles			
<input checked="" type="checkbox"/> Heating and Ventilation			
<input checked="" type="checkbox"/> Other/miscellaneous			
<input checked="" type="checkbox"/> Exterior light operation			

This work has been brought to my attention and I have decided not to have all the work completed before leaving the premises.

Inspected by Nathan Keen Quality Control By Nathan Keen Customer Signature _____

This is not an invoice (all estimates are valid for 30 days). This is a report on mechanical condition, not an invoice or quote for work to be done. Please ask for a written estimate for remedial work.

The Porsche 7 Steps-Check

Porsche Centre Reading

0118 9303911



PORSCHE

Contact Telephone Number Mobile: 07782 324897

L

Wip Number 28649

Reg. Number FL61WXE

Vehicle Cayman R

Mileage 19,482

MOT Due _____

Service Due 20/10/2019






	Comments/Recommendations	Fitted Price Inc Vat	Auth
STEP 6: Underbody Checks - Te			
G Transmission & Final Drive Visual Check			
G Steering and Suspension			
G Drive Shafts			
G Hoses			
G Oil Seals			
R Exhaust System & Underbody Protection	Exhaust fixings corroded excessively recommend replacement parts= exhaust fixings repair kit.		N
A Front Brake Disc Thickness	0.7mm before max wear would recommend replacement of discs due to being lipped/worn/light corrosion to inner and outer faces along with pads as currently measuring at 5mm wont last till next service. front brake pads, discs and fitting kits.		N
A Front Brake Pads Thickness	Pads 5 mm remaining recommend replacement of front brake pads and discs as wont last till next service, wear indicator will be on the dash anytime soon. parts= front brake pads, discs and fitting kits.		N
G Rear Brake Disc Thickness	1.0mm before max wear		
G Rear Brake Pads Thickness	Pads 7 mm remaining		
G Check & Confirm Tyre Condition	Checked and tyre report amended		
G Other/miscellaneous			
STEP 7: QA - Test Drive - Techn			
Levels Correct	**Not Inspected**		
Work Complete	**Not Inspected**		
Handling & Performance	**Not Inspected**		
	Dents	Important: This report is the result of a visual inspection only. Further checks or disassembly may be required to determine the full extent of requirements.	
	Scratches		
	Chips		
	Rust		
	Corrosion		
Other	Total price for authorised work	107.86	

This work has been brought to my attention and I have decided not to have all the work completed before leaving the premises.

Inspected by Nathan Keen Quality Control By Nathan Keen Customer Signature _____

This is not an invoice (all estimates are valid for 30 days). This is a report on mechanical condition, not an invoice or quote for work to be done. Please ask for a written estimate for remedial work.

Your tyres. Reg No: FL61WXE Booking No: 28649

Tyres		What does this mean?		Visually OK	Advisory	Immediate attention																																																		
Left Front Tyre  <table border="1"> <tr><td>31</td><td>% worn</td></tr> <tr><td>6</td><td>mm</td></tr> <tr><td>✓</td><td>pressure checked</td></tr> <tr><td>6</td><td>inner tread depth</td></tr> <tr><td>7.5</td><td>middle tread depth</td></tr> <tr><td>7.5</td><td>outer tread depth</td></tr> </table>		31	% worn	6	mm	✓	pressure checked	6	inner tread depth	7.5	middle tread depth	7.5	outer tread depth	Right Front Tyre  <table border="1"> <tr><td></td><td>% worn</td></tr> <tr><td>6.5</td><td>mm</td></tr> <tr><td>✓</td><td>pressure checked</td></tr> <tr><td>6.5</td><td>inner tread depth</td></tr> <tr><td>7.5</td><td>middle tread depth</td></tr> <tr><td>7.5</td><td>outer tread depth</td></tr> </table>			% worn	6.5	mm	✓	pressure checked	6.5	inner tread depth	7.5	middle tread depth	7.5	outer tread depth	Left Rear Tyre  <table border="1"> <tr><td>15</td><td>% worn</td></tr> <tr><td>7</td><td>mm</td></tr> <tr><td>✓</td><td>pressure checked</td></tr> <tr><td>7</td><td>inner tread depth</td></tr> <tr><td>8</td><td>middle tread depth</td></tr> <tr><td>8</td><td>outer tread depth</td></tr> </table>		15	% worn	7	mm	✓	pressure checked	7	inner tread depth	8	middle tread depth	8	outer tread depth	Right Rear Tyre  <table border="1"> <tr><td>15</td><td>% worn</td></tr> <tr><td>7</td><td>mm</td></tr> <tr><td>✓</td><td>pressure checked</td></tr> <tr><td>7</td><td>inner tread depth</td></tr> <tr><td>7.5</td><td>middle tread depth</td></tr> <tr><td>7.5</td><td>outer tread depth</td></tr> </table>		15	% worn	7	mm	✓	pressure checked	7	inner tread depth	7.5	middle tread depth	7.5	outer tread depth	Spare or Tyre Inflation Kit 
31	% worn																																																							
6	mm																																																							
✓	pressure checked																																																							
6	inner tread depth																																																							
7.5	middle tread depth																																																							
7.5	outer tread depth																																																							
	% worn																																																							
6.5	mm																																																							
✓	pressure checked																																																							
6.5	inner tread depth																																																							
7.5	middle tread depth																																																							
7.5	outer tread depth																																																							
15	% worn																																																							
7	mm																																																							
✓	pressure checked																																																							
7	inner tread depth																																																							
8	middle tread depth																																																							
8	outer tread depth																																																							
15	% worn																																																							
7	mm																																																							
✓	pressure checked																																																							
7	inner tread depth																																																							
7.5	middle tread depth																																																							
7.5	outer tread depth																																																							
Comments N2 Rated		Comments N2 Rated		Comments N2 Rated		Comments N2 Rated		Comments Canister - Expired																																																

Please note: This report and any repair costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Parts subject to wear are considered defective when the maximum amount of wear permissible is reached.

Tyre labelling

What does it all mean?

All tyres now come with a label that gives ratings for fuel efficiency, wet grip and rolling noise. In the case of fuel efficiency, a rating of A indicates the most efficient and G the least. For wet grip, a tyre with an A rating provides the shortest braking distance and G, the longest. Finally, external rolling noise is measured in decibels. One wave indicates a quieter tyre and three waves are louder (when comparing identical section widths).



PORSCHE

Porsche Centre Guildford

Woodbridge Meadows
Guildford, Surrey
GU1 1BD
Telephone: 01483 408 800
Fax: 01483 408 814
Email: info@porscheguildford.co.uk
Web: www.porsche.co.uk/guildford

Cash Invoice

Invoice form with fields for Invoice Name & Address, Account No. (C0002), Document Number (23626012), Date & Tax Point (20/10/2017), Order Number, and Driver Name & Address.

Table with columns: Make & Model (Cayman R), Chassis No. (WP0ZZZ98ZCU790237), Engine No. (MA121), Mileage (17422), Time (17:30), Page (1). Includes Reference No. (5SGL), Reg No., Reg Date (23/09/2011), VSB No., W.I.P. No. (W 14886), and Job No. (732158).

Main items table with columns: Description of Goods / Services, Qty., Unit Price, Unit Des., Net Total, and V. Includes items like Intermediate maintenance, MOBIL ONE 1 Litre, WINDOW CLEANER, ALUM. SEALING RI, SEALING RING, PARTICLE FILTER, FILTER ELEMENT, Mobil 1 New Life OW-, BRAKE FLUID, V-BELT, and Engine compartment lid removed and reinstalled.

Summary table with columns: V, Rate, Service/Goods, V.A.T. Includes a small logo on the left side.

Customer's Signature Date Time
Head Office & Registered Office
Porsche Retail Group Ltd. Bath Road, Calcot, Reading, Berkshire RG31 7SG
Reg No 220221 VAT No 479 4101 33



PORSCHE

Porsche Centre Guildford

Woodbridge Meadows
Guildford, Surrey
GU1 1BD
Telephone: 01483 408 800
Fax: 01483 408 814
Email: info@porscheguildford.co.uk
Web: www.porsche.co.uk/guildford

Cash Invoice

Invoice Name & Address, Account No. C0002, Document Number 23626012, Date & Tax Point 20/10/2017, Order Number, Driver Name & Address

Table with columns: Make & Model (Cayman R), Chassis No. (WP0ZZZ98ZCU790237), Engine No. (MA121), Mileage (17422), Time (17:30), Page (2). Reference No. (5SGL), Reg No. (23/09/2011), VSB No. (W 14886), Job No. (732158).

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Unit Des., Net Total, V. Includes items like Shift cable removed and reinstalled, Engine compartment lid removed and reinstalled, Rear wall flap removed and reinstalled, Console removed and reinstalled, CABLE, 057856/LEVER, Support, Fuse checked, Loudspeaker booster troubleshooting, Loudspeaker booster removed and reinstalled, Booster.

Summary table with columns: V, Rate, Service/Goods, V.A.T.

Customer's Signature, Date, Time, Head Office & Registered Office: Porsche Retail Group Ltd Bath Road, Calcot, Reading, Berkshire RG31 7SG, Reg No. 220221, VAT No. 479 4101 33



PORSCHE

Porsche Centre Guildford

Woodbridge Meadows
Guildford, Surrey
GU1 1BD
Telephone: 01483 408 800
Fax: 01483 408 814
Email: info@porscheguildford.co.uk
Web: www.porsche.co.uk/guildford

Cash Invoice

Invoice Name & Address		Account No. C0002 Document Number 23626012 Date & Tax Point 20/10/2017 Order Number	Driver Name & Address			
Make & Model		Chassis No.	Engine No.	Mileage	Time	Page
Cayman R		WP0ZZZ98ZCU790237	MA121	17422	17:30	3
Reference No.	Reg No.	Reg Date.	VSF No.	W.I.P. No.	Job No.	
	5SGL	23/09/2011		W 14886	732158	

	Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
X	P9A7.007.483.00 TORX SCREW	4.00	1.60	EACH	6.40	S
				Subtotal:	460.34	
Z	GT31 YOUR TECHNICIAN TODAY WAS JAKE FERGUSSON				0.00	Z
				Subtotal:	0.00	

Any Queries Please Contact: Ashleigh Greenslade

E & O E		V	Rate	Service/Goods	V.A.T.		
Parts	908.25	S	20.00	1710.65	342.13	Net	1710.65
Surcharge	0.00					V.A.T.	342.13
Lab/Oil/Tyres	802.40					Total	2052.78
Sublet	0.00					Paid	0.00
Menus	0.00					Owing	2052.78

Customer's Signature Date Time

PORSCHE CENTRE READING ()
 BATH ROAD
 CALCOT
 M***39913 110****5694
 REF: 13587959



PORSCHE

Porsche Centre Reading
 Bath Road, Calcot, Reading
 Berkshire RG31 7SG
 Telephone: 0118 930 3911
 Telephone: 0118 971 1611 (Trade Parts)
 Fax: 0118 925 2898 (Sales)
 Fax: 0118 971 1612 (Trade Parts)
 Email: info@porschereading.co.uk
 Web: www.porsche.co.uk/reading

VISA DEBIT

5532
 KEYED

Cash Invoice

SALE
 CARDHOLDER COPY
 PLEASE KEEP THIS RECEIPT
 FOR YOUR RECORDS

AMOUNT £577.37

CUSTOMER NOT PRESENT
 THANK YOU
 16:38 05/11/15

AUTH CODE: 005479

Account No.
C0002
 Document Number
13587959
 Date & Tax Point
20/10/2015
 Order Number
CB5300187

Driver Name & Address

Chassis No.	Engine No.	Mileage	Time	Page
WPOZZZ98ZCU790237	MA121	12983	18:19	1
Reg No.	Reg Date.	VSBN.	W.I.P. No.	Job No.
5SGL	23/09/2011		W 45795	635005

Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
A ABC Carry out Air Bag Check £70				58.08	S
Subtotal:				58.08	
A DBC Check Drive belt £70				58.08	S
Subtotal:				58.08	
A SPR Replace spark plugs £200 INC				76.01	S
X P999.170.130.90 S.PLUG FGR5NQE04	6.00	15.11	EACH	90.66	S
Subtotal:				166.67	
G MECH REPLACE STEERING RACK CUSTOMER CONTRIBUTION			005	304.52	S
Subtotal:				304.52	
G MECH REPLACE CORRODED EXHAUST FIXINGS CUSTOMER CONTRIBUTION			007	296.61	S

E & O. E.

V	Rate	Service/Goods	V.A.T.

© F&P

Customer's Signature Date Time



PORSCHE

Porsche Centre Reading

Bath Road, Calcot, Reading
Berkshire RG31 7SG
Telephone: 0118 930 3911
Telephone: 0118 971 1611 (Trade Parts)
Fax: 0118 925 2898 (Sales)
Fax: 0118 971 1612 (Trade Parts)
Email: info@porschereading.co.uk
Web: www.porsche.co.uk/reading

Cash Invoice

Customer & Address, Account No. C0002, Document Number 13587959, Date & Tax Point 20/10/2015, Order Number CB5300187, Driver Name & Address

Table with columns: Make & Model, Chassis No., Engine No., Mileage, Time, Page. Row 1: Cayman R, WP0ZZZ98ZCU790237, MA121, 12983, 18:19, 2. Row 2: Reference No., Reg No., Reg Date., VSB No., W.I.P. No., Job No. Row 3: PP/17/JS, 5SGL, 23/09/2011, W 45795, 635005

Main invoice table with columns: Description of Goods / Services, Qty., Unit Price, Unit Des., Net Total, V. Rows include MECH (REPLACE CORRODED VACUUM LINE CLIPS), VHC (Carry out vehicle health check), VAL (Carry out vehicle analysis including transmission), RT15 (YOUR TECHNICIAN TODAY WAS Justin Semonella), CON (Contribution), FREE (CARRY OUT WASH & VACUUM FREE OF CHARGE). Subtotals are shown for each section.

Summary table with columns: V, Rate, Service/Goods, V.A.T. Includes a small logo on the left side.

Customer's Signature Date Time



PORSCHE

Porsche Centre Reading
Bath Road, Calcot, Reading
Berkshire RG31 7SG
Telephone: 0118 930 3911
Telephone: 0118 971 1611 (Trade Parts)
Fax: 0118 925 2898 (Sales)
Fax: 0118 971 1612 (Trade Parts)
Email: info@porschereading.co.uk
Web: www.porsche.co.uk/reading

Cash Invoice

Name & Address		Account No. C0002	Driver Name & Address	
		Document Number 13587959		
		Date & Tax Point 20/10/2015		
		Order Number CB5300187		
Make & Model	Chassis No.	Engine No.	Mileage	Time
Cayman R	WP0ZZZ98ZCU790237	MA121	12983	18:19
Reference No.	Reg No.	Reg Date.	VSB No.	W.I.P. No.
PP/17/JS	5SGL	23/09/2011		W 45795
				Job No. 635005

Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
Subtotal:				0.00	

Any Queries Please Contact: Gina Draper

E. & O. E.	V	Rate	Service/Goods	V.A.T.	Net	481.14
Parts	S	20.00	481.14	96.23	V.A.T.	96.23
Surcharge					Total	577.37
Lab/Oil/Tyres					Paid	0.00
Sublet					Owing	577.37
Menus						

Customer's Signature Date Time

goods on the authority of the Customer. The Vehicle or its accessories are provided to the Customer in respect of death or personal injury or property damage or loss or expense and shall be limited or damage occasioned by the release of the Customer to have possession of the



PORSCHE
RETAIL GROUP

Porsche Centre Reading

Porsche Centre Reading (Retail), Bath Road, Calcot, RG31 7SG
Telephone: 0118 930 3911
Email: info@porschereading.co.uk
www.porsche.co.uk/reading

Vehicle Health Check

Customer Name	Lincoln	Vehicle Reg	FL61WXE
Customer Tel No		Mileage	
WIP Number	44910	Date	21/09/2015

	ok	Advisory	Urgent	Description	Authorised?	Follow-up	Declined	Follow Up Date	Warranty
Inside the Car									
External Lights		X		o/s number plate retaining clips broken			X		
Washers & Wipers		X		requires wipers			X		
Horn	X								
Check for Warning Lights	X								
Internal Lights & Functions	X								
Heating & Ventilation	X								
Media Functions	X								
Service Due within 3 Mth?	X								
Additional	X								
Body Condition									
External trim/ Bodywork Accident Damage/ Corrosion	X								
Wheel Condition		X		slight flat spot to n/s/f wheel					X
Additional		X		air bag check due 4 years	X				
Under Bonnet									
Engine Oil Level	X								
Coolant level & Strength	X								
Brake Fluid Level & Condition	X								
Battery Condition		X		non genuine battery					X
Aux Belts		X		drive belt check 4 years	X				
Additional		X		requires rewax					X
Under Vehicle									
Hubs & Bearings	X								
Suspension/ Bushes/ Mounts	X								
Engine Hoses/ Pipes	X								
Engine Fluid Leaks	X								
Gear Box Leaks	X								
Brake Hose/ Pipes	X								
Additional		X		sports exhaust metal vacuum pipe clips rusted away	X				
Exhaust Condition		X		exhaust flange fixings rusting away	X				
Front Brake Pads & Disc's		X		front pads approx 30% discs fine					X
Rear Brake Pads & Disc's		X		rear pads approx 20 % discs fine					X
Steering			X	steering rack leaking into steering bellows	X				

PORSCHE CENTRE READING (

BATH ROAD
CALCOT
M***39913 TID****5694
REF: 13587189



PORSCHE

Porsche Centre Reading

Bath Road, Calcot, Reading
Berkshire RG31 7SG
Telephone: 0118 930 3911
Telephone: 0118 971 1611 (Trade Parts)
Fax: 0118 925 2898 (Sales)
Fax: 0118 971 1612 (Trade Parts)
Email: info@porschereading.co.uk
Web: www.porsche.co.uk/reading

VISA DEBIT

**** * 8129
KEYED

Cash Invoice

SALE
CARDHOLDER COPY
PLEASE KEEP THIS RECEIPT
FOR YOUR RECORDS

Account No. C0002		Driver Name & Address	
Document Number 13587189			
Date & Tax Point 22/09/2015			
Order Number			
Chassis No.	Engine No.	Mileage	Time
WP0ZZZ98ZCU790237	MA121	12818	12:48
Page			1
Reg No.	Reg Date.	VSB No.	W.I.P. No.
5SGL	23/09/2011		W 44910
			634691

AMOUNT **£760.00**
CUSTOMER NOT PRESENT
THANK YOU
12:30 22/09/15
AUTH CODE: **022957**

PP/21/JS

Description of Goods / Services	Qty.	Unit Price	Unit Des.	Net Total	V
A P40				329.22	S
Carry Out Major Service					
Quoted customer £610.00					
X P000.044.000.87 WINDOW CLEANER	1.00	4.27	EACH	4.27	S
X P900.123.106.30 ALUM. SEALING RI	1.00	0.97	EACH	0.97	S
X P9A1.107.224.00 FILTER ELEMENT	1.00	19.48	EACH	19.48	S
X P996.107.313.51 SEALING RING	1.00	5.87	EACH	5.87	S
X P997.571.219.01 PARTICLE FILTER	1.00	49.35	EACH	49.35	S
X ZMOBIL1 I LTR OIL	1.00	16.67	EACH	16.67	S
X ZOR2897333500 SOLVENT CLEANER 500m	1.00	7.50	EACH	7.50	S
P LNL0W40 TANK Mobil 1 New Lif	6.00	10.00	EACH	60.00	S
P LNL0W40 TANK Mobil 1 New Lif	1.50	10.00	EACH	15.00	S
			Subtotal:	508.33	
				105.26	S
A BFC					
Carry out Brake Fluid Change					
Quoted customer £150.00					
X P000.043.203.66 BRAKE FLUID	1.00	19.74	EACH	19.74	S
			Subtotal:	125.00	
				0.00	S
A VHC					
Carry out vehicle health check					
			Subtotal:	0.00	

E & O. E.

V	Rate	Service/Goods	V.A.T.

Customer's Signature Date Time
Head Office & Registered Office: Porsche Retail Group Ltd. Bath Road, Calcot, Reading, Berkshire RG31 7SG. Reg. No. 220221. VAT No. 479 4101 33



PORSCHE

Porsche Centre Reading

Bath Road, Calcot, Reading
Berkshire RG31 7SG
Telephone: 0118 930 3911
Telephone: 0118 971 1611 (Trade Parts)
Fax: 0118 925 2898 (Sales)
Fax: 0118 971 1612 (Trade Parts)
Email: info@porschereading.co.uk
Web: www.porsche.co.uk/reading

Cash Invoice

Invoice form with fields for Invoice Name & Address, Account No. (C002), Document Number (13587189), Date & Tax Point (22/09/2015), Order Number, and Driver Name & Address.

Table with columns: Make & Model (Cayman R), Chassis No. (WP0ZZZ98ZCU790237), Engine No. (MA121), Mileage (12818), Time (12:48), Page (2), Reference No. (PP/21/JS), Reg No. (5SGL), Reg Date. (23/09/2011), VSB No., W.I.P. No. (W 44910), Job No. (634691).

Main invoice table with columns: Description of Goods / Services, Qty., Unit Price, Unit Des., Net Total, V. Includes items like VAL Carry out vehicle analysis, FREE CARRY OUT WASH & VACUUM, and RT15 YOUR TECHNICIAN TODAY WAS Justin Semonella.

Any Queries Please Contact: Gina Draper

Summary table with columns: V, Rate, Service/Goods, V.A.T., Net, V.A.T., Total, Paid, Owing. Totals: Net 633.33, V.A.T. 126.67, Total 760.00, Paid 0.00, Owing 760.00.



PORSCHE
RETAIL GROUP

Porsche Centre Reading

Porsche Centre Reading (Retail), Bath
Road, Calcot, RG31 7SG
Telephone: 0118 930 3911
Email: info@porschereading.co.uk
www.porsche.co.uk/reading

Vehicle Health Check

Customer Name	Lincoln	Vehicle Reg	FL61WXE
Customer Tel No		Mileage	
WIP Number	44910	Date	21/09/2015

	ok	Advisory	Urgent	Description	Authorised?	Follow-up	Declined	Follow Up Date	Warranty
Inside the Car									
External Lights	X	X		o/s number plate retaining clips broken	X		X		
Washers & Wipers	X	X		requires wipers	X		X		
Horn	X				X				
Check for Warning Lights	X				X				
Internal Lights & Functions	X				X				
Heating & Ventilation	X				X				
Media Functions	X				X				
Service Due within 3 Mth?	X				X				
Additional	X				X				
Body Condition									
External trim/ Bodywork Accident Damage/ Corrosion	X				X				
Wheel Condition	X	X		slight flat spot to n/s/f wheel	X		X		
Additional	X	X		air bag check due 4 years	X		X		
Under Bonnet									
Engine Oil Level	X				X				
Coolant level & Strength	X				X				
Brake Fluid Level & Condition	X				X				
Battery Condition	X	X		non genuine battery	X		X		
Aux Belts	X	X		drive belt check 4 years	X		X		
Additional	X	X		requires re wax	X		X		
Under Vehicle									
Hubs & Bearings	X				X				
Suspension/ Bushes/ Mounts	X				X				
Engine Hoses/ Pipes	X				X				
Engine Fluid Leaks	X				X				
Gear Box Leaks	X				X				
Brake Hose/ Pipes	X				X				
Additional	X	X		sports exhaust metal vacuum pipe clips rusted away	X		X		
Exhaust Condition	X	X		exhaust flange fixings rusting away	X		X		
Front Brake Pads & Disc's	X	X		front pads approx 30% discs fine	X		X		
Rear Brake Pads & Disc's	X	X		rear pads approx 20 % discs fine	X		X		
Steering	X	X		steering rack leaking into steering bellows	X		X		

Service Additional	Description	Authorised?	Follow Up Date	Warranty
Air Conditioning Service				
Pollen Filter Condition				
Fuel & Air Filters				
Additional	spark plugs due 4 years			X
Ducts & Drains	pus and drains to be cleaned			X

Other	Description	Authorised?	Follow Up Date	Warranty
Check Oil				
Check Tyres	mixed tyre makes , tyres 3mm			X
Check Tyre Sealant is in Date	tyre sealant due			X

Tyres	Out	Mld	Inn	Make	Pattern
1. Off Side Front	7.0	6.0	5.0	Michelin	235/35 zr 19 n2
1. Near Side Front	6.0	6.0	5.0		
1. Near Side Rear	4.0	4.0	6.0	Pirelli	265/35 zr19 n2
1. Off Side Rear	3.0	3.0	5.0		
1. Spare					

Service Advisor		Technician		Customer	
Date	Time	Date	Time	Date	Time



PORSCHE

We are delighted to have had the opportunity to look after your Porsche recently, and would like to thank you for choosing Porsche Centre Reading for your after-sales care.

At Porsche Centre Reading we are dedicated to ensuring that each and every one of our customers receives an exceptional experience indicative of the Porsche brand.

With the above in mind, you will shortly receive a Porsche Passion Survey requesting feedback on your visit today. This allows us to continuously improve the customer experience given. It is therefore important to both Tim Sweet and the team in the Aftersales Department.

Porsche Centre Reading is committed to delivering an 'Excellent' level of service to each of our customers; if however, you feel that on this occasion we have not met this standard or exceeded your expectations, please email us back on louise.jenkins-smith@porschereading.co.uk and I will contact you as soon as possible to resolve any concerns you may have.

Yours sincerely

Louise Jenkins-Smith
After-Sales Manager
Porsche Centre Reading



Porsche
 Fort King
 Edinburgh
 Telephone
 Fax: 0131
 Email: info@sytner.com
 Web: www.sytner.com

SYTNER CARS T/A PORSCHE
 PORSCHE EDINBURGH
 EDINBURGH

44556552 24260724
 16/04/13 12:44 0691

& Add VISA DEBIT ICC
 A00000000031010
 *****2918
 Exp: 09/14 Start: 10/11 00

Email: mark.sajda@smc

You were served by: Scott Fraser

Inv. Printed By: Scott Fraser

Account No.	Document Number	Date & Tax Point	Order Num		
C00002	14019347	16/04/2013	03.50/W/N		
Make & Model	Chassis No.	Engine No.	Mileage	Time	Page
Cayman R	WP0ZZZ98ZCU790237	R B42585	4792	12:41	1
Reference No.	Reg No.	Reg Date	VSB No.	W.I.P. No.	Job No.
	FL61WXE	23/09/2011		W 57278	17359

Special offers on air con svc!

Description of Goods / Services	Qty.	Unit Price	Unit	Net Total	V
A 987.20 Carried out minor service				194.91	S
A BFC Carried out brake fluid change				106.10	S
L MOBIL1 Mobill OW40 Fully Synthetic Engine Oil				117.28	S
X P000.044.000.87 WINDOW CLEANER	1.00	4.27	EACH 11	4.27	S
X O151047 MOBIL 1 Ow40 1L	1.00	13.00	EACH N	13.00	S
X P000.043.203.66 BRAKE FLUID	1.00	19.06	EACH 7	19.06	S
X Z997.571.219.01 POLLEN FILTER	1.00	47.38	EACH N	47.38	S
X P900.123.106.30 ALUM. SEALING RI	1.00	0.80	EACH 8	0.80	S
X P996.107.313.51 SEALING RING	1.00	5.30	EACH 6	5.30	S
X P9A1.107.224.00 FILTER ELEMENT	1.00	16.88	EACH 9	16.88	S
T TGT Thank you for allowing me to work on your vehicle. Gareth Thomson, Technician				F.O.C.	S
T TREP Tyre Report : - Pirelli P Zero N2 N/S/F =5.2/5.4/4.6mm O/S/F =4.9/5.6/5.7mm N/S/R =4.3/3.3/5.0mm O/S/R =5.0/3.1/4.4mm Legal minimum 1.6mm Front 235/35 R 19 Rear 265/35 R 19				F.O.C.	S

All goods remain the property of the vendor until full payment has been made and any relevant cheques cleared. Cheques will be accepted to the limit of a supporting Bankers Card. Full terms of business available on request and on reverse of document.

V	Rate	Service/Goods	VAT	Net	
S	20.00	524.98	105.00	524.98	
				V.A.T.	105.00
				Total	629.98
				Paid	0.00
				Owing	629.98

PORSCHE

Intermediate maintenance (A markets*) Cayman (987), Cayman S (987) Boxster (987), Boxster S (987) 911 Carrera (997), 911 Carrera S (997) as of 2010 model

Vehicle Ident. No. W0ZZZ98ZCU7910234

Working instruction for order no.

59298

- Intermediate maintenance**
at 30,000, 90,000, 150,000, 210,000 km etc./20,000, 60,000, 100,000, 140,000 miles etc.
(Labour operation 03 14 00 ..)
For a description of the various models, see Technical Manual

Note: If the mileage for a regular service is not reached, intermediate maintenance must be carried out after 2, 6, 10..... years.

The term 'checking' includes all necessary subsequent work, such as adjusting, readjusting, correcting and topping up, but does not include repairing, replacing and reconditioning parts or assemblies.

Diagnostic system: read out fault memory; reset maintenance interval	✓
Change engine oil and oil filter	✓
Vehicle underbody and engine compartment: visual inspection for leaks (oils and fluids) and chafing damage (lines and hoses) Underbody panels: visual inspection for completeness, secure installation and damage	✓
Coolant hoses: check condition Radiators and air inlets: visual inspection for external contamination and blockage Coolant: check level and antifreeze	✓
Particle filter: replace filter element	✓
Brake system: visual inspection of brake pads and brake discs for wear (without removing and fitting wheels)	✓
Brake hoses and lines: visual inspection for leaks, damage, routing and corrosion	✓
Drive shafts: visual inspection of the boots for leaks and damage	✓
Tyres: check condition and tyre pressure	✓
Check the door locks, lid locks and safety hooks of the front lid to ensure that they are secure and functioning properly	✓
Vehicle lighting: check operation All headlights: check adjustment Horn: check operation	✓
Windscreen wiper/washer system, headlight cleaning system: check fluid level and nozzle settings, check window cleaner or antifreeze, depending on time of year; check wiper blades	✓
Electrical equipment, warning and indicator lights: check operation	✓
Battery: check functional state and fluid level	✓
Replace spark plugs: see Additional maintenance	✓

* Applies to vehicles in the following countries:

- | | | | |
|------------------------|---------------|-----------------------|-------------|
| Andorra | France | Malta | Spain |
| Austria | Germany | Monaco | Sweden |
| Belgium | Greece | Netherlands | Switzerland |
| Bosnia and Herzegovina | Hungary | Norway | |
| Croatia | Iceland | Poland | |
| Czech Republic | Ireland | Portugal | |
| Denmark | Italy | Serbia and Montenegro | |
| England | Liechtenstein | Slovakia | |
| Finland | Luxembourg | Slovenia | |

Continued overleaf

Copyright by
Dr. Ing. h. c. F. Porsche AG
After Sales Engineering
Printed in Germany - 03/09

PORSCHE

Intermediate maintenance (A markets*) Cayman (987), Cayman S (987) Boxster (987), Boxster S (987) 911 Carrera (997), 911 Carrera S (997) as of 2010 model

Vehicle Ident. No. _____

Working instruction for
order no. _____

--

Additional maintenance for spark plugs
(Labour operation 03 81 00 ..)

Replace spark plugs	every 90,000 km/60,000 miles or every 4 years	<input checked="" type="checkbox"/>
---------------------	---	-------------------------------------

Additional maintenance for drive belt
(Labour operation 03 60 00 ..)

Check drive belt	every 60,000 km/40,000 miles or every 4 years	<input type="checkbox"/>
Check drive belt	every 150,000 km/100,000 miles or every 10 years	<input type="checkbox"/>
Check drive belt	every 240,000 km/160,000 miles or every 16 years	<input type="checkbox"/>

Additional maintenance for convertible top
(Labour operation 03 70 00 ..)

Service and maintain convertible top (911 Carrera only)	every 30,000 km/20,000 miles or every 2 years	<input type="checkbox"/>
---	---	--------------------------

Additional maintenance every 90,000 km/60,000 miles or every 6 years
(Labour operation 03 83 00 ..)

Air cleaner: replace filter element		<input type="checkbox"/>
Replace drive belt	Boxster	<input type="checkbox"/>
Electronically controlled all-wheel drive (Carrera 4 only): change oil		<input type="checkbox"/>
PDK transmission: change clutch fluid		<input type="checkbox"/>

Additional maintenance every 180,000 km/120,000 miles or every 12 years
(Labour operation 03 88 00 ..)

Manual transmission: change oil		<input type="checkbox"/>
All-wheel final drive: change oil (911 Carrera/S only)		<input type="checkbox"/>
PDK transmission: change transmission oil		<input type="checkbox"/>

Every 2 years

Prepare condition report for long-life guarantee	<input checked="" type="checkbox"/>
Change brake fluid	<input checked="" type="checkbox"/>

Every 4 years

Replace tyre sealant	<input type="checkbox"/>
----------------------	--------------------------

After 4 years, then every 2 years

Check Tyre Pressure Monitoring system battery	<input type="checkbox"/>
---	--------------------------

After 4, 8, 10 years, then every 2 years

Visual inspection of airbag units	<input type="checkbox"/>
Ancillary unit mounts and suspension: visual inspection of all rubber mountings and boots for damage	<input type="checkbox"/>

Signature (mechanic): C. Th...

Test drive:

Remote control, front seats, footbrake and handbrake (also actuation travel), engine, clutch, steering, transmission, ParkAssist, cruise control, PSM switch, PASM switch, Sport switch, heating, air conditioning and instruments: check operation	<input type="checkbox"/>
Oils, fluids: visual inspection for leaks	<input type="checkbox"/>

Signature (final check): C. Th...

Copyright by
Dr. Ing. h.c. F. Porsche AG
After Sales Engineering
Printed in Germany - 03/09

PORSCHE
Porsche Centre Edinburgh
Fort Kinnaird
Edinburgh EH15 3HR
0131 475 5000
Porsche Centre